



000 4 23

DATE:	9/29/99	TIME:	1500
WEATHER:	clear		
LOCATION:	Rinker materials		
FIELD TAKEN BY:		Jm	

RINKER MATERIALS  
SITE INSPECTION

9/29/99



00:00:00











Jeb Bush  
Governor

# Department of Environmental Protection

# FILE

Southeast District  
P.O. Box 15425  
West Palm Beach, Florida 33416

David B. Struhs  
Secretary

DEC 22 1999

Mr. James S. Jenkins, III  
Rinker Materials Corporation  
P.O. Box 24635  
West Palm Beach, FL 33416

Dear Mr. Jenkins,

The attached Soil Thermal Treatment Facility Inspection Report documents a routine inspection of your facility at 1200 NW 137th Avenue, Miami, FL, by the Department on September 29, 1999. During this inspection, as noted on the attached inspection report, an accumulation of oil/sludge inside the secondary containment of the soil storage building apparently from spills and/or leaks was observed. The source of this material needs to be identified and the oil/sludge trapped between the stem wall and the outer wall in the Northeast corner of the soil storage building needs to be removed, as well as the oil accumulation in the vicinity of the drums stored in the Northwest corner of the soil storage building to prevent a potential discharge from the soil storage building. **Please provide a written reply to confirm the source/s have been identified and actions taken to prevent reoccurrence in the future.**


In anticipation of the upcoming changeover in the cement manufacturing process (wet process to dry process), several areas of the current permits may require modification in order to remain current. It appears the facility layout, handling and processing of materials, handling of drum wash area wastewater, and management of leachate from the soil storage building are some of the areas which may need to be addressed. To determine whether or not permitting changes are necessary and ensure timely processing, please contact Robert Johns/MDERM regarding permit no. SO13-300512 and this office regarding permit no. SO13-290034 as soon as possible. In addition, the original alternate procedure (AP-STTF001) needs to be reviewed for continued applicability. Thank you for your continued cooperation.

Additionally, under the general provisions of the new soil thermal treatment facilities rule, 62-713, F.A.C., persons operating soil treatment facilities

under a permit issued by the Department prior to August 5, 1999, may continue to operate that facility under the terms of their existing permit unit expires, except that the treated soil shall meet the requirements of 62-713.520, F.A.C., by February 1, 2000.

If you have any questions or need further information, please contact Lee Martin at 561-681-6676.

Sincerely,

A handwritten signature in black ink, reading "Paul Alan Wierzbicki". The signature is written in a cursive, flowing style.

Paul Alan Wierzbicki, P.G.  
Waste Cleanup Supervisor

Atch: STTF Inspection dated 9/29/99

cc: Robert Johns, Paul Lasa, MDERM, Miami w/atch  
Tom Conrardy, Zoe Kulakowski, DEP/BWC, Tallahassee w/atch  
Jeff Smith, DEP/WPB w/atch  
Don Emery, Mike Vardeman, Rinker Materials, Miami w/atch





Jeb Bush  
Governor

# Department of Environmental Protection

Southeast District  
P.O. Box 15425  
West Palm Beach, Florida 33416

David B. Struhs  
Secretary

## SOIL THERMAL TREATMENT FACILITY INSPECTION REPORT

1. TYPE INSPECTION: ☐ COMPLAINT ☒ ROUTINE ☐ FOLLOW-UP ☐ PERMITTING

2. FACILITY NAME Rinker Portland Cement Corp.

DER/EPA ID FLD981758485 COMET SITE ID 69992

3. ADDRESS 1200 NW 137th Ave, Miami, FL, 33182  
Mailing: P.O. Box 24635, West Palm Beach, FL 33416-4635

COUNTY Dade PHONE 305- 221-7645 DATE 9/29/99 TIME 10:00 am

4. TYPE OF FACILITY Thermal Soil Treatment Facility

5. **DESCRIPTION OF OPERATION:**

Facility Operations include limrock mining and contaminated soil processing to produce cement.

Rinker uses kilns fired by coal, natural gas, or used oil in production.

6. APPL. REGULATIONS: ☐ 62-2, F.A.C. ☒ 62-775, F.A.C.

7. **RESPONSIBLE OFFICIAL:** (Name and Title)

James Jenkins, Vice President

8. **SURVEY PARTICIPANTS AND PRINCIPAL INSPECTORS:**

Lee Martin, FDEP

Don Emery, Rinker Materials

9. FACILITY LATITUDE 25°46'57" conf. LONGITUDE 80°25'20" conf. 8/93

10. TYPE OWNERSHIP: FEDERAL STATE COUNTY MUNICIPAL PRIVATE

11. NOTICE NO: SO13-290034 DATE ISSUED: 6/28/96 EXP. DATE: 6/7/2001  
SO13-300512 6/4/98 6/4/2002

Rev 8/18/94

"Protect, Conserve and Manage Florida's Environment and Natural Resources"

Printed on recycled paper.

A routine inspection was conducted at the Rinker Portland Cement Corporation's soil thermal treatment facility regulated pursuant to Chapter 62-775, Florida Administrative Code (FAC) and Chapter 62-701, FAC. This facility operates a rotary kiln and utilizes the petroleum contaminated soil and coal tar contaminated soil in the manufacture of cement.

#### BACKGROUND INFORMATION:

Rinker was issued a General Permit #SO13-290034 to operate a soil thermal treatment facility on June 28, 1996 which expires on June 7, 2001. The Rinker facility was operating as an existing facility as defined in 62-775.200, FAC prior to the effective date of this rule. Additionally, the facility treats coal tar contaminated soil under a Solid Waste Material Recovery Facility Permit #SO13-300512 issued June 4, 1997 which expires on June 4, 2002. A complete process description is provided in the Rinker permit application; however, the process was reviewed at the inspection as follows:

According to Don Emery, prior to accepting any soil for thermal treatment pursuant to 62-775, FAC, Rinker requires a soil analysis profile. Based on this profile, and specific conditions from DEP and Metro Dade Department of Environmental Resources Management (DERM), soils are brought by truck to the soil storage facility. DERM has granted approval authority to Rinker, subject to specific conditions in their DERM solid waste permit. Rinker claims to accept no hazardous wastes as defined in 40 CFR Part 261.

Rinker has operated a materials substitution program since 1991. This program researches and evaluates different alternative materials for use as raw materials in the production of cement or for use as an alternative fuel source in the kilns. Two alternative materials currently in use include the substitution of petroleum contaminated soils for clean silica sand and the substitution of "on-spec" waste oil for fuel oil in kiln burners. Other alternative material substitutions under discussion and/or evaluation for possible future use include: (1) substitution of oily waste water for part of the slurry makeup water, (2) burning tires for fuel, (3) replacing FP&L slag with other power plant ashes such as ash from MSW incinerators, (4) using spent petroleum catalyst as an aluminum source, (5) blending oily sludges with contaminated soils, and (6) using other petroleum contaminated material.

Rinker has received approval for burning old tires as a fuel and iron supplement. The tires are injected whole, two at a time, through a patented system during each rotation of the kiln. The point of injection is approximately midway along the kiln where the temperature is approximately 1800 ° F. Additionally, the tires are packed with petroleum contaminated booms, diapers, absorbent material, jet fuel filters, etc.; however, operational problems with lowering of temperatures has suspended continuous burning but some batch burning is still performed.

Rinker has received a determination that the use of spent petroleum catalyst as an aluminum source is not regulated under 62-775, F.A.C.; however, the characteristics provided would make storage on the bare ground inappropriate. Several loads (10-12) of spent catalyst from a Hess operation in Puerto Rico were received in the past, but handling problems due to the extremely dusty nature of the material has delayed subsequent shipments while a pneumatic off-loading and handling system is being investigated.

Rinker has applied for and received a Solid Waste Material Recovery Facility Permit No. SO13-300512 which allows Rinker to accept and treat certain coal tar contaminated soils. Rinker first accepted coal tar contaminated soils from mid June-mid August 1997 and revised the treated soil reporting form to reflect the coal tar parameters. According to Mr. Emery, during this inspection period Rinker only treated 10-15 drums of coal tar contaminated soils the last week of April 1999.

Rinker has applied for an alternative procedure to allow processing of certain petroleum related sludges/residues along with petroleum contaminated soil. This request has been approved under Alternate Procedure No. AP-STTF0036 with certain restrictions.

The afterburner system for the petroleum contaminated soils is in operation, the soils process through a preliminary kiln (stone dryer) with afterburner first, then go through the cement kiln. Preliminary in house analysis of the soils, although not required, indicate the soils meet clean soil criteria before they are processed through the cement kiln.

#### SOIL STORAGE FACILITY:

Incoming soils to be thermally treated by Rinker arrive by independent contractors via truck, are weighed, and taken to the Material Screening Building (MSB) for processing. Rinker has changed their policy concerning drum handling due to the increase in drill cuttings received in drums and the subsequent bottle neck caused in the off loading area. The drums are placed in the Northwest corner of the MSB and emptied as time permits and during this inspection all drums observed were located inside the building; however, during this inspection one or more drums appeared to be leaking as evidenced by a layer of thick oily waste material accumulating on the floor around the stored drums. Even though the material is within the secondary containment of the building there is a potential for the material to spread outside the building; therefore, the leaky drum or drums should be identified, managed, and the oily material removed from the floor to prevent a potential discharge outside the facility.

Once emptied the drums are then rinsed at the drum washing area and crushed for salvage. The rinse water is contained and used on site in slurry production, the sediments are returned to the soil storage facility. The MSB located South of the railroad tracks became operational February 9, 1992 and consists of a 100' by 300' monolith concrete slab sealed to solid concrete walls on three sides with a concrete curb across the front. The MSB has an open front to accommodate trucks and equipment, enclosed sides, and a roof. The floor slopes to the southeast corner where a sump is located to collect any contaminated water from wind blown rain seeping through the contaminated soils. The leachate collection tank has been relocated outside the Southeast corner of the MSB. The tank is within a secondary containment structure and piping outside the facility is double-walled. An additional interior concrete curb sloping away from the Northeast front wall toward the interior of the MSB had been installed. An additional stem wall has been constructed along the Northeast front wall and rain gutters have been redirected after investigation following the December 1996 inspection. During this inspection a thick oily sludge type material was identified in the area between the stem wall and the outer wall of the building. Even though the material is within the secondary containment of the building, this area was not designed for storage of uncontained oily sludge material and there is a potential for the material to spread outside the building; therefore, the uncontained oily sludge material should be removed and the area cleaned to prevent a potential discharge outside the facility. This will continue to be checked in the future. The four groundwater wells off the corners of the MSB have flush mounted manhole lids. Additionally, the monitor well off the Northwest corner of the MSB noted in the last inspection had been replaced but had been repaired and resealed; therefore, a monitor well completion report is not needed.

The metal and plastics removed from the soils are collected for transport to the County landfill, Rinker should maintain receipts for proper disposal. The larger concrete debris screened out initially are taken to the rock crusher to be pulverized separately and mixed back in with the contaminated soils at the MSB. Spent oil filters are drummed and stored separately at the MSB and processed for recycling to Cliff Berry, Inc. A covered dumpster has been located in the Northeast corner of the MSB to allow collection of oily wastes/sludges which are mixed with the fuel oil and burned in the kiln.

#### RECORDKEEPING:

Rinker has received a Department alternative procedure approval (File No. AP-STTF001) for testing of contaminated soils. Rinker relies solely on the test results supplied by other labs; however, Rinker requires acknowledgment of a Department approved Quality Assurance plan from the labs supplying the data. Rinker performs spot checks of some samples. Rinker also performs groundwater analyses through their in-house laboratory, under a Department approved Quality Assurance Plan, for their Groundwater Monitoring Plan. A review of records for untreated soil for July 1999 indicated some batches of untreated soils were received which exceeded the clean soil criteria for metals; however, spot checks on some of these batches were made and blending records were provided as required by 62-775.400(4), FAC, which confirms blended soils comply with total metals standards. Rinker began treating low level PCB contaminated soils in April 1994 and developed a form to track the source, soil PCB content, quantity, PCB concentration, pounds PCB treated, and cumulative year to date PCB treated. No PCB contaminated soils were received during July 1999. Rinker began treating coal tar contaminated soils in mid-June 1997 and developed a form to track the required analytical data for the treated soils, no coal tar contaminated soils were processed during this inspection period. A review of treated soil (clinker) forms for TCLP

analyses indicates the results from six samples for Cadmium, nine samples for Lead, four samples for Barium, and one sample for Selenium exceed the respective groundwater standard; however, all this material is stabilized in concrete rather than disposed of as clean soil. The remainder of the clean soil criteria in 62-775 was not exceeded.

**SUMMARY:**

The MSB provides for proper handling and storage of petroleum contaminated soils, low level PCB contaminated soils, and coal tar contaminated soils and allows Rinker to process contaminated soils in an environmentally sound manner. No other signs of discharge were noted and all facility personnel were very cooperative.



EXHIBIT E  
Florida Department of Environmental Regulation  
STATIONARY SOIL THERMAL TREATMENT FACILITY  
INSPECTION REPORT

Name of Facility RINKER MATERIALS  
Location 1200 NW 137<sup>TH</sup> AVE. MIAMI, FL  
General Permit No. SO 13-290034 Date of Inspection 9/29/99  
Contact Person DON EMERY  
Person Completing Report LEE MARTIN

Instructions: Complete the appropriate spaces for each item listed below. Use comments space to provide additional information for each item. Additional paper may be used if necessary.

Yes No SITE SURVEY

- ☒ 1. Does information provided on general permit notice of intent form coincide with actual facility?
- ☒ 2. Is soil sampling procedure correct?
- ☒ 3. Are monitoring wells properly installed (proper number and location)?
- ☒ 4. Are monitor wells being properly sampled and analysed for required parameters?
- ☒ 5. Is untreated soil stockpiled separately from treated soil and properly identified?
- ☒ 6. Is untreated soil adequately covered by roofing?
- ☒ 7. Do floors for storage appear to be properly constructed and in good condition?
- ☒ 8. Are floors properly bermed to provide runoff control?
- ☒ 9. Is a leachate collection system provided?

Yes No REPORTING FORMS

- ☒ 10. Are untreated soil reporting forms being properly completed? starting date 7/2/99 end date 7/27/99
- ☒ 11. Are treated soil reporting forms being properly completed? starting date 5/18/99 end date 8/31/99

12. Indicate frequency clean soil criteria is being met?
- 100 % TRPH - 10 mg/kg, or
  - % TRPH - 50 mg/kg, PAH - 6 mg/kg, and VOH - 50 ug/kg
13. Indicate ranges and approximate median values of untreated soil analyses for the following parameters.
- TRPH BDL mg/kg to 34600 mg/kg, median 627 mg/kg
  - VOA BDL mg/kg to 27665 mg/kg, median 1 mg/kg
  - Arsenic BDL mg/kg to 26 mg/kg
  - Barium BDL mg/kg to 1223 mg/kg
  - Cadmium BDL mg/kg to 15 mg/kg
  - Chromium BDL mg/kg to 33.5 mg/kg
  - Lead BDL mg/kg to 1416 mg/kg
  - Mercury BDL mg/kg to 1.1 mg/kg
  - Selenium BDL mg/kg to 90 mg/kg
  - Silver BDL mg/kg to 8.1 mg/kg
14. Indicate ranges and approximate median values of treated soil analyses for the following parameters.
- TRPH BDL mg/kg to BDL mg/kg, median BDL mg/kg
  - VOA BDL mg/kg to BDL mg/kg, median BDL mg/kg
  - Arsenic 1.0 mg/kg to 4.2 mg/kg
  - Barium 100 mg/kg to 3351 mg/kg
  - Cadmium BDL mg/kg to 4.5 mg/kg
  - Chromium 32.5 mg/kg to 73.9 mg/kg
  - Lead BDL mg/kg to 50 mg/kg
  - Mercury BDL mg/kg to BDL mg/kg
  - Selenium BDL mg/kg to 239 mg/kg
  - Silver BDL mg/kg to 9.6 mg/kg
  - mg/kg to        mg/kg
  - mg/kg to        mg/kg

Comments: OIL ACCUMULATION OBSERVED WITHIN SECONDARY  
CONTAINMENT IN VICINITY OF DRUMS STORED IN NORTHEAST  
CORNER AND BETWEEN STEM WALL AND OUTER WALL IN  
NORTHEAST CORNER. SOURCES NEED TO BE IDENTIFIED AND  
OIL REMOVED/CLEANED UP TO PREVENT POTENTIAL DISCHARGES,

William L Martin  
Signature

December 20, 1999  
Date



Jeb Bush  
Governor

# Department of Environmental Protection

Southeast District  
P.O. Box 15425  
West Palm Beach, Florida 33416

David B. Struhs  
Secretary

## SOIL THERMAL TREATMENT FACILITY INSPECTION REPORT

1. TYPE INSPECTION:        COMPLAINT   X   ROUTINE        FOLLOW-UP        PERMITTING

2. FACILITY NAME Rinker Portland Cement Corp.

DER/EPA ID FLD981758485 COMET SITE ID 69992

3. ADDRESS 1200 NW 137th Ave, Miami, FL, 33182  
Mailing: P.O. Box 24635, West Palm Beach, FL 33416-4635

COUNTY Dade PHONE 305-221-7645 DATE 9/29/99 TIME 10:00 am

4. TYPE OF FACILITY Thermal Soil Treatment Facility

5. **DESCRIPTION OF OPERATION:**

Facility Operations include limerock mining and contaminated soil processing to produce cement.

Rinker uses kilns fired by coal, natural gas, or used oil in production.

6. APPL. REGULATIONS:        62-2, F.A.C.   X   62-775, F.A.C.

7. **RESPONSIBLE OFFICIAL:** (Name and Title)

James Jenkins, Vice President

8. **SURVEY PARTICIPANTS AND PRINCIPAL INSPECTORS:**

Lee Martin, FDEP

Don Emery, Rinker Materials

9. FACILITY LATITUDE 25°46'57" conf. LONGITUDE 80°25'20" conf. 8/93

10. TYPE OWNERSHIP: FEDERAL STATE COUNTY MUNICIPAL PRIVATE

11. NOTICE NO: SO13-290034 DATE ISSUED: 6/28/96 EXP. DATE: 6/7/2001  
SO13-300512 6/4/98 6/4/2002

Rev 8/18/94

"Protect, Conserve and Manage Florida's Environment and Natural Resources"

Printed on recycled paper.

A routine inspection was conducted at the Rinker Portland Cement Corporation's soil thermal treatment facility regulated pursuant to Chapter 62-775, Florida Administrative Code (FAC) and Chapter 62-701, FAC. This facility operates a rotary kiln and utilizes the petroleum contaminated soil and coal tar contaminated soil in the manufacture of cement.

#### BACKGROUND INFORMATION:

Rinker was issued a General Permit #SO13-290034 to operate a soil thermal treatment facility on June 28, 1996 which expires on June 7, 2001. The Rinker facility was operating as an existing facility as defined in 62-775.200, FAC prior to the effective date of this rule. Additionally, the facility treats coal tar contaminated soil under a Solid Waste Material Recovery Facility Permit #SO13-300512 issued June 4, 1997 which expires on June 4, 2002. A complete process description is provided in the Rinker permit application; however, the process was reviewed at the inspection as follows:

According to Don Emery, prior to accepting any soil for thermal treatment pursuant to 62-775, FAC, Rinker requires a soil analysis profile. Based on this profile, and specific conditions from DEP and Metro Dade Department of Environmental Resources Management (DERM), soils are brought by truck to the soil storage facility. DERM has granted approval authority to Rinker, subject to specific conditions in their DERM solid waste permit. Rinker claims to accept no hazardous wastes as defined in 40 CFR Part 261.

Rinker has operated a materials substitution program since 1991. This program researches and evaluates different alternative materials for use as raw materials in the production of cement or for use as an alternative fuel source in the kilns. Two alternative materials currently in use include the substitution of petroleum contaminated soils for clean silica sand and the substitution of "on-spec" waste oil for fuel oil in kiln burners. Other alternative material substitutions under discussion and/or evaluation for possible future use include: (1) substitution of oily waste water for part of the slurry makeup water, (2) burning tires for fuel, (3) replacing FP&L slag with other power plant ashes such as ash from MSW incinerators, (4) using spent petroleum catalyst as an aluminum source, (5) blending oily sludges with contaminated soils, and (6) using other petroleum contaminated material.

Rinker has received approval for burning old tires as a fuel and iron supplement. The tires are injected whole, two at a time, through a patented system during each rotation of the kiln. The point of injection is approximately midway along the kiln where the temperature is approximately 1800 ° F. Additionally, the tires are packed with petroleum contaminated booms, diapers, absorbent material, jet fuel filters, etc.; however, operational problems with lowering of temperatures has suspended continuous burning but some batch burning is still performed.

Rinker has received a determination that the use of spent petroleum catalyst as an aluminum source is not regulated under 62-775, F.A.C.; however, the characteristics provided would make storage on the bare ground inappropriate. Several loads (10-12) of spent catalyst from a Hess operation in Puerto Rico were received in the past, but handling problems due to the extremely dusty nature of the material has delayed subsequent shipments while a pneumatic off-loading and handling system is being investigated.

Rinker has applied for and received a Solid Waste Material Recovery Facility Permit No. SO13-300512 which allows Rinker to accept and treat certain coal tar contaminated soils. Rinker first accepted coal tar contaminated soils from mid June-mid August 1997 and revised the treated soil reporting form to reflect the coal tar parameters. According to Mr. Emery, during this inspection period Rinker only treated 10-15 drums of coal tar contaminated soils the last week of April 1999.

Rinker has applied for an alternative procedure to allow processing of certain petroleum related sludges/residues along with petroleum contaminated soil. This request has been approved under Alternate Procedure No. AP-STTF0036 with certain restrictions.

The afterburner system for the petroleum contaminated soils is in operation, the soils process through a preliminary kiln (stone dryer) with afterburner first, then go through the cement kiln. Preliminary in house analysis of the soils, although not required, indicate the soils meet clean soil criteria before they are processed through the cement kiln.



## SOIL STORAGE FACILITY:

Incoming soils to be thermally treated by Rinker arrive by independent contractors via truck, are weighed, and taken to the Material Screening Building (MSB) for processing. Rinker has changed their policy concerning drum handling due to the increase in drill cuttings received in drums and the subsequent bottle neck caused in the off loading area. The drums are placed in the Northwest corner of the MSB and emptied as time permits and during this inspection all drums observed were located inside the building; however, during this inspection one or more drums appeared to be leaking as evidenced by a layer of thick oily waste material accumulating on the floor around the stored drums. Even though the material is within the secondary containment of the building there is a potential for the material to spread outside the building; therefore, the leaky drum or drums should be identified, managed, and the oily material removed from the floor to prevent a potential discharge outside the facility.

Once emptied the drums are then rinsed at the drum washing area and crushed for salvage. The rinse water is contained and used on site in slurry production, the sediments are returned to the soil storage facility. The MSB located South of the railroad tracks became operational February 9, 1992 and consists of a 100' by 300' monolith concrete slab sealed to solid concrete walls on three sides with a concrete curb across the front. The MSB has an open front to accommodate trucks and equipment, enclosed sides, and a roof. The floor slopes to the southeast corner where a sump is located to collect any contaminated water from wind blown rain seeping through the contaminated soils. The leachate collection tank has been relocated outside the Southeast corner of the MSB. The tank is within a secondary containment structure and piping outside the facility is double-walled. An additional interior concrete curb sloping away from the Northeast front wall toward the interior of the MSB had been installed. An additional stem wall has been constructed along the Northeast front wall and rain gutters have been redirected after investigation following the December 1996 inspection. During this inspection a thick oily sludge type material was identified in the area between the stem wall and the outer wall of the building. Even though the material is within the secondary containment of the building, this area was not designed for storage of uncontained oily sludge material and there is a potential for the material to spread outside the building; therefore, the uncontained oily sludge material should be removed and the area cleaned to prevent a potential discharge outside the facility. This will continue to be checked in the future. The four groundwater wells off the corners of the MSB have flush mounted manhole lids. Additionally, the monitor well off the Northwest corner of the MSB noted in the last inspection had been replaced but had been repaired and resealed; therefore, a monitor well completion report is not needed.

The metal and plastics removed from the soils are collected for transport to the County landfill, Rinker should maintain receipts for proper disposal. The larger concrete debris screened out initially are taken to the rock crusher to be pulverized separately and mixed back in with the contaminated soils at the MSB. Spent oil filters are drummed and stored separately at the MSB and processed for recycling to Cliff Berry, Inc. A covered dumpster has been located in the Northeast corner of the MSB to allow collection of oily wastes/sludges which are mixed with the fuel oil and burned in the kiln.

## RECORDKEEPING:

Rinker has received a Department alternative procedure approval (File No. AP-STTF001) for testing of contaminated soils. Rinker relies solely on the test results supplied by other labs; however, Rinker requires acknowledgment of a Department approved Quality Assurance plan from the labs supplying the data. Rinker performs spot checks of some samples. Rinker also performs groundwater analyses through their in-house laboratory, under a Department approved Quality Assurance Plan, for their Groundwater Monitoring Plan. A review of records for untreated soil for July 1999 indicated some batches of untreated soils were received which exceeded the clean soil criteria for metals; however, spot checks on some of these batches were made and blending records were provided as required by 62-775.400(4), FAC, which confirms blended soils comply with total metals standards. Rinker began treating low level PCB contaminated soils in April 1994 and developed a form to track the source, soil PCB content, quantity, PCB concentration, pounds PCB treated, and cumulative year to date PCB treated. No PCB contaminated soils were received during July 1999. Rinker began treating coal tar contaminated soils in mid-June 1997 and developed a form to track the required analytical data for the treated soils, no coal tar contaminated soils were processed during this inspection period. A review of treated soil (clinker) forms for TCLP

analyses indicates the results from six samples for Cadmium, nine samples for Lead, four samples for Barium, and one sample for Selenium exceed the respective groundwater standard; however, all this material is stabilized in concrete rather than disposed of as clean soil. The remainder of the clean soil criteria in 62-775 was not exceeded.

**SUMMARY:**

The MSB provides for proper handling and storage of petroleum contaminated soils, low level PCB contaminated soils, and coal tar contaminated soils and allows Rinker to process contaminated soils in an environmentally sound manner. No other signs of discharge were noted and all facility personnel were very cooperative.

EXHIBIT E  
Florida Department of Environmental Regulation  
STATIONARY SOIL THERMAL TREATMENT FACILITY  
INSPECTION REPORT

Name of Facility RINKER MATERIALS  
Location 1200 NW 137<sup>th</sup> AVE. MIAMI, FL  
General Permit No. SO 13-290034 Date of Inspection 7/29/99  
Contact Person DON EMERY  
Person Completing Report LEE MARTIN

Instructions: Complete the appropriate spaces for each item listed below. Use comments space to provide additional information for each item. Additional paper may be used if necessary.

Yes No SITE SURVEY

- ✓      1. Does information provided on general permit notice of intent form coincide with actual facility?
- ✓      2. Is soil sampling procedure correct?
- ✓      3. Are monitoring wells properly installed (proper number and location)?
- ✓      4. Are monitor wells being properly sampled and analysed for required parameters?
- ✓      5. Is untreated soil stockpiled separately from treated soil and properly identified?
- ✓      6. Is untreated soil adequately covered by roofing?
- ✓      7. Do floors for storage appear to be properly constructed and in good condition?
- ✓      8. Are floors properly bermed to provide runoff control?
- ✓      9. Is a leachate collection system provided?

Yes No REPORTING FORMS

- ✓      10. Are untreated soil reporting forms being properly completed? starting date 7/2/99 end date 7/27/99
- ✓      11. Are treated soil reporting forms being properly completed? starting date 5/18/99 end date 8/31/99

12. Indicate frequency clean soil criteria is being met?
- 100 % TRPH - 10 mg/kg, or
  - % TRPH - 50 mg/kg, PAH - 6 mg/kg, and VOH - 50 ug/kg
13. Indicate ranges and approximate median values of untreated soil analyses for the following parameters.
- TRPH BDL mg/kg to 34600 mg/kg, median 627 mg/kg
  - VOA BDL mg/kg to 27665 mg/kg, median 1 mg/kg
  - Arsenic BDL mg/kg to 26 mg/kg
  - Barium BDL mg/kg to 1223 mg/kg
  - Cadmium BDL mg/kg to 15 mg/kg
  - Chromium BDL mg/kg to 33.5 mg/kg
  - Lead BDL mg/kg to 1416 mg/kg
  - Mercury BDL mg/kg to 1.1 mg/kg
  - Selenium BDL mg/kg to 90 mg/kg
  - Silver BDL mg/kg to 8.1 mg/kg
14. Indicate ranges and approximate median values of treated soil analyses for the following parameters.
- TRPH BDL mg/kg to BDL mg/kg, median BDL mg/kg
  - VOA BDL mg/kg to BDL mg/kg, median BDL mg/kg
  - Arsenic 1.0 mg/kg to 4.2 mg/kg
  - Barium 108 mg/kg to 3351 mg/kg
  - Cadmium BDL mg/kg to 4.5 mg/kg
  - Chromium 32.5 mg/kg to 73.9 mg/kg
  - Lead BDL mg/kg to 50 mg/kg
  - Mercury BDL mg/kg to BDL mg/kg
  - Selenium BDL mg/kg to 239 mg/kg
  - Silver BDL mg/kg to 9.6 mg/kg
  - mg/kg to        mg/kg
  - mg/kg to        mg/kg

Comments: OIL ACCUMULATION OBSERVED WITHIN SECONDARY  
CONTAINMENT IN VICINITY OF DRUMS STORED IN NORTHEAST  
CORNER AND BETWEEN STEM WALL AND OUTER WALL IN  
NORTHEAST CORNER. SOURCES NEED TO BE IDENTIFIED AND  
OIL REMOVED/CLEANED UP TO PREVENT POTENTIAL DISCHARGES,

William L Martin  
 Signature

December 20, 1999  
 Date



VOA	TRPH	Jul-99	VOA		TRPH	
1	36					
1	776		Mean	1063.538	Mean	4615.395
118	330		Standard Error	664.1946	Standard Error	1461.186
1650	738		Median	1	Median	627.5
1050	2330		Mode	1	Mode	1447
1	10.8		Standard Deviatio	4304.473	Standard Deviatio	9469.568
1	120		Sample Variance	18528489	Sample Variance	89672724
3461	34600		Kurtosis	37.96288	Kurtosis	3.459175
1	577		Skewness	6.043116	Skewness	2.214524
1300	24000		Range	27664	Range	34597
1	596		Minimum	1	Minimum	3
1	1191		Maximum	27665	Maximum	34600
1	348		Sum	44668.6	Sum	193846.6
1	790		Count	42	Count	42
1	27000		Confidence Level(	1341.369	Confidence Level(	2950.927
1	1447					
1	344					
445	3					
100	29000					
1	112					
1	5801					
1	640					
1	5					
1	1202					
20	72.8					
2957	382					
1	19000					
1	5					
3361	28000					
1	190					
1	1020					
5	615					
1	229					
550	1944					
27665	260					
1940	393					
19.6	90					
1	1447					
1	1000					
1	4400					
1	2774					
1	28					

# Florida Department of Environmental Regulation

Twin Towers Office Bldg. 2600 Blair Stone Road Tallahassee, Florida 32399-2400

Month July Year: 1999

## Soil Thermal Treatment Facility Untreated Soil Reporting Form

Name of Facility: RINKER MATERIALS CORP.

Air Permit No.: A013-172154

Soil Treatment Permit No.: SW-01117-97

Stationary XXX or Mobile Facility:           

DER Form #	17-776.900(2)
Form Title	Soil Thermal Treatment Facility
Effective Date:	Untreated Soil Reporting Form
DER Application No.:	

1	2	3	4	5										6	7	8	9
				Analytical Results													
				Metals										Totals			
Date	Reporting ID#	Sample Number	Amount Vol. or	AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses		
7/1/99	3002851 - 199900005	1.	19.16	26.	1.4	BDL	2.7	BDL	BDL	BDL	1.4	BDL	36.	BDL	Attach Lab Results Only		
7/1/99	3016752 - 199900007	1.	48.49	0.7	322.	1.20	6.5	18.4	BDL	59.	1.25	BDL	776.	BDL	Costa Del Sol		
7/1/99	3026877 - 199900005	1.	3.28	2.37	2.97	<0.018	4.39	2.59	<0.002	<233	576	118.8	330.	BDL			
7/1/99	3026926 - 199900013	1.	8.29	0.9	143.	0.17	9.7	23.4	BDL	BDL	BDL	1650.	738.	BDL			
7/1/99	3002894 - 199900026	1.	59.99	0.9	323.	1.0	5.2	33.3	BDL	80.	BDL	1050.	2330.	BDL			
7/1/99	3003039 - 199900008	5.	147.17	BDL	3.62	BDL	3.22	2.2	BDL	BDL	BDL	BDL	10.84	BDL			
7/1/99	3026878 - 199900002	1.	72.24	BDL	BDL	BDL	0.30	0.71	BDL	BDL	BDL	BDL	120.	BDL			
7/1/99	3002894 - 199900026	1.	14.28	BDL	33.4	BDL	33.5	13.6	BDL	BDL	BDL	3461.	34600.	BDL			
7/1/99	3002894 - 199900031	1.	5.18	2.5	188.	1.9	15.9	1416.	0.13	75.5	BDL	BDL	577.	BDL	SE Freightlin		
7/1/99	3025963 - 199900002	1.	17.80	1.8	41.	1.5	15.	7.0	BDL	BDL	BDL	1300.	24000.	BDL			
7/1/99	3042148 - 199900005	1.	3.71	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	596.	BDL			
7/1/99	3009901 - 199900012	1.	18.97	0.6	42.5	0.68	6.3	6.3	BDL	BDL	BDL	BDL	1191.	BDL			
7/1/99	3002894 - 199900025	1.	91.67	1.3	848.	2.45	18.4	23.4	BDL	90.	4.70	BDL	348.	BDL			
7/1/99	3004123 - 199900001	1.	40.59	BDL	BDL	BDL	BDL	3.2	BDL	BDL	BDL	BDL	790.	BDL			
7/1/99	3002947 - 199900001	1.	16.99	2.3	<29.	<0.4	8.9	21.	1.1	<3.3	<7.6	BDL	27000.	BDL			
7/1/99	3009901 - 199900007	1.	28.52	0.7	30.9	0.12	8.52	62.3	0.50	0.4	8.1	BDL	1447.	BDL			
7/1/99	3002894 - 199900027	1.	83.92	1.3	927.	2.8	9.5	127.	0.28	BDL	5.0	BDL	344.	BDL	CJ Mendez		
7/1/99	3003009 - 199900004	1.	43.58	8.7	1223.1	2.1	19.3	77.9	0.83	4.20	BDL	445.5	30.	BDL			
7/1/99	3003055 - 199900004	1.	16.44	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	100.	29000.	BDL			
7/1/99	3013197 - 199900002	3.	360.79	BDL	102.5	0.9	3.3	5.03	BDL	BDL	0.55	BDL	112.33	BDL			
7/1/99	3002894 - 199900029	1.	14.72	.99	1058.	2.	13.3	25.9	BDL	2.7	2.85	BDL	5801.	BDL			
7/1/99	3000799 - 199900001	1.	22.19	2.4	10.	BDL	7.1	BDL	BDL	BDL	BDL	BDL	640.	BDL			
7/1/99	3026911 - 199900003	3.	284.01	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL			

26 1220 2.8 33.5 1416 1.1 90 3.1

Month July Year: 1999

## Soil Thermal Treatment Facility Untreated Soil Reporting Form

Name of Facility: **RINKER MATERIALS CORP.**

Air Permit No.: **A013-172164**

Soil Treatment Permit No.: **SW-01117-97**

Stationary XXX or Mobile Facility: \_\_\_\_\_

DER Form #	17-775.900(2)
Form Title	Soil Thermal Treatment Facility
Effective Date:	Untreated Soil Reporting Form
DER Application No.:	

1	2	3	4	5	6	7	8	9								
				Analytical Results												
				Metals												
				Totals												
Date	Reporting ID#	Sample	Vol. or	AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH	VOH	Indicate Other Analyses	
7/19/99	3026926 - 199900014	3.	185.32	4.8	1177.5	2.50	15.2	19.0	BDL	2.7	2.4	BDL	1202.	BDL	Attach Lab Results Only	
7/19/99	3026932 - 199900002	7.	1389.44	.68	3.39	.07	4.21	15.66	BDL	BDL	BDL	19.9	72.86	BDL		
7/20/99	0799COD - 199900001	3.	333.49	2.6	606.	1.07	7.6	14.4	BDL	3.0	BDL	2967.	382.	BDL		
7/21/99	3002943 - 199900003	1.	15.73	2.7	<29.	<0.4	4.5	23.	<0.4	<3.32	<0.52	BDL	19000.	BDL		
7/21/99	3006318 - 199900007	3.	255.25	BDL	3.6	BDL	2.8	7.8	BDL	BDL	BDL	BDL	BDL	BDL	Coastal Fisher	
7/21/99	3026883 - 199900007	1.	1.75	3.9	90.	15.	9.2	120.	BDL	BDL	BDL	3361.	28000.	BDL		
7/22/99	3002912 - 199900003	3.	473.26	234	69.67	.437	2.43	16.97	BDL	.267	.833	BDL	190.66	BDL		
7/22/99	3021737 - 199900002	1.	10.88	BDL	7.1	BDL	1.0	6.0	BDL	BDL	BDL	BDL	1020.	BDL		
7/22/99	3026910 - 199900002	9.	2275.12	.93	7.1	.17	4.17	46.17	0.015	BDL	BDL	5.33	615.33	.12		
7/22/99	3026912 - 199900004	1.	14.95	BDL	13.0	BDL	6.10	7.60	BDL	BDL	BDL	BDL	229.	BDL		
7/22/99	3026926 - 199900015	1.	60.81	0.6	413.	2.18	BDL	600.	BDL	BDL	BDL	550.	1944.	BDL	Chevron Tank #40	
7/23/99	3002894 - 199900030	1.	79.60	BDL	BDL	0.04	BDL	7.6	BDL	BDL	BDL	27665.	260.	BDL		
7/23/99	3010320 - 199900001	3.	425.73	<1.	<11.	<2.1	<4.2	12.67	BDL	BDL	<2.1	1940.67	393.33	BDL		
7/26/99	3026888 - 199900001	3.	158.66	BDL	4.17	BDL	1.26	2.19	BDK	3.6	BDL	19.780	90.	BDL		
7/26/99	COD9901 - 199900008	1.	21.155	0.7	30.9	0.12	8.52	62.3	0.50	0.4	8.1	BDL	1447.	BDL		
7/26/99	COD9901 - 199900009	1.	43.91	1.2	174.	BDL	19.7	41.1	BDL	BDL	BDL	BDL	1000.	BDL		
7/26/99	COD9901 - 199900010	1.	21.37	.562	249.	2.5	16.3	20.4	BDL	BDL	7.35	BDL	4400.	BDL		
7/26/99	COD9901 - 199900011	1.	31.22	0.7	341.	0.95	BDL	25.9	BDL	64.	1.05	BDL	2774.	BDL		
7/27/99	3002894 - 199900032	1.	136.57	3.6	12.6	0.34	13.9	99.2	BDL	BDL	0.1	BDL	28.	BDL		

48 1177 15 19.9 400 .5 64 91

4.8 1177 15 19.9 400 .5 64 8.1

**Florida Department of Environmental Regulation  
Soil Thermal Treatment Facility  
Untreated Soil Reporting Form**

Name of Facility: RINKER MATERIALS CORP  
Air Permit No: A013-172154  
Soil Treatment Permit No: SW-01117-91  
Stationary-XXX or Mobile Facility:

**ATTACHMENT "A"  
Metals Blending Report**

Month July Year 1999

Day of Month	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										Source		
				Metals								Totals				
				AS	BA	CD	CR	PB	HG	SE	AG	VOA	RPH			
				5										8		
2-Jul	3002851-untreated blending soil	199900005		26	1.4	BDL	2.7	BDL	BDL	BDL	BDL	BDL	1.4			Costa Del Sol Blended 2 - 1
8-Jul	3002894-untreated blending soil	199900031		2.5	188	1.9	15.9	1416	BDL	0.13	75.5	BDL	BDL			SE Freightliners Blended 15 - 1
16-Jul	3002894-untreated blending soil	199900027		1.3	927	2.8	9.5	127	BDL	0.28	BDL	BDL	5			CJ MENDI'Z Blended 1 - 1
21-Jul	3026883-untreated blending soil	199900007		3.9	90	15	9.2	120	BDL	BDL	BDL	BDL	BDL			COASTAL FISHER Blended 1 - 1



**Florida Department of Environmental Regulation  
Soil Thermal Treatment Facility  
Untreated Soil Reporting Form**

Name of Facility: RINKER MATERIALS CORP

Air Permit No: A013-172154

Soil Treatment Permit No: SW-011117-91

Stationary:XXX or Mobile Facility:

**ATTACHMENT "A"  
Metals Blending Report**

Month July Year 1999

1		2		3		4		5						
Day of Month	Soil Batch ID#	Sample Number	Amount Volume or Weight cy/tn	Analytical Results										
				Metals				Totals			Source			
				AS	BA	CD	CR	PB	HG	SI	AG	VOA	RPH	
22-Jul														
3026926-	199900015													
untreated	analysis													
blending	soil			0.6	413	2.18	BDL	600	BDL	BDL	BDL			
blending	soil							BDL						
								17.5						
untreated	analysis													
blending	soil													
blending	soil													
untreated	analysis													
blending	soil													
blending	soil													

Chevron Tank #40  
Blended 6 - 1


# RINKER MATERIALS SUBSTITUTION

## Materials Analysis Report

REPORT DATE 8/15/99  
SAMPLE DATE 7/15/99  
SAMPLE SOURCE CJ MENDEZ  
REFERENCE # 3002894-990027  
R.E.S. NUMBER 13067/13068  
SAMPLE TYPE SOIL

PARAMETER	RESULTS CONTAMINATED	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	21.1	BDL	19.9	mg/kg	7420	10

BLEND = 1 Contaminated With 1 CLEAN  
BDL = Below detection limit

  
\_\_\_\_\_  
Juan A. Gonzalez  
QA/QC Manager


# RINKER MATERIALS SUBSTITUTION

## Materials Analysis Report

REPORT DATE 8/15/99  
SAMPLE DATE 7/8/99  
SAMPLE SOURCE SE FREIGHTLINERS  
REFERENCE # 3002894-990031  
R.E.S. NUMBER 13063/13064  
SAMPLE TYPE SOIL

PARAMETER	RESULTS CONTAMINATED	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	18.0	BDL	17.3	mg/kg	7420	10

BLEND = 1 Contaminated With 15 CLEAN  
BDL = Below detection limit

  
\_\_\_\_\_  
Juan A. Gonzalez  
QA/QC Manager


# RINKER MATERIALS SUBSTITUTION

## Materials Analysis Report

REPORT DATE 8/15/99  
SAMPLE DATE 7/2/99  
SAMPLE SOURCE COSTA DEL SOL  
REFERENCE # 3002851-99005  
R.E.S. NUMBER 13055/13056  
SAMPLE TYPE SOIL

PARAMETER	RESULTS CONTAMINATED	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
ARSENIC	BDL	BDL	BDL	mg/kg	7061	0.5

BLEND = 1 Contaminated With 2 CLEAN  
BDL = Below detection limit

  
\_\_\_\_\_  
Juan A. Gonzalez  
QA/QC Manager


# RINKER MATERIALS SUBSTITUTION

## Materials Analysis Report

REPORT DATE 8/15/99  
SAMPLE DATE 7/21/99  
SAMPLE SOURCE CHEVRON TANK #40  
REFERENCE #  
R.E.S. NUMBER 13061/13062  
SAMPLE TYPE SOIL

PARAMETER	RESULTS CONTAMINATED	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	18.7	BDL	17.5	mg/kg	7420	10

BLEND = 1 Contaminated With 6 CLEAN  
BDL = Below detection limit

  
\_\_\_\_\_  
Juan A. Gonzalez  
QA/QC Manager


# RINKER MATERIALS SUBSTITUTION

## Materials Analysis Report

REPORT DATE 8/15/99  
SAMPLE DATE 7/21/99  
SAMPLE SOURCE COASTAL FISHER  
REFERENCE # 3026883-990007  
R.E.S. NUMBER 13065/13066  
SAMPLE TYPE SOIL

PARAMETER	RESULTS CONTAMINATED	RESULT CLEAN	RESULT BLEND	UNITS	METHOD	D LIMITS
LEAD	20.1	BDL	17.1	mg/kg	7420	10

BLEND = 1 Contaminated With 1 CLEAN  
BDL = Below detection limit

  
\_\_\_\_\_  
Juan A. Gonzalez  
QA/QC Manager



# Rinker Environmental Services

## Materials Analysis Report

1200 N.W. 137th Avenue  
Miami, FL 33182

Telephone (800) 226-7647  
(305) 225-1423  
Facsimile (305) 220-9875

REPORT DATE	7/15/99	DATE SAMPLED	
SAMPLE SOURCE	S.E. FREIGHTLINERS	DATE RECEIVED	7/8/99
SAMPLE LOCATION	MIAMI, FL	REFERENCE #	CBI
COLLECTED BY	DON EMERY	R.E.S. NUMBER	12885
SAMPLE TYPE	SOIL	PAGE	Page 1 of 2

PARAMETER	RESULT	UNITS	METHOD	D. LIMITS	ANALYSIS DATE	ANAL. INITIAL
Arsenic	2.5	mg/kg	7060	0.5	7/14/99	PEP
Barium	188	mg/kg	7080	5	7/13/99	JSP
Cadmium	1.9	mg/kg	7130	0.5	7/13/99	JSP
Chromium	15.9	mg/kg	7190	1	7/13/99	JSP
Mercury	0.13	mg/kg	7470A	0.08	7/14/99	FJG
Lead	1416	mg/kg	7420	1	7/13/99	JSP
Selenium	75.5	mg/kg	7740	0.4	7/14/99	PEP
Silver	BDL	mg/kg	7760	1	7/13/99	JSP
Chloromethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
Bromomethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
Vinyl Chloride	BDL	mg/kg	5030/8021	150	7/10/99	AP
Dichlorodifluoromethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
Chloroethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
Methylene Chloride	BDL	mg/kg	5030/8021	150	7/10/99	AP
Trichlorofluoromethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,1-Dichloroethene	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,1-Dichloroethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
trans-1,2-Dichloroethene	BDL	mg/kg	5030/8021	150	7/10/99	AP
Chloroform	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,2-Dichloroethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,1,1-Trichloroethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
Carbon Tetrachloride	BDL	mg/kg	5030/8021	150	7/10/99	AP
Bromodichloromethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,2-Dichloropropane	BDL	mg/kg	5030/8021	150	7/10/99	AP
cis-1,3-Dichloropropene	BDL	mg/kg	5030/8021	150	7/10/99	AP
Trichloroethene	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,1,2-Trichloroethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,1,1,2-Tetrachloroethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
trans-1,3-Dichloropropene	BDL	mg/kg	5030/8021	150	7/10/99	AP
Dibromochloromethane	BDL	mg/kg	5030/8021	150	7/10/99	AP
Bromoform	BDL	mg/kg	5030/8021	150	7/10/99	AP
Tetrachloroethene	BDL	mg/kg	5030/8021	150	7/10/99	AP



<b>REPORT DATE</b>	7/15/99	<b>DATE SAMPLED</b>	
<b>SAMPLE SOURCE</b>	S.E. FREIGHTLINERS	<b>DATE RECEIVED</b>	7/8/99
<b>SAMPLE LOCATION</b>	MIAMI, FL	<b>REFERENCE #</b>	CBI
<b>COLLECTED BY</b>	DON EMERY	<b>R.E.S. NUMBER</b>	12885
<b>SAMPLE TYPE</b>	SOIL	<b>PAGE</b>	Page 2 of 2

PARAMETER	RESULT	UNITS	METHOD	D. LIMITS	ANALYSIS	ANAL.
					DATE	INITIAL
MTBE	BDL	mg/kg	5030/8021	150	7/10/99	AP
Benzene	BDL	mg/kg	5030/8021	150	7/10/99	AP
Toluene	BDL	mg/kg	5030/8021	150	7/10/99	AP
Ethylbenzene	BDL	mg/kg	5030/8021	150	7/10/99	AP
p-Xylene	BDL	mg/kg	5030/8021	150	7/10/99	AP
Chlorobenzene	BDL	mg/kg	5030/8021	150	7/10/99	AP
m-Xylene	BDL	mg/kg	5030/8021	150	7/10/99	AP
o-Xylene	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,4-Dichlorobenzene	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,3-Dichlorobenzene	BDL	mg/kg	5030/8021	150	7/10/99	AP
1,2-Dichlorobenzene	BDL	mg/kg	5030/8021	150	7/10/99	AP
TRH	577	mg/kg	9073	1	7/9/99	AP
Halogens	BDL	mg/kg	9020	100	7/9/99	AP
TCLP Pb	BDL	mg/L	1311	5	7/14/99	JSP

BDL = Below Detection Limits

\* Compounds are Screened Only, with an estimated detection limit.

All analyses were performed using EPA, ASTM, USGS, or Standard Methods.


All analyses were performed within EPA holding times unless otherwise noted.

Analyses are reported in dry weight unless otherwise indicated by units.

QAP # 950491

DOH# E86536

Respectfully submitted,

  
 Juan A. Gonzalez  
 QA/QC Manager

Name of Facility: RUMBLE MATERIALS CORP

Air Permit No: A013-1-12154

Soil Treatment Permit No: SW-01117-91

Stationary:XXX or Mobile Facility:

Treated Soil: \_\_\_\_\_

ting Form

Month \_\_\_\_\_ Year 99

Day of Month	Soil Batch ID#	Sample Number	Length of Run Hours	Amount Volume or Weight cy/tn	Analytical Results																					
					Total Metals					TCLP Metals						Totals										
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH		
5/18/99	5183	42	116		3.5	199	BDL	140.4	6.16	BDL	2.7	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL		
					Be	CN	Phenols	Dibenzofuran					Be	Benzene										TOH		
					6											7										
5/18/99	5183	42	116		6											7										
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH		
					3.4	423	BDL	158.2	5.5	BDL	0.5	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL		
					Be	CN	Phenols	Dibenzofuran					Be	Benzene										TOH		
					6											7										
6/1/99	611	42	116		6											7										
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH		
					3.0	351	2.5	739	6.5	BDL	0.5	BDL	BDL	2.28	0.23	BDL	0.26	BDL	0.7	BDL	BDL	BDL	BDL	BDL		
					Be	CN	Phenols	Dibenzofuran					Be	Benzene										TOH		
					6											7										
6/1/99	617	42	116		6											7										
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH		
					3.1	269	2.16	59.1	3.2	BDL	BDL	BDL	BDL	2.19	0.25	BDL	0.21	BDL	BDL	BDL	BDL	BDL	BDL	BDL		
					Be	CN	Phenols	Dibenzofuran					Be	Benzene										TOH		
					2.5	BDL	BDL	BDL					BDL	BDL										TOH		
					6											7										
6/1/99	619	42	116		6											7										
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH		
					3.2	435	2.55	31.4	17.9	BDL	95	9.6	BDL	2.23	0.25	BDL	0.23	BDL	BDL	BDL	BDL	BDL	BDL	BDL		
					Be	CN	Phenols	Dibenzofuran					Be	Benzene										TOH		
					6											7										

3.5 351 2.6 739 17.9 BDL 95 9.6 BDL 2.28 0.25 BDL 2.1 BDL 0.7 BDL

Name of Facility: RI MATERIALS CORP  
 Air Permit No: A013-1-154  
 Soil Treatment Permit No: SW-01117-91  
 Stationary:XXX or Mobile Facility:

Month Year 99

Day of Month	Soil Batch ID#	Sample Number	Length of Run Hours	Amount of Volume or Weight cy/tn	Analytical Results																				
					Total Metals					TCLP Metals					Totals										
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH	TOH
7-19	6-30	42	168		3.1	4910	2.176	32.5	18.3	BDL	239	5.4	BDL	1.25	1024	BDL	1.33	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					Be	CN	Phenols	Dibenzofuran					Be												
7-19	7-5	42	168		2.4	108	BDL	48.7	10.5	BDL	1.3	0.1	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					Be	CN	Phenols	Dibenzofuran					Be												
7-21	7-11	42	168		1.4	119	BDL	50.7	7.9	BDL	1.2	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					Be	CN	Phenols	Dibenzofuran					Be												
7-21	7-25	42	168		2.2	116	BDL	52.3	BDL	BDL			BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					Be	CN	Phenols	Dibenzofuran					Be												
7-26	8-1	42	168		2.4	120	BDL	54.8	5.2	BDL	1.3	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					Be	CN	Phenols	Dibenzofuran					Be												

3.1 496 2.15 54.8 18.3 BDL 239 5.4 BDL 1.25 1024 BDL 1.33 BDL BDL BDL

Name of Facility: R... MATERIALS CORP  
 Air Permit No: A013-12154  
 Soil Treatment Permit No: SW-01117-91  
 Stationary, XXX or Mobile Facility:

Day of Month	Soil Batch ID#	Sample Number	Length of Run Hours	Amount Volume or Weight cy/m	Analytical Results											Month	Year								
					Total Metals						TCLP Metals					Totals									
					As	Ba	Cd	Cr	Pb	Hg	Se	Ag	As	Ba	Cd	Cr	Pb	Hg	Se	Ag	VOA	RPH	PAH	VOH	
8-11	819	42	168		1.0	650	4.5	36	50	BDL	0.9	BDL	BDL	2.5	0.06	BDL	0.37	BDL	BDL	BDL	BDL	BDL	BDL	BDL	BDL
					6						7					8 9 10 11									
8-11	819	42	168		2.3	850	4.5	43	45	BDL	0.7	BDL	BDL	1.2	0.05	BDL	0.37	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					6						7					8 9 10 11									
8-20	825	42	168		4.2	650	4.5	36	39	BDL	0.7	BDL	BDL	BDL	BDL	BDL	0.24	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					6						7					8 9 10 11									
8-20	825	42	168		1.5	650	4.5	40	42	BDL	0.10	BDL	BDL	BDL	BDL	BDL	0.24	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					6						7					8 9 10 11									
8-20	825	42	168		4.2	650	4.5	43	45	BDL	0.7	BDL	BDL	BDL	BDL	BDL	0.24	BDL	BDL	BDL	BDL	BDL	BDL	BDL	
					6						7					8 9 10 11									

STATE OF FLORIDA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION

DISTRICT ROUTING SLIP

To: Paul Wierzbicki

DATE: 9/14/99

CC To:

	<b>PENSACOLA</b>	<b>NORTHWEST DISTRICT</b>	
	Panama City	Northwest District Branch Office	
	Tallahassee	Northwest District Branch Office	
	Sopchoppy	Northwest District Satellite Office	
	<b>TAMPA</b>	<b>SOUTHWEST DISTRICT</b>	
	Punta Gorda	Southwest District Branch Office	
	Bartow	Southwest District Satellite Office	
	<b>ORLANDO</b>	<b>CENTRAL DISTRICT</b>	
	Melbourne	Central District Satellite Office	
	<b>JACKSONVILLE</b>	<b>NORTHEAST DISTRICT</b>	
	Gainesville	Northeast District Branch Office	
	<b>FORT MYERS</b>	<b>SOUTH DISTRICT</b>	
	Marathon	South District Branch Office	
X	<b>WEST PALM BEACH</b>	<b>SOUTHEAST DISTRICT</b>	
	Port St. Lucie	Southeast District Branch Office	

☐ Reply Optional  
Date Due \_\_\_\_\_

☐ Reply Required  
Date Due: \_\_\_\_\_

☐ Info Only

Comments:

From:

Tel.:

Joe Kulakowski

8C 278-3935

## Memorandum

## Florida Department of Environmental Protection

200368

To: Paul Wierzbicki, Southeast District Office  
THROUGH: Jim Crane, Bureau of Waste Cleanup *JJC*  
FROM: Zoe Kulakowski, Bureau of Waste Cleanup *ZPK*  
DATE: September 14, 1999  
SUBJECT: Rinker Portland Cement Corporation, 1200 Northwest  
137th Avenue, Miami, Dade County

I have reviewed the Chapter 62-775, F.A.C. Ground Water Monitoring Report dated August 9, 1999 for the referenced site. The July 2, 1999 analytical results show acceptable ground water quality. Figure 2 shows an incorrect ground water elevation for MW-25 according to the data presented in Table 2.

/zpk

RECEIVED  
SEP 16 1999  
DEPT OF ENVIRONMENTAL PROTECTION  
WEST PALM BEACH