Knauss, Elizabeth

From: BOSEK, JOHN E <bosek.john@cleanharbors.com>

Sent: Wednesday, May 10, 2017 1:58 PM **To:** Knauss, Elizabeth; garcia.javier@epa.gov

Cc: Desha, David A.; Madden, Melissa; MCDUFFIE, JAMES W; LEISER, PAUL A

Subject: RE: Inspection follow up.

Attachments: Mix Pit 008.jpg; IMG_0247.jpg; IMG_0249.jpg; IMG_0250.jpg

Good afternoon Beth -

I just returned from vacation so pardon the delay in getting back with you. Here are the requested photos of the inspected items and the resolution. The mix tub trench was cleaned out by the close of business the day of the inspection, as well as the material removed from the gap beneath the wall.

Safety Starts with Me: Live It 3-6-5

John Bosek

Facility General Manager

Clean Harbors Florida LLC

7001 Kilo Avenue

Bartow, FL 33830

(o) 863.519.6331

(c) 863.559.1610

(f) 863.519.6361

bosek.john@cleanharbors.com

www.cleanharbors.com



From: Knauss, Elizabeth [mailto:Elizabeth.Knauss@dep.state.fl.us]

Sent: Friday, May 05, 2017 2:23 PM **To:** BOSEK, JOHN E; garcia.javier@epa.gov **Cc:** Desha, David A.; Madden, Melissa

Subject: Inspection follow up.

John – I spoke with our solid waste folks about the issues I observed around the mix tub. Can you send me verification that the issues we observed in the solid waste processing area have been corrected? Photos of the north side and back of the containment, along with a photo of the sump area would be helpful.

- Per the permit, the leachate collection system and sump are supposed to be cleaned out at least once per operating day.
- The waste outside the containment walls needed to be cleaned up.
- The gaps between the concrete and metal, and between the metal panels need to be sealed so that waste will not leak out.

Thanks









