

LIGHTING RESOURCES, LLC

1007 SW 16TH PL

OCALA, FL

Photo No. 2

Front of Site looking northeast at Administrative Offices and guest parking area.



DRIVEWAY TO LEFT OF BUILDING

BEFORE.....

Photo No. 3


Front of Site looking north along western edge of Site property with adjacent property (located to the west of Site) shown on the left.



Balcan Room Door next to Driveway

Photo No. 12

Northwest corner of Site looking south along west side of Facility Building and Site property (fencing on the right).






Thanksgiving November 28, 2019




Balcan Room Door next to Driveway -after







After....



Roof After.....



Installing New Balcan




New Balcan Conveyor View



New Conveyor for End Caps



Overhead door from Warehouse into Balcan Area B *After*



New Overhead door from Warehouse into Balcan Area B



New Overhead Door to Area C from Balcan Processing Room



New Interior HVAC and Ceiling and Lights

November 28, 2019 Fire

- Continued to operate sending spent lamps to Lighting Resource Facilities in Fort Worth, Texas and Johnson City, Tennessee
- ➤ Demolition cleared the entire room (Completed February 2020)
- Contractor rebuilt the Walls, Ceiling, HVAC, Lighting, Floor and Electrical.(Completed June 2020)
- Material still stored in trailers offsite at a secure location in Ocala awaiting processing. (July to current)
- New Balcan was received and installed by LR crew. (UK crew was not allowed to travel due to Covid.) (September 2020)
- ➤ Began processing lamps on a continuing basis with single crew. (Reduced staff due to Covid.) (October 2020)
- >Added second shift to tackle the stored trailers. (November 2020)

18

