## Citrus County Fire Reque

## FIRE PREVENTION INSPECTION REPORT

3600 W. Sovereign Path, Suite 141 • Lecanto, FL 34461 • 352-527-5527 • Fax 352-527-5404

Business Name: citras locaty A	endfill Tire Sterese	Business Phone: 726 - 5576
Physical Address: 230 W, C.		Business Hours:
Mailing Address:	City Limits: [ ] Y [ ] N	Responsible Party:
City: Locate	Zip Code:	Contact Info:
Plaza [ ] Yes [ ≯No:		AED[ ] KNOX[ ] LWRT[ ] DRILLS[ ] CEMP[
Unit # / Suite:		Type of Construction:
Owner/Manager:	Station: 23	Occupancy Class: 5 to 198
Owner/Mgr. Phone #:		Occupant Load:
F 11		Square Footage:
[ ] Initial [ ] Annual [ ] Re-inspection	[ ] Request [ ] Complaint [	] Other
CODE DEFICIENCIES:	-0.00 GR200 GP-0-100	
STORAGE	ELECTRIC EQUIPMENT	KITCHEN SUPRESSION SYSTEM
[ ] Improper storage of combustible material	Overloaded circuits	[ ] Filters missing or improperly installed
[ ] Storage too close to ceiling	[ ] Electrical panel obstructed	[ ] Extinguishment system not in accordance
Storage too close to electrical panel	[ ] Electrical panel / boxes open	w/NFPA 96
[ ] Unsafe storage	Coverplate missing     Temporary wiring / extension cords	[ ] Accumulation of grease in ducting  Date last inspected:
EXIT DEFICIENCIES	[ ] GFCI not functioning	Company:
Exits inadequate number or capacity     Aisles/corridors too narrow	[ ] HVAC equipment not maintained	COOKING EQUIPMENT
Exit door does not swing in direction of travel	FIRE ALARM	[ ] Accumulation of grease on/in cooking equipmen
Door not equipped with approved exit hardware	Fire alarm not provided	[ ] Cooking equipment maintenance
Exit doors inoperative or locked	[ ] Log book not provided	Date last inspected:
Exit blocked / obstructed     Emergency lights not provided or working	Fire alarm does not meet code  Fire alarm not inspected / maintained	Company:
Exit sign (s) not illuminated	Smoke detector not provided	HOOD SYSTEM
Exit sign (s) battery not operable	[ ] Smoke detector inoperative	[ ] Hood & duct system not in accordance
EXTINGUISHERS	Date last inspected:	
[ ] Extinguishers not provided	Company:	Company
[ ] Not proper type	SPRINKLERS/STANDPIPE	NFPA1: 33.1.10
Not inspected / tagged Not visible / accessible	[ ] System not inspected / maintained	WFP H 1
Inadequate number	Valves closed     Loaded sprinkler heads	Rims to be the
Not charged / operable	Heads obstructed or too close to stock	removed
Not properly installed	[ ] FDC deficiency	air.cal
Date last inspected:	[ ] Missing spare heads / wrench	
Type:Number:	Date last inspected: QtrAnnual Company:	
	System Type:	
Deficiencies noted below may cause a fire, contribute to the spread of fire, or cause undue injury in the event of a fire. Deficiencies must be corrected FORTHWITH. For additional information or assistance, please call: 352-527-5527. BUILDING PERMITS ARE REQUIRED FOR ALL RENOVATION / REPAIRS.		
DECUMPANTO / COMMENTO		
REQUIREMENTS / COMMENTS:  1. Fire Extinguisher et light recycling requires tas		
louder ck Fer time Exting.		
A15 7018		
4/2-/-	0 " 0 "	512/19
Inspection Date / Time: 4/25/19	Compliance Date:	
Inspector: 144559 6.11:~		Rev. 8/18
Page 1 white - office YELLOW -customer Rev. 8/18		