

SLL  
Completed

Fla. Tire Recycling, Inc.  
Joe Lewis

Southern  
roadway  
looking  
east

10.C.#2



10A.#2

MSSW  
SE  
corner  
of  
property





SE.  
corner  
10.A.#2  
MSSW



west  
side of  
Rangevine  
Road  
looking  
north





Fla. Fire Recycling, Inc.

South canal  
- looking  
north at  
water  
sheet flow  
into canal



Same  
as above





So. Canal  
- sheet flow  
of water  
into canal  
- looking  
north  
10D #1  
S.A.



Pile 18-T  
from  
S.A.





Fla. Tire Recycling, Inc.



South  
canal  
looking east  
50' wide  
lane.  
10D #1.  
S.A.



10D #1.  
S.A.



South  
Canal  
looking  
north



same  
as above





Fla. Tire Recycling Inc.



N.W.  
corner.  
Pile #15  
row  
#15 of S.A.



west boundary  
looking south  
10D. #1  
A.



westside  
of property  
- water  
flowing  
on site  
south to  
broken  
earth plug -



looking  
north  
along  
western  
boundary











2 1794

2 1794

2 1794

#10 D#1  
 S.A.  
 Pomeranian (head)  
 looking north  
 of T 13 to S-11  
 of 311-107 A.  
 No fine leaves  
 FC # 13 FC #2





Remnants  
of S11 to  
T-13 from  
Wharf of  
S.A.

Fl. Inc P



Fla. Tire Recycling, Inc.



west side  
along  
Range Line  
Road  
looking  
north  
at new  
southern access roadway