

ENVIRONMENTAL PROTECTION DIVISION

Lori Cunniff, CEP, CHMM, Deputy Director

Community, Environmental and Development Services Department

800 Mercy Drive, Suite 4 Orlando, Florida 32808-7806 (407) 836-1400 • FAX (407) 836-1499 www.ocfl.net

May 24, 2013

Wilson Estevez Taft Recycling, Inc. 375 West 7th Street, Taft Orlando, Florida 32824

RE: Taft Recycling Inc. Materials Recovery Facility

Permit No. SW-022429-MRF/TF-06-1105 Monthly Compliance Inspection Report

Dear Mr. Estevez,

An inspection was conducted at your facility on March 28, 2013. Under the authority of Orange County Code Chapter 32, Article V, the inspection was designed to ascertain compliance with applicable Florida law, including Sections 62-701 through 722 Florida Administrative Code, regarding solid waste management.

Any potential non-compliance issues are listed in the attached report. Please respond in writing, by the date of resolution noted on the inspection report, describing what you have done to come into compliance. Address your response to Ricardo A. Moore at the letterhead address. A follow-up inspection will be conducted to verify compliance. Please call (407) 836-1454 if you have any questions.

Sincerely,

Arnaldo Mercado

Environmental Programs Administrator

analis Efercado

RAM/DB/AM:sgt

EC: Landfill Inspection File

Gloria DePradine, Florida Dept. of Environmental Protection, gloria.depradine@dep.state.fl.us

INSPECTION REPORT MATERIALS RECOVERY FACILITY | TRANSFER STATION

Environmental Protection Division 800 Mercy Drive, Orlando, FL 32808 Ph 407.836.1400; Fax 407.836.1499




Fac. Name:	Taft Recycling, Inc.	Purpose:	Monthly Foll	low-up 🔲 Ot	her
Location:	375 West 7 th Street, Taft	Insp. date:	Mar 28, 2013	Time:	09:00 - 11:50
Permit #:	SW-022429-MRF/TS-06-1105	Inspector:	Ricardo Moore	Site Rep:	Wilson Estsvez

The requirements listed below provide an opportunity for the Division's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Item	Requirements	Ok	Not Ok	Unk	N/A
1	Facility permitted [32-214 (a)(1)] Expiration date: May 8, 2016	\boxtimes			
2	Prohibited routes free of inbound/outbound hauling vehicles? [32-216(a)(16)] Roads: N/A	\boxtimes			
3	Haul route free of litter from site and inbound/outbound vehicles? [32-216(a)(13)] Roads: Sidney Hayes Road, Landstret, Fourth St, and Vineland.	\boxtimes			
4	Site entrance access road paved? [32-216(a)(6)]	\boxtimes			
5	Entrance clear of staging vehicles, dirt, and other obstructions or interference? [32-216(a)(18)]	\boxtimes			
6	Sign at entrance listing acceptable waste? [32-216(a)(14)]	\boxtimes			
7	Sign at entrance listing hours of operation? [62-701.710(4)(c)1]	\boxtimes			
8	Scalehouse or gate attendant present to observe and control incoming traffic? [32-216(a)(13)]	M	Ц	Ц	Ц
9	Haul vehicles with waste covered/tarped when entering/exiting facility?	M	Ц	Ц	Ц
10	Current Orange County permit displayed and plans available on site? [32-214(h)]	\boxtimes	Ц	닏	닏
11	Current FDEP permit displayed?		Ц	닏	닏
12	Is a trained operator on duty at the facility whenever the facility is operating? [62-701.710(4)(c)1]		Ц	Ц	Ц
13	Are training records current and available on-site at the facility? [62-701.710(4)(c)]	\boxtimes	Ш	Ш	Ш
	Operators: Wilson Estevez, and tony Benjamin.; Spotters: Bruce, Danny, Steve, Tonyand Wilson if				
1.4	necessary.		\Box	$\overline{}$	П
14	If scale used to quantify waste, is it calibrated each year and functional? [32-216(a)(22)] Date last calibrated: February 9, 2013			_	
15	At least 3 detailed random load inspections being conducted and logged each week? [32-216 (a)(14)] (For MRF, inspections do not need to be logged, but rejected loads do.)	\boxtimes		Ш	Ш
16	Setbacks clear unless authorized (see plans)? [32-216(a)(11)]	M			
17	Landscaping planted and maintained (see plans) [32-216(a)(11)]	\boxtimes			
	(e.g. grass; canopy trees 40 ft centers along street; 60 ft elsewhere; 10 ft tall; 2.5" dia.)				
18	Berms and other visual buffers established and maintained (see plans) [32-216(a)(11)]	\boxtimes			
19	Is access to the facility properly controlled (6 ft chain-link fence w/ locking gate)? [32-216(a)13); 62-701.710(4)(c)]	\boxtimes			
20	Legible "No Trespassing" signs (3 sq ft, 5-inch letters, 500 ft centers, and corners)? [32-216(a)(13)]	\boxtimes			
21	Stormwater ponds and other controls maintained clear of vegetation/debris ?[32-216(a)(32)]	\boxtimes			
22	Objectionable odors controlled from leaving site? [62-701.710(4)(d)]	\boxtimes			
23	Adequate dust control?	\boxtimes			
24	Adequate vector control?	\boxtimes			
25	For areas not enclosed, is litter controlled and are litter control devices maintained? [62-701.710(3)(a)]	\boxtimes			
26	Is the leachate collection and removal system maintained and operated as required?[62-701.710(3)(b)]	\boxtimes			
27	Are all drains and leachate conveyances kept clean so that leachate flow is not impeded? [62-701.710(4)(b)]	\boxtimes			
28	Are putrescible wastes stored no longer than 48 hours or as otherwise allowed in the Operation and Maintenance Plan? [62-701.710(4)(b)]	\boxtimes			
29	Are areas where putrescible waste is stored or processed cleaned at least weekly (or more frequently if required by permit) to prevent odor and vector problems? [62-701.710(4)(b)]	\boxtimes			
	(Permit condition for dry sweep cleaning: Yes wet cleaning: When needed.)				

	incoming waste? [32-216(a)(14); 62-701.710(4)(c)2] Names of spotters present: Bruce on front end		L	Ш	Ш
-	<u>loader</u>				
31	Is the facility accepting only permitted waste types? [32-216(a)(14)]	\boxtimes	L		Ш
22	Waste types authorized: Class I, Class III and C&D.		_		
32	Are unauthorized wastes removed from the waste stream and placed into appropriate containers for disposal at a permitted facility? [62-701.710(4)(c)2]				
33	Regulated wastes properly stored in area separate from disposal or sorting areas? (e.g. secondary containment) Photo.				
34	Unauthorized waste volume less than one 20-cu yd container, or as allowed in the Operation and Maintenance Plan? [32-216 (a)(14)] Amount allowed: Waste kept at 10 cu- yards or less.				
35	Recovered materials stored within permitted dimensions and volumes?	\boxtimes			
36	Recovered materials stored in a manner that prevents threats to ground water quality or air quality standards? [62-701.220(2)]				
37	Recovered materials shipped out within one year? [62-701.220(1)]	\boxtimes			
38	If groundwater wells required (e.g. outdoor processing of C/D), are they intact and properly maintained? [62-701(2)(b); 62-701.710(10)(b)] See site sketch.				\boxtimes
39	Unauthorized open-burning of solid waste prohibited. [62-701.300(3)]				
				1	
Tool	Description of issue(s) requiring follow-up by the facility	Dura	u k	do	
Issu	such as providing additional information or corrective action	Due	by	' da	te
Issu		Due	by	' da	te
Issu	such as providing additional information or corrective action	Due	e by	da	te
Issu	such as providing additional information or corrective action	Due	: by	da	te
Issu	such as providing additional information or corrective action	Due	by	da	tte
Issu	such as providing additional information or corrective action	Due	by	da	tte
Issu	such as providing additional information or corrective action	Due	by	da	tte
Issu	such as providing additional information or corrective action 1	Due	by	' da	tte
Issu	such as providing additional information or corrective action	Due	· by	da	tte
Issu	such as providing additional information or corrective action 1	Due	by	da	tte
Issue	such as providing additional information or corrective action 1	Due	by	da	tte





Photograph Access road parking lot facing W. # 1




Photograph | Waste was observed standing beyond doors 1 and 2 on access road. Please see notes # _2 | section.



Photograph # 3 Fully enclosed unauthorized waste storage roll off.



Photograph Access road/parking lot on the W. side of the facility facing S. #_4_



Photograph # _5

E. side of facility access road/parking lot facing N.



Photograph # _6

S.W. storm water retention pond drain appears unobstructed.



Photograph S.E. storm water retention pond drain appears unobstructed.



Photograph Storm water retention pond was clean.



Photograph B

Bailed cardboard stored on E. side of facility access road/parking lot.



Photograph # <u>10</u>

Roll off filled with waste tires.