From:	Taylor, Kaitlyn A
To:	cgregory@wpcorp.net
Cc:	Knight, Jade; avmiranda wpcorp.net; emiranda wpcorp.net
Subject:	Exit Interview - World Petroleum Corp (FLD980709075)
Date:	Friday, November 1, 2024 12:55:00 PM
Attachments:	image001.png

Good Afternoon,

This email serves as an exit interview for the Routine Compliance Evaluation Inspection conducted at the facility World Petroleum Corp (FLD980709075) on 10/30/2024, located at 3650 SW 47th Ave, Davie, FL 3331. First, I want to thank you for your level of cooperation and for your time given during the inspection.

As discussed during our visit, I am reaching out to request some additional information and supporting documentation to facilitate the completion of the inspection report that would count toward your compliance status. Please provide the following by **11/15/2024**:

- Photo documentation of all containers of used oil labeled with the words "used oil" **per 40 CFR 279.22(c)(1) and 62-710.401(6) F.A.C.**
    - One 5-gallon bucket and one 55-gallon drum was observed on site not labeled "used oil".

- Photo documentation of the roll-off container of processed oily solids labeled with the words "Processed Solid Waste" per **permit 54228-010-HO & 54228-011-SO Part II Subpart E - Non-Hazardous, Non-Used Oil Waste Conditions #8.**

- Photo documentation of a copy of the facilities permit kept at the worksite of the permitted activity per **permit 54228-010-HO & 54228-011-SO Part I - General and Standard Conditions #7.**

- Photo documentation of the date of the annual review of the contingency plan noted in the written operating record at the facility **per permit 54228-010-HO & 54228-011-SO Part II Subpart A – General Operating Conditions #4e.**

- Photo documentation of the tank farm secondary containment cracks and deteriorated epoxy sealant repaired. Please provide a timeline for the repairs to be reviewed by the Department.
    - **Permit 54228-010-HO & 54228-011-SO Part II Subpart B - Used Oil Conditions #8** states that facility should repair any cracks or gaps in the secondary containment floor and perimeter walls prior to resuming operation and **40 CFR 279.54(d)(2)** states that the entire containment system must be sufficiently impervious to used oil.
    - Based on the observation/photos taken at the time of the inspection the Department determined that repairs/resealing is necessary.

If you have any questions or concerns, please feel free to contact me.

Kind regards,

Kaitlyn Taylor
Environmental Consultant
Florida Department of Environmental Protection
Southeast District – West Palm Beach
Kaitlyn.A.Taylor@floridadep.gov
O: 561.681.6628
In O: 7:30am-3:30pm