From:	Jackson, Jackey
To:	Lubozynski, Tom; Rush, Kim
Subject:	FW: Pics 3
Date:	Thursday, September 11, 2014 1:38:37 PM
Attachments:	ATT63789959.txt ATT63789960.txt ATT63789961.txt ATT63789962.txt ATT63789963.txt

---

Tom/Kim,

Sending pictures of some of the improvements we have made since your last visit. We have resolved the drainage problem on the south east corner of the asphalt cap, by creating a small swell and adding a culvert pipe from the top edge of the end of the berm down to the bottom, it is working well, we have not had any more erosion problems. We have built an asphalt flume on the north west side of the asphalt pad, this also is working well.

We have removed the liners from the bottoms of both retention pond and both ponds are dry. We are getting quotes on an engineering firms to survey the asphalt cap and develop a plan to correct the ponding problems the asphalt pad is experiencing.

The grassy cap is in good repair and all the gas vent pipes are in-tack. Their should be several emails coming with pics.

-----Original Message-----
From: Jackson, Jackey
Sent: Thursday, September 11, 2014 1:26 PM
To: Jackson, Jackey
Subject: Pics 3