

Thursby, Kim

From: Curtis, Jeff [Jeff.Curtis@safety-kleen.com]
Sent: Wednesday, May 15, 2013 12:58 PM
To: Epost HWRS
Subject: RE: Safety-Kleen Systems, Inc. (Tampa) FLD 980 847 271,Natural Attenuation Monitoring Report #3 dated May 9, 2013

Received.

Thank you,

Jeff Curtis EHS Manager | Safety-Kleen | A Clean Harbors Company | Boynton Beach, FL | jeff.curtis@safety-kleen.com

561.738.3026 (o) | 561.523.4719 (c) | 561.731.1696 (f) | safety-kleen.com



From: Epost HWRS [<mailto:EpostHWRS@dep.state.fl.us>]
Sent: Wednesday, May 15, 2013 12:52 PM
To: Curtis, Jeff
Cc: Bahr, Tim; Goddard, Charles; Knauss, Elizabeth; McGinnis, Sean; Schoepke, Robert; RStebnisky@ectinc.com; Russell, Merlin; Tripp, Anthony
Subject: Safety-Kleen Systems, Inc. (Tampa) FLD 980 847 271,Natural Attenuation Monitoring Report #3 dated May 9, 2013

In an effort to provide a more efficient service, the Florida Department of Environmental Protection's Hazardous Waste Regulation Section is forwarding the attached document to you by electronic correspondence "e-correspondence" in lieu of a hard copy through the normal postal service.

We ask that you verify receipt of this document by sending a "reply" message to epost_hwrs@dep.state.fl.us. (An automatic "reply message" is not sufficient to verify receipt). If your email address has changed or you anticipate that it will change in the future, please advise accordingly in your reply. You may also update this information by contacting Kim Thursby at (850) 245-8792.

The attached document is in "pdf" format and will require Adobe Reader 6 or higher to open properly. You may download a free copy of this software at www.adobe.com/products/acrobat/readstep2.html.

Please note that our documents are sent virus free. However, if you use Norton Anti-virus software, a warning may appear when attempting to open the document. Please disregard this warning.

Your cooperation in helping us affect this process by replying as requested is greatly appreciated. If you should have any questions about the attached document(s), please direct your questions to the contact person listed in the correspondence.

Tim Bahr
Environmental Administrator
Hazardous Waste Regulation
Department of Environmental Protection
E-Mail Address: epost_hwrs@dep.state.fl.us

Please take a few minutes to share your comments on the service you received from the department by clicking on this link [DEP Customer Survey](#).



FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

BOB MARTINEZ CENTER
2600 BLAIRSTONE ROAD
TALLAHASSEE, FLORIDA 32399-2400

RICK SCOTT
GOVERNOR

HERSCHEL T. VINYARD JR.
SECRETARY

May 15, 2013

Sent Via E-mail

Jeff.Curtis@safety-kleen.com


Mr. Jeff Curtis
Safety-Kleen Systems, Inc.
5309 24th Avenue South
Tampa, Florida 33619

Subject: Safety-Kleen Systems, Inc. (Tampa) FLD 980 847 271, Operating Permit No. 34744-HO-007, *Natural Attenuation Monitoring Report #3* dated May 9, 2013

Dear Mr. Curtis:

Your February 6, 2012 Septic System Plan/Report indicated that Safety Kleen's long-term solution was to connect to the sewer system. Your estimated date of completion was originally May 2012, one year ago. Periodically, you have informed the Department of delays or status, the latest being in your e-mail dated May 10, 2013.

Our February 17, 2012 approval of the Plan/Report instructed you to notify the Department (Tampa and Tallahassee offices) once your connection to the sewer system was completed. To date, you have not completed your proposed corrective actions for this SWMU. Your current report indicates that well MW-2 continues to have the highest groundwater head:



Mr. Jeff Curtis
Page 2 of 2
May 15, 2013


Groundwater flow is out of equilibrium because wastewater continues to enter the septic tank/drainfield area.

Your May 10, 2013 e-mail indicates that you expect all legal issues be resolved and necessary permits in place before the end of this month and that contractors will begin work immediately upon receipt of the permit. As is, the potential still exists for discharges of contaminants to the septic tank/drainfield area.

We agree that according to paragraph 62-780.690(8)(g), Florida Administrative code, that a minimum of two consecutive clean sampling events are required for consideration of the NFA. However, these events will begin once the sewer connection has been completed and groundwater reaches equilibrium. Your next groundwater sampling must be performed in July 2013.

If you have any questions, please call me at 850-245-8796 or e-mail me at merlin.russell@dep.state.fl.us

Sincerely,



Merlin D. Russell Jr.
Professional Geologist II
Hazardous Waste Regulation

MR/mdr

cc via e-mail: Beth Knauss, FDEP Tampa, Elizabeth.Knauss@dep.state.fl.us
Sean McGinnis, FDEP Tampa, Sean.McGinnis@dep.state.fl.us
Bob Schoepke, Safety-Kleen, Robert.Schoepke@safety-kleen.com
Rick Stebnisky, ECT, RStebnisky@ectinc.com