STATE OF FLORIDA

DEPARTMENT OF ENVIRONMENTAL REGULATION

SOUTHWEST DISTRICT

7601 HIGHWAY 301 NORTH TAMPA, FLORIDA 33610

813-985-7402 SunCom - 570-8000



BOB GRAHAM

VICTORIA J. TSCHINKEL SECRETARY

DR. RICHARD D. GARRITY / DISTRICT MANAGER

August 25, 1986

Ms. Ellen J. Jurczak, P.E. Environmental Engineer/Permit Manager Safety-Kleen Corporation 777 Big Timber Road Elgin. Illinois 60120

MEGRANE

AUG 29 1986

Re: Safety-Kleen Corp. 980 847 271

Construction Permit Application HC29-118986

Second Notice of Deficiencies

Hazardous Waste

Dear Ms. Jurczak:

We acknowledge receipt of your response to our first notice of deficiencies as submitted on August 4, 1986, and additional information received on August 12, 1986. However, we have reviewed your application and found it incomplete due to the lack of some information, and because amendments are required in some parts of the application. The required information and amendments necessary to complete your application are itemized in attached sheets.

When a permit application is incomplete, all processing of the application is suspended. Pursuant to Section 120.60, Florida Statutes, the Department may deny a permit application if the applicant, after receiving timely notice, fails to correct errors, omissions, or supply additional information within a reasonable period of time.

We expect to receive your submittal addressing the information requested in this notice within fifteen days from this date.

Sincer#ly,

Armando Gonzalez Permitting Engineer Hazardous Waste Section

AG/br Enclosure

cc: Satish Kastury – DER/Tallahassee ✓ Stanley Walczynski – Safety-Kleen Corp.

Deficiencies

Part I - General

A. General Information

 Items 5 and 20 of application form show incorrect EPA I.D. numbers. Also, boxes in item #2 were not filled out. Resubmit both pages.

B. Site Information


 Submit a l":2000' scale map containing map scale, orientation, date and drinking water wells within 1/4 mile.

D. Operation Information

- 1. Submit a drawing locating the wet dumpsters.
- 2. To comply with 40 CFR 270.14(a), drawings shall be certified by a registered engineer.

Part III - Tanks

1. In view of the attached Conversation Record sheet, submit a testing procedure for tanks. Inspection logs to record results should also be provided.



CONVERSATION RECORD

Permit No. South State 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Date June 16, 1986	Subject Safety Clean Facility.
County Hisphmaigh Mr. Harry Mattingly Telephone No. 623-1126 Representing Safety Cloam M Telephoned No. 1 Was Called [] Scheduled Meeting [] Unscheduled Meeting Other Individuals Involved in Conversation/Meeting Summary of Conversation/Meeting	Time 3:00 pm	Subject <u>Salety Clean Facility.</u> Solvent Spill Permit No.
Representing Safety Clean M Telephoned Me [] Was Called [] Scheduled Meeting [] Unscheduled Meetin Other Individuals Involved in Conversation/Meeting Summary of Conversation/Meeting		County 11,1800 mough
Representing Safety Clean M Telephoned Me [] Was Called [] Scheduled Meeting [] Unscheduled Meeting Other Individuals Involved in Conversation/Meeting Summary of Conversation/Meeting	Mr. Harry Mattingly	Telephone No. 623-1126
Melephoned Me [] Was Called [] Scheduled Meeting [] Unscheduled Meeting Other Individuals Involved in Conversation/Meeting Summary of Conversation/Meeting		
Summary of Conversation/Meeting		
Summary of Conversation/Meeting ms mattinger, called and inpatter a 45 gallen galvent (mineral spirits) leake at their new facility. They were testing new tanks for lanks and found one, resulting in the spill. The spill was rentained in a concrete limed containment are and the spill was to be cleaned up wring absorbant towels. The towels were them to be placed in a drum and sent to the tromp office in Elgin, Ollimois. Location: 54 th are and 24th St	Other Individuals Involved in Conv	ersation/Meeting
supported a 45 gallen solvent (minoral spirits) leake at their new facility. They were testing new tanks for loaks and found one, resulting in the spill. The spill was rentained in a concrete limed containment are and the spill was to be closined up wring absorbant towards. The towards were them to be placed in a drum and sent to the rooms office in Elgin, Ollimois. Location: 54 th are and 24th St		
at their new facility. They were testing new tanks for leaks and found one, resulting in the spile. The spile was rentained in a concrete lined contrumner area and the spile was to be cleaned up wing absorband towels. The towels were them to be placed in a drum and sent to the rums office. In Edgin, Ollimois. Location: 54 th are and 24th St	Summary of Conversation/Meeting	ms mattingly called and
at their new facility. They were testing new tanks for leaks and found one, resulting in the spile. The spile was rentained in a concrete lined contrumner area and the spile was to be cleaned up wing absorband towels. The towels were them to be placed in a drum and sent to the rums office. In Edgin, Ollimois. Location: 54 th are and 24th St	inporteri a 45 gallon solu	sent (mineral spirits) leale
leaked and found one, resulting in the spill. The spill was rentamed in a concrete limed contamment area and the spill was to be cleaned up wing absorbant towers. The towels were them to be placed in a drum and sent to the home office in Elgin, Ollimais. Location: 54 th are and 24th St		_
spill was rentained in a concrete limed containment are and the spill was to be cleaned up wing absorbant towels. The towels were them to be placed in a drum and sent to the rumo office in Elgin, Ollimois. Location: 54 th are and 24th St		<i>y</i> .
absorband towells. The towels were them to be placed in a drum and sent to the home office in Elgin, Delimois. Location: 59 th are and 24th St	•	\mathbf{O}
placed in a drum and Sent to the humo office in Elgen, Delimois. Location: 54 th ave and 24th St	area and the spill was	to be cleaned up woung
Elgin, Ollimois. Location: 54 th ave and 24th St	absorband towells. The 4	and were them to be
Elgin, Ollimois. Location: 54 th ave and 24th St		
Location: 54th ave and 24th St		
	Location: 54 th Que an	d 24th St
(continue on another Signature Karen Zwolak		
(continue on another Signature Karen Zwolak		
(continue on another Signature Haren Zwolak		
(continue on another Signature Haren Zwolak		
that if page 1	(continue on another sheet, if necessary)	Signature Hassa Dusalala
Title Engineer I, Ondust Was		Signature Maren Zwolak. Title Engineer I, Andusi Wasi