April 15, 2019



Bryan Baker, P.G.
Florida Department of Environmental Protection
Environmental Administrator, Hazardous Waste Program and Permitting
2600 Blair Stone Rd MS4560
Tallahassee, FL 32399

Mr. Baker,

As required by Triumvirate Environmental Services, Inc. (TEI) hazardous waste operating permit #26916-009-HO and solid waste operating permit #0288830-006-SO, Triumvirate is providing the following report regarding the vehicle fire that occurred in the parking lot area of the 10100 Rocket Blvd, Orlando, FL 32824 facility. There were no material releases to the environment, no impacts to public safety or health, and no injuries to onsite personnel from this incident. A full summary of the incident is provided below. A copy of the Orange County Fire Department's report on the incident is also attached for your reference.

TEI EPA ID #:

FLD980559728

TEI Vehicle #:

7005

Vehicle Make:

1999 Freightliner

Tag #:

FL P17 72A

VIN:

IFUYDXYB3XPA73026

RECEIVED

APR 1 6 2019

**DEP Central District** 

The Vac Truck was used starting at 6:45AM on the morning of April 11, 2019 for job number 339034 at Polynt Composites USA, Inc., located at 10124 Rocket Blvd, Orlando, FL. Triumvirate was hired to pump out water from a tank as it was being cleaned. The material being pumped into the tank of the vehicle was approximately 1,380 gallons of non-hazardous, non-regulated water with inert solvents. The vehicle was running intermittently at the job site until 12:15PM when the job was completed.

The Vac Truck returned to the Triumvirate facility at 12:25PM and parked in the southwest corner of the property. When exiting the vehicle, the driver noticed a burning smell and checked under the wheel wells and noticed what appeared to be a small amount of white smoke coming from the engine compartment. The employee informed their supervisor about the white smoke. It was thought that the vehicle was simply overheating since it had been used that morning.

Approximately 3 minutes later the driver went outside and noticed flames coming from the vehicle and immediately let their supervisor know of the situation. It was immediately noted by management that the fire was too big for facility personnel to extinguish. In accordance with Triumvirate's Contingency Plan, emergency services were immediately called via 911 at approximately 12:30PM. The facility was evacuated, and police and fire arrived at the site at approximately 12:40PM. The Orange County Fire

Department were provided a copy of the manifest to show that there were no hazardous materials on the vac truck and the fire was extinguished by the fire department.

Waste material was not the cause of the fire. The suspected cause of the fire was from component(s) in or near the area of the dashboard of the truck. This is based upon the inspection of the truck by the Orange County Fire Department and their observation that the fire appeared to have started somewhere near the dashboard area and spread from there.

At no time was there a danger to the rest of the facility or the waste that was onsite at the facility. The Vac Truck was approximately 100 feet away from the rest of the facility. The cargo and fuel tanks of the Vac Truck were not compromised. The contents of both the cargo tank, as well as the vehicle fuel tanks, will be removed once the truck is inspected by an insurance adjuster. Once removed, the waste will be disposed at an authorized disposal facility. The cargo and fuel tanks will be inspected daily until the contents are removed from the tanks.

Please contact me if there are any further questions or concerns regarding this incident.

Respectfully

Randy D. Troy

Environmental, Transportation, Safety and Compliance Specialist

Triumvirate Environmental Services, Inc.

10100 Rocket Blvd.

Orlando, FL 32824

rtroy@triumvirate.com

(407) 859-4441

Enclosure: Orange County Fire Department Report 2019-0035911

CC: Katie Wright, FLDEP

Richard Barry, Director of Compliance, Triumvirate
Kevin Coulon, General Manager Southeast Division, Triumvirate

RECEIVED

APR 1 6 2019

**DEP Central District** 



## Orange County Fire Rescue

Station: **73**Shifts Or Platoon: **A Shift** 

Location:
10100 ROCKET BLVD #STE1
Orlando FL 32824

Lat/Long: N 28° 25′ 4.14″ W 81° 23′ 14.3″

Zone:

2 - Battalion 2

Location Type: 1 - Street address

Map Page: **45-11** 

Population Density: Urban

Incident Type:

132 - Road freight or transport vehicle fire

FDID: 07252

Incident #: 2019-0035911 Exposure ID: 39266587

Exposure #: 0

Incident Date: **04/11/2019**Dispatch Run #: **191010231** 

Report Completed by:	Raike , Frank W.	<b>ID:</b> 107842	Date: 04/11/2019
Report Reviewed by:	Not Reviewed		
Report Printed by:	Alex, Bethany	<b>ID:</b> 129974	Date: 4/12/2019 Time: 11:22

Structure Ty	ype: Prope	rty Use: <b>569</b>	- Professional	supplie	s, servi	ces			
Automatic E	extinguishme	nt System Pre	sent: Detect	ors Prese	ent: 🗆	Cause	of Igr	nition: <b>Unintentional</b>	
Aid Given or	r Received:	None	Primary action t	aken:	10	- Fire c	contr	ol or extinguishment, other	
Additional a	ctions:	80 - Infe	ormation, inves	stigation	n & enf	orcem	ent, e	other, -	
Losses		Pre-Incide	nt Values						
Property:	\$0.00	Property:		Civilian	Injuries	:	0	Fire Service Injuries:	0
Contents:	\$0.00	Contents:		Civilian	Fatalitie	es:	0	Fire Service Fatalities:	0
Total:	\$0.00	Total:		Total C	asualties	ŝ:	0	Total Fire Service Casualties:	0
Total # of a	pparatus on	call:		2	Total #	of per	sonne	el on call:	7

## **NARRATIVE (2)**

Narrative Title: n/a

Narrative Author: Byrne, Pamela Narrative Date: 04/11/2019 14:26:18 Narrative Apparatus ID: Q55

## Narrative:

Q55 responded to Truck fire Triumvirate Environmental Inc of Florida. Upon arrival front of the truck was fully involved. 1 3/4 line pulled and water/foam on the fire. Hydrant water established. Fire knocked down and overhaul completed. Prior to the fire while parked and running the worker driving the truck noticed that there was white smoke coming from the passenger side of the truck. The worker then went into the front office to notify the staff. By the time they came back out the truck was fully involved and 911 was called. Upon further inspection it appeared the fire starting in the dashboard area and spread from there. Cargo tank was not compromised (which contained water and a cleaning solvent). Scene was left with Manager.

Initial Vehicle involved: Vin# 1FUYDXYB3XPA73026 Lic Pl # N6597V. Truck owned by Triiumvirate Environmental INC.

Exposed vehicle (was moved during the fire) was initially parked on a different property near the involved truck close enough to sustain minor front end damage from heat. Vin #5N1AR2MN2DC645857 Lic PI# JB978R.

RECEIVED

APR 1 6 2019

**DEP Central District** 

## NARRATIVE (3)

Narrative Title: Truck Fire
Narrative Author: Raike, Frank
Narrative Date: 04/11/2019 21:15:10

Narrative Apparatus ID: E52

Narrative:

Assisted with firefighting and securing water supply

Unit	<b>E</b> 52	Unit	Q55
Type:	Engine	Type:	Quint
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	4	# of People	3
Alarm	04 /11/2019 12:35:08	Alarm	04 /11/2019 12:35:08
Dispatched	04 /11/2019 12:37:46	Dispatched	04 /11/2019 12:35:42
Enroute	04 /11/2019 12:37:59	Enroute	04 /11/2019 12:36:22
Arrived	04 /11/2019 12:47:18	Arrived	04 /11/2019 12:46:05
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	04 /11/2019 13:25:46	Cleared Scene	04 /11/2019 13:25:06
In Quarters	/ / : :	In Quarters	/ / : :
In Service	04 /11/2019 13:25:46	In Service	04 /11/2019 13:25:06
Number Of People no	, - ,	All Oct FICE	0.,,11,2013 13.23.00

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Engine area, running gear, wheel area	Heat Source	Heat from powered equipment, other
Item First Ignited	Electrical wire, cable insulation	Fire Is Confined To Object Of Origin	TRUE
Type Of Material		Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Electrical failure, malfunction,	, other	
Human Factors Contributing	None		
Mobile Property Involve And Type	Involved in ignition and burned	Mobile Property Type	Tank truck - nonflammable cargo
Mobile Property Make	Other Make	Mobile Property Year	1999
Mobile Property Model		License Plate	N6597V
State	FL	VIN	1FUYDXYB3XPA73026

PEOPLE PERSON 1				
Is Owner Telephone Num	False	Business Name Involvement	General Manager of the businees involved	
Name	DEI	Date of Birth	General manager of the businees involved	
Address				

PEOPLE PERSON 2			
Is Owner	False	Business Name	
Telephone Number		Involvement	Car was damaged from fire
Name		Date of Birth	
Address			

CUSTOM FIELDS FORM	
Was the PIP used?	No
Does the PIP require up-dating?	
If PIP requires updates, please explain.	
How much water was used?	
Fire attack methods	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Alvera, Alec	FF		E52
Byrne, Pamela J.	LT/PM		Q55
Caamano, Jose A.	EN		E52
Capps, John M.	FF		Q55
Kabboord, Kai Sage	FF		E52
Lennon, Daniel P.	EN		Q55
Raike, Frank W.	LT/PM		E52