

Eckoff, Michael

From: Eckoff, Michael
Sent: Monday, May 4, 2020 2:52 PM
To: Hartshorn, Justin T; Cook, Robert
Cc: Klawinski, Tyler T; Troy, Randy D; Barry, Richard M; Coulon, Kevin P; Lombardi, Michael W
Subject: RE: Triumvirate Environmental Services Inc. - Roof Repairs at 10100 Rocket Blvd (Orlando)

Hello Justin,

Thank you for the information. Please keep us updated on the progress.

Thank you and be safe,
Michael

From: Hartshorn, Justin T <jhartshorn@triumvirate.com>
Sent: Monday, May 4, 2020 1:49 PM
To: Cook, Robert <Robert.Cook@dep.state.fl.us>; Eckoff, Michael <Michael.Eckoff@FloridaDEP.gov>
Cc: Klawinski, Tyler T <tklawinski@triumvirate.com>; Troy, Randy D <rtroy@triumvirate.com>; Barry, Richard M <rbarry@triumvirate.com>; Coulon, Kevin P <kcoulon@triumvirate.com>; Lombardi, Michael W <MLombardi@triumvirate.com>
Subject: Triumvirate Environmental Services Inc. - Roof Repairs at 10100 Rocket Blvd (Orlando)

Good Afternoon Bob and Michael,

Triumvirate Environmental Services, Inc. (TESI) operates a hazardous waste facility located at 10100 Rocket Blvd, Orlando, FL 32824 under Permit #26916-009-HO (hazardous waste) and 0288830-006-SO (solid waste). TESI needs to replace the remainder of the roof on the facility and install new skylights. TESI is providing the following information prior to physical alterations to the facility in accordance with Part I, Section 12(e) of Permit #26916-009-HO.

Summary description of the project:

Industrial Commercial Roofing (ICR) has been contracted to perform roof repair and skylight replacement work on the rest of the roof that was not impacted by the repairs in October 2019. ICR is the same company that did the previous roof work. They are estimated to start work activities in mid-May 2020 and are projected to conclude the work in 1-2 weeks. An exact start date is not known at this time. They are starting to order materials and are not certain on when they will arrive. Triumvirate will ensure ICR contractors have been trained on the necessary safety and emergency action plan procedures while they work at the site.

Evaluation of effect on facility:

The facility operation schedule will be modified to ensure waste operations do not interfere with the roof repair activities. All waste will continue to be managed in accordance with TESI's hazardous and solid waste operating permits.

If you have any questions on the proposed work, please let me know.

Regards,

Justin Hartshorn, CHMM, CPEA
Corporate Environmental Compliance Auditor | Triumvirate Environmental, Inc.
200 Inner Belt Road, Somerville, MA 02143

Office: 617-715-8902 | Mobile: 304-373-4989
jhartshorn@triumvirate.com | www.triumvirate.com