

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number FLD092980150	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 022127867 JJK		
5. Generator's Name and Mailing Address MOSAIC FERTILIZER - SOUTH PIERCE 16830 CIRCUS CROSSING DR LITHIA, FL 33547 Generator's Phone: 868-844-5303			Generator's Site Address (if different than mailing address) ELECTRICAL ENGINEERING ENTERPRISE 5316 E. HENRY AVE. TAMPA, FL 33610 NICOLE WILLIAMS 813-740-9601				
6. Transporter 1 Company Name ACTION RESOURCES			U.S. EPA ID Number ALR000007237				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address TEI OF ALABAMA LLC 101 PARKWAY EAST DELL CITY, AL 35125 Facility's Phone: 205-338-9997			U.S. EPA ID Number ALD983167891				
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
		No.	Type				
1.	NON DOT REGULATED POLYCHLORINATED BIPHENYLS	1	CM	3679	K		
2.							
3.							
4.							
14. Special Handling Instructions and Additional Information 1- PCB CONTAMINATED ELECTRICAL EQUIPMENT <50PPM PRF-1801018							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name William Suck		Signature <i>[Signature]</i>			Month 1	Day 21	Year 2021
16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name Nicholas With		Signature <i>[Signature]</i>			Month 1	Day 21	Year 2021
Transporter 2 Printed/Typed Name		Signature			Month	Day	Year
18. Discrepancy							
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection							
Manifest Reference Number:							
18b. Alternate Facility (or Generator)					U.S. EPA ID Number		
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator)						Month	Day
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1.	2.	3.	4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name		Signature			Month	Day	Year