



Florida Department of Environmental Protection  
Twin Towers Office Bldg. 2600 Blair Stone Road. Tallahassee, Florida 32399-

Division of Waste Management  
Bureau of Petroleum Storage Systems

Storage Tank Facility Annual Compliance Site Inspection Report

**Facility Information:**

Facility ID: 8518320 County: BREVARD Inspection Date: 05/06/2014  
 Facility Type: C -Fuel user/Non-retail  
 Facility Name: CEMEX - PALM BAY READY-MIX PLANT # Of Inspected ASTs: 1  
 3420 DIXIE HWY NE USTs: 0  
 PALM BAY, FL 32905 Mineral Acid Tanks: 0  
 Latitude: 28° 3' 16.5955"  
 Longitude: 80° 35' 32.3469"  
 LL Method: DPHO

**Inspection Result:**

Result : In Compliance  
 Description: Facility is In Compliance.

**Financial Responsibility**

Over Due

Financial Responsibility: SELF-INSURANCE - LETTER FROM CHIEF FINANCIAL OFFICER  
 Effective Date: 04/16/2010 Expiration Date: 04/15/2011

**Signatures:**

TKBVNR - BREVARD COUNTY NATURAL RESOURCES MGMT OFFICE

**Storage Tank Program Office**

(321) 633-2017

**Storage Tank Program Office Phone Number**

Thomas Stewart

**INSPECTOR NAME**

**INSPECTOR SIGNATURE**

Greg Davis

**REPRESENTATIVE NAME**

NO SIGNATURE

**REPRESENTATIVE SIGNATURE**

Facility ID: 8518320

Owners of UST facilities are reminded that the Federal Energy Policy Act of 2005 requires Operator Training at all facilities by August 8, 2012. For further information please visit:  
[http://www.dep.state.fl.us/waste/categories/tanks/pages/op\\_train.htm](http://www.dep.state.fl.us/waste/categories/tanks/pages/op_train.htm)

---

### System Tests

Type	Date Completed	Results	Reviewed	Next Due Date	Comment
------	----------------	---------	----------	---------------	---------

#### Completed Tests

Annual Operability Test	05/30/2007	Passed	05/30/2007	05/30/2008	
Annual Operability Test	09/01/2010	Passed	09/01/2010	09/01/2011	Krueger interstitial guage is functional.
Annual Operability Test	04/14/2009	Passed	04/16/2008	04/14/2008	
Annual Operability Test	03/25/2009	Passed	03/25/2009	03/25/2010	

#### Inspection Comments

05/06/2014

Double-walled steel over steel tank with kreuger gauges . Could not access facility. Blocked with concrete barriers and chain. However, the storage tank is obviously gone. On contacting Mr. Davis, I was informed that the storage tank was sold three months ago. I sent Mr. Davis a copy of the STRF with instructions. Because the system was installed with full secondary containment, had no piping in contact with the soil and has had no record of incident when in use, closure assessment is unnecessary. Current placard paid for. The property is no longer an active facility. A copy of this inspection report is being sent to Mr. Davis by e-mail.