

**FACILITY INFORMATION: Facility Name:** AMERICAN CEMENT WASTE TIRE FACILITY **On-site Inspection Start Date:** 09/10/2020 **On-site Inspection End Date:** 09/10/2020 WACS No.: 98523 Facility Street Address: 4750 EAST COUNTY ROAD 470 Sumterville City: **County Name:** SUMTER Zip: 33585

### **INSPECTION PARTICIPANTS:**

(Include ALL Landfill and Department Personnel with Corresponding Titles)Principal Inspector: Mary Powers, InspectorOther Participants: George Townsend, Environmental Manager;

### **INSPECTION TYPE:**

Routine Operation Inspection for WPF - Waste Tire Processing Facility

### ATTACHMENTS TO THE INSPECTION CHECKLIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

### Note: Checklist items with shaded boxes are for informational purposes only.

1.0 - SECTION 1.0 - FILE REVIEW 9.0 - SECTION 9.0 - WASTE TIRE FACILITIES Inspection Date: 09/10/2020

## 1.0 - SECTION 1.0 - FILE REVIEW

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

| ltem<br>No. | FILE REVIEW (Pre- or Post-Inspection, as appropriate.)   | Ok | Not<br>Ok | Unk | N/A |
|-------------|--|----|-----------|-----|-----|
| 1.1         | For landfills and C&D disposal facilities, does the facility have a current plan for the method and sequence of filling wastes? 62-701.500(2)(f) for landfills; 62-701.730(7)(a) for C&D debris sites  |    |           |     | 1   |
| 1.2         | For landfills, are the following records being reported to the Department?(Check any that are Not OK)<br>Waste reports (annually) 62-701.500(4)<br>Annual estimate of remaining life 62-701.500(13)(c)   |    |           |     | 1   |
| 1.3         | Is gas monitoring being performed as required by the permit? 62-701.500(9), 62-701.530(2)  |    |           |     | 1   |
| 1.4         | Are the results of the gas sampling reported to the Department quarterly? 62-701.530(2)(c)   |    |           |     | 1   |
| 1.5         | Is water quality sampling and testing performed according to standard procedures and at the required frequencies? 62-701.510(2) for landfills; 62-701.730(8) and 62-701.730(10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.  |    |           |     | 1   |
| 1.6         | Do the results of the water quality testing suggest there may be adverse impacts to water quality from the operation of the solid waste facility? 62-701.510(3) and (4); 62-701.730(4)(c) and (10) for C&D debris sites; 62-713.400(3) for stationary soil treatment facilities.   |    |           |     | 1   |
| 1.7         | For closed landfills and C&D disposal facilities with final elevations higher than 20 feet above grade, has a final survey report verifying the final elevations and contours of the facility been submitted to the Department? 62-701.600(6)(b), 62-701.730(9)(e)   |    |           |     | 1   |
| 1.8         | Is financial assurance adequate? 62-701.630 for landfills; 62-701.710(7)(a) and 62-<br>701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-<br>713.600(6)(a) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.<br>NOTE: The Solid Waste Financial Coordinator in Tallahassee can assist with this information. | 1  |           |     |     |
| 1.9         | Are cost estimates current and adjusted every year? 62-701.630(4) for landfills; 62-701.710(7)(a) and 62-701.710(1)(d)1. for waste processing facilities; 62-701.730(11)(a) for C&D debris facilities; 62-713.600(6)(b) and 62-713.600(6)(c) for stationary soil treatment facilities; 62-711.500(3) for waste tire facilities.  | 1  |           |     |     |
| 1.10        | For C&D debris disposal and disposal with recycling facilities, is an Annual Report submitted to the Department for the disposal operation by February 1st of each year? 62-701.730(12)  |    |           |     | 1   |
| 1.11        | For C&D recycling facilities with no disposal, is an Annual Report for the recycling facility submitted to the Department by February 1st of each year? 62-701.710(8)(b)   |    |           |     | 1   |
| 1.12        | For compost facilities, has the compost product been sampled and analyzed every 20,000 tons or every 3 months (whichever is sooner)? 62-709.530(1)   |    |           |     | 1   |
| 1.13        | For compost facilities, has the annual report been submitted by June 1st? 62-709.530(3)  |    |           |     | 1   |

Inspection Date: 09/10/2020

### 9.0 - SECTION 9.0 - WASTE TIRE FACILITIES

#### **Requirements:**

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

| Item<br>No. | SOLID WASTE PROHIBITIONS (unless "grandfathered" in, see 62-<br>701.300(18))   | Ok | Not<br>Ok | Unk | N/A |
|-------------|--|----|-----------|-----|-----|
| 9.1.1       | Unauthorized storage, processing, or disposal of solid waste except as authorized at a permitted solid waste management facility or other exempt facility? 62-701.300(1)(a)  | 1  |           |     |     |
| 9.1.2       | Unauthorized disposal or storage prohibited, except yard trash, within 500 feet of a potable water well? 62-701.300(2)(b)  | 1  |           |     |     |
| 9.2         | Unauthorized storage or disposal of yard trash prohibited within the minimum setbacks of (Check any that are Not OK) 62-701.300(12)<br>100 feet from potable water wells (except on-site)?<br>50 feet from water bodies?   | 1  |           |     |     |
| 9.3         | Unauthorized disposal or storage prohibited in any natural or artificial body of water including ground water and wetlands? (Does not apply to standing water after a storm event) 62-701.300(2)(d)  | 1  |           |     |     |
| 9.4         | Unauthorized disposal or storage prohibited, except yard trash, within 200 feet of any natural or artificial body of water, including wetlands without permanent leachate controls, except impoundments or conveyances which are part of an on-site, permitted stormwater management system or on-site water bodies with no off-site discharge? 62-701.300(2)(e) | 1  |           |     |     |
| 9.5         | Unauthorized open burning of solid waste prohibited except in accordance with Department requirements? 62-701.300(3)   | 1  |           |     |     |
| Item<br>No. | WASTE TIRE FACILITY - GENERAL REQUIREMENTS FOR<br>STORAGE  | Ok | Not<br>Ok | Unk | N/A |
| 9.6         | If the facility accepts tires from the public, is a sign posted at the facility entrance stating operating hours, cost of disposal and site rules? 62-711.540(1)(a)  |    |           |     | 1   |
| 9.7         | Are operations involving the use of open flames conducted no closer than 25 feet of a waste tire pile? 62-711.540(1)(b)  | 1  |           |     |     |
| 9.8         | If the facility accepts tires from the public, is an attendant always present on site when the site is open for business? 62-711.540(1)(c)   |    |           |     | 1   |
| 9.9         | Are fire protection services assured through notification to local fire protection authorities? 62-711.540(1)(d)   | 1  |           |     |     |
| 9.10        | Is an annual fire safety survey conducted? 62-711.540(1)(d)  | 1  |           |     |     |
| 9.11        | Is a copy of the annual fire safety report made part of the next quarterly report? 62-711.540(1)(d)  | 1  |           |     |     |
| 9.12        | Does the facility have an Emergency Preparedness Manual (EPM) on-site? 62-711.540(1)(e)  | 1  |           |     |     |
| 9.13        | Does the EPM contain the following information? (Check all that are Not OK) Contact names and numbers 62-711.540(1)(e)1 List of emergency response equipment and locations on-site 62-711.540(1)(e)2 Procedures to be followed in the event of a fire 62-711.540(1)(e)3  | ~  |           |     |     |
| 9.14        | Is the operator at the facility maintaining records of the quantity of waste tires received at the site, stored at the site, and shipped from the site? 62-711.540(1)(g) and 62-711.400(5)   | 1  |           |     |     |
| 9.15        | If the operator of the site is not the owner of the property, has written authorization been obtained from the property owner to operate the facility? 62-711.540(1)(h)  | 1  |           |     |     |
| 9.16        | Is adequate communications equipment available at the site? 62-711.540(1)(i)   | 1  |           |     |     |
| 9.17        | Is the owner or operator providing for control of mosquitoes and rodents so as to protect the public health and welfare? 62-711.540(1)(j)  | 1  |           |     |     |

# AMERICAN CEMENT WASTE TIRE FACILITY

Inspection Date: 09/10/2020

| Item No.    | WASTE TIRE FACILITY - STORAGE INDOORS   | Ok   | N<br>O | ot<br>k   | Unk | N/A |
|-------------|---|------|--------|-----------|-----|-----|
| 9.18        | Are waste tire piles more than 50 feet in width? 62-711.540(2)(a)   |      |        |           |     | 1   |
| 9.19        | Are waste tire piles along a wall more than 25 feet in width? 62-711.540(2)(a)  |      |        |           |     | 1   |
| 9.20        | Are widths of main aisles between piles less than 8 feet? 62-711.540(2)(b)  |      |        |           |     | 1   |
| 9.21        | Is there less than 3 feet of clearance between the top of storage to sprinkler detectors or roof structures? 62-711.540(2)(c)   |      |        |           |     | 1   |
| 9.22        | Is there less than 3 feet of clearance between waste tire piles and unit heaters, etc.? 62-711.540(2)(d)  |      |        |           |     | 1   |
| 9.23        | If waste tires are stored up to 15 feet high, do walls between adjacent warehouse areas and between manufacturing and warehouse areas have at least a four-hour fire rating? 62-711.540(2)(e)   |      |        |           |     | 1   |
| 9.24        | If waste tires are stored over 15 feet high, do walls between manufacturing and warehouse areas have a fire rating of not less than six hours and do steel columns have one-hour fireproofing? If the top of storage exceeds 20 feet in height, do columns and their connections with other structural members have two-hour fireproofing? 62-711.540(2)(f) |      |        |           |     | 1   |
| 9.25        | Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(2)(h)   |      |        |           |     | 1   |
| ltem<br>No. | WASTE TIRE FACILITY - STORAGE OUTDOORS  |      | Ok     | Not<br>Ok | Unk | N/A |
| 9.26        | Is the waste tire site operated within 200 feet from a body of water? 62-711.540(3)(a)  |      | 1      |           |     |     |
| 9.27        | Does the waste tire pile have a width less than 50 feet? 62-711.540(3)(b)   |      | 1      |           |     |     |
| 9.28        | Does the waste tire pile have an area less than 10,000 sq. ft? 62-711.540(3)(b)   |      | 1      |           |     | 1   |
| 9.29        | Does the waste tire pile have a height less than 15 feet? 62-711.540(3)(b)  |      | 1      |           |     | 1   |
| 9.30        | Is there a 50 feet wide fire lane around the perimeter of the waste tire pile? 62-711.540(3)  | )(c) | 1      |           |     | 1   |
| 9.31        | Is there unobstructed access to the fire lane? 62-711.540(3)(c)   |      | 1      |           |     | 1   |
| 9.32        | Is the access controlled through the use of doors, fences, gates, natural barriers or other means? 62-711.540(3)(d)   |      | 1      |           |     |     |
| 9.33        | Is the site kept free of grass, underbrush, and other potentially flammable vegetation? 62 711.540(3)(f)  | -    | 1      |           |     |     |
| 9.34        | Is the site bermed or given other adequate protection to prevent liquid runoff from enterin water bodies? 62-711.540(3)(e)  | g    | 1      |           |     |     |
| 9.35        | Are residuals contained on-site and disposed of in a permitted solid waste management facility or properly recycled? 62-711.540(5)  |      | 1      |           |     |     |
| 9.36        | Does the waste tire site qualify for the exceptions to the technical and operational standa as allowed by rule? 62-711.540(6)   | rds  | 1      |           |     |     |
| ltem<br>No. | WASTE TIRE FACILITY - COLLECTION CENTER   |      | Ok     | Not<br>Ok | Unk | N/A |
| 9.37        | Are no more than 1,500 tires at the collection center at any one time? 62-711.550(1)(a)   |      |        |           |     | 1   |
| 9.38        | Are all waste tires, which are not used tires, removed from site yearly for recycling, processing, or disposal? 62-711.550(1)(b)  |      |        |           |     | 1   |

# AMERICAN CEMENT WASTE TIRE FACILITY

### COMMENTS:

#### Permit 0297136-003-WT issued 2/6/19 and expires 4/7/24

The American Cement Plant produces Portland cement using a dry process kiln with a preheater and calciner. The cement kiln is authorized to burn tires and tire-derived fuel as a supplemental fuel. Presorted tires are delivered to the facility from a single contractor in container trailers. Tires are not cut or shredded onsite. The organic components of the tires are combusted in the high-temperature kiln, providing heat value (Btu's) to the process. The inorganic components are incorporated into the kiln production (cement clinker). The anticipated planned daily throughput is 60 tons per day and the planned annual throughput is 21,900 tons per year.

The facility shall not exceed 80.4 of whole waste tires stored at one time. They keep an electronic tracking system of how many tires are received and burned to ensure compliance with this limit. The quantity of tires reported on site as of the 2019 4th quarter report was 23.38 tons, with 1.38 tons being consumed from the tires already present on site (no waste tires were accepted to the facility during this quarter). The facility most recently accepted tires in the 2nd quarter of 2019. Submitted reports for the 1st and 2nd quarter of 2020 show no processing or accepting of waste tires subsequent to the 4th quarter of 2019. A facility representative stated that less tires are being processed due to the exploration of an alternate fuel source.

During the inspection, waste tires were stored inside of three trailers. No tires were stored on the tire handling conveyor system at the time of inspection. Each trailer holds approximately 13 tons of tires. Tires were not being processed at the time of inspection.

Please ensure that a copy of the fire-safety survey is made part of the next quarterly report. Also ensure that the emergency preparedness manual is on-site and accessible to all employees.

## **ATTACHMENTS:**

Trailer 1



Trailer 3



Trailer 2



Empty waste tire conveyor belt



# AMERICAN CEMENT WASTE TIRE FACILITY

Inspection Date: 09/10/2020

Inspection Date: 09/10/2020

## Signed:

| Mary Powers                   | Inspector                 |                    |
|-------------------------------|---------------------------|--------------------|
| PRINCIPAL INSPECTOR NAME      | PRINCIPAL INSPECTOR TITLE |                    |
| PRINCIPAL INSPECTOR SIGNATURE | FDEP<br>ORGANIZATION      | 09/17/2020<br>DATE |
| George Townsend               | Environmental Manager     |                    |
| REPRESENTATIVE NAME           | REPRESENTATIVE TITLE      |                    |
| NO SIGNATURE REQUIRED         | Suwannee American Cement  |                    |
| REPRESENTATIVE SIGNATURE      | ORGANIZATION              |                    |

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.

#### **Report Approvers:**

Approver: David Smicherko

Inspection Approval Date: 09/28/2020