



File Checklist for Water Supply Restoration Replacement Actions

2/1/2011

Site Code

250031401

Site Information

Physical Location of Well

4435 BEECHWOOD DRIVE
BOWLING GREEN

Resident Information

ALBRITTON, LEEZA
4435 BEECHWOOD DRIVE
BOWLING GREEN 33834

1. Date - Notification letter sent to owner	5/14/2009
2. Date - Signed form received from owner	12/27/2010
3. Date - Remedial action initiated	1/12/2011
4. Date - Payment processed for remedial action	1/20/2011
5. Date - Remedial action entered into database	1/20/2011
6. Restoration/Replacement Action Recommended	1
7. Type of remedial action performed	FI
8. Cost incurred on remedial action	741.6
9. Funding source	NIT

Sample Results -- Contaminants above MCL or HAL(Highest Value Detected)
All results are reported in parts per billion; except Nitrate, Total Nitrate + Nitrate reported in parts per million

NITRATE (TOTAL AS N)	12
----------------------	----

Comments: NITRATE=12; RO INSTALL

RO FI 1/20/11

HWY 17 SOUTH TO HWY 2; RIGHT TO HWY 663; LEFT TO BEECHWOOD DRIVE; RIGHT TO #4435.

There are no water lines or the cost of the connection is more than ten year present worth cost of the filter.