

Smith, George

From: Hsu, Benjamin
Sent: Tuesday, July 24, 2018 9:47 AM
To: SWD_Waste
Subject: FW: Follow-Up Items --- FDEP Inspection 5/4/2018 (Pasco Resource Recovery)
Attachments: 45799_201710_conf_SWfdd.txt; 45799_201710_conf_SWldd.txt; 45799_201710_conf_SWldd_ErrorLog.txt; 45799_201711_conf_swgwmr.pdf

From: Hsu, Benjamin
Sent: Tuesday, July 24, 2018 9:45 AM
To: ADaPT EDD
Cc: Tafuni, Steven ; Madden, Melissa
Subject: FW: Follow-Up Items --- FDEP Inspection 5/4/2018 (Pasco Resource Recovery)

Hello ADaPT,

These are EDD files for a resampling event for a single parameter: nitrate/nitrite

Thanks,

Benjamin Hsu
Engineering Specialist 1 - Air / Solid Waste Compliance Assurance Program
Florida Department of Environmental Protection - Southwest District
13051 North Telecom Parkway, Suite 101, Temple Terrace, FL 33637-0926
benjamin.hsu@floridadep.gov
Office: 813-470-5720
Fax: 813-470-5995

From: Candia Mulhern [<mailto:cmulhern@pascocountyfl.net>]
Sent: Monday, July 23, 2018 3:26 PM
To: Hsu, Benjamin <Benjamin.Hsu@dep.state.fl.us>
Subject: RE: Follow-Up Items --- FDEP Inspection 5/4/2018 (Pasco Resource Recovery)

Hi Benjamin:

Attached is the nitrate confirmation reports as requested below. The well was resampled for nitrate in November of 2017.

I am sorry for the delay in submitting this report.



Candia E. Mulhern
Laboratory Manager
Utilities Environmental Lab
Pasco County
P 727-847-8902
F 727-847-8112
8864 Government Dr.
New Port Richey, FL 34654
cmulhern@pascocountyfl.net

“Serving our community to create a better future.”

From: Justin G. Roessler
Sent: Friday, May 18, 2018 2:19 PM
To: Candia Mulhern; John Power
Subject: FW: Follow-Up Items --- FDEP Inspection 5/4/2018 (Pasco Resource Recovery)

Hi Candia,

Please see below. Let us know when the next sampling date is so we can provide a response.

Thank you,
Justin Roessler

From: Hsu, Benjamin [<mailto:Benjamin.Hsu@dep.state.fl.us>]
Sent: Friday, May 18, 2018 2:05 PM
To: John Power; Justin G. Roessler; Michael A. Frestick
Cc: Madden, Melissa
Subject: RE: Follow-Up Items --- FDEP Inspection 5/4/2018 (Pasco Resource Recovery)

In addition, please provide these by end-of-day Wednesday, 5/23/2018, as we have an internal deadline of 3 weeks from the date of inspection (which equates to Friday, 5/25/2018) to complete our inspection reports. Thank you.

Benjamin Hsu
Engineering Specialist 1 - Air / Solid Waste Compliance Assurance Program
Florida Department of Environmental Protection - Southwest District
13051 North Telecom Parkway, Suite 101, Temple Terrace, FL 33637-0926
benjamin.hsu@floridadep.gov
Office: 813-470-5720
Fax: 813-470-5995

From: Hsu, Benjamin
Sent: Friday, May 18, 2018 1:10 PM
To: jpower@pascocountyfl.net; jroessler@pascocountyfl.net; mfrestick@pascocountyfl.net
Cc: Madden, Melissa <Melissa.Madden@dep.state.fl.us>
Subject: Follow-Up Items --- FDEP Inspection 5/4/2018 (Pasco Resource Recovery)

Hello John Power & Friends,

Thank you for the facility tour two weeks ago (Friday, 5/4/2018).

I have in my notes some items to follow-up on post-inspection

Please see below.

Thanks and I hope you have a good weekend.

Photos Requested


1. Photo of repaired cover on well 2MW-24D (inspection photo attached).
2. Photo of Class III cells 1 + 2 waste pushed back to within the edge of liner / off the concrete (inspection photo attached).
3. Photo of more cover added to cell SW-2 to cover exposed waste (inspection photo attached).

Documents Requested

4. Copy of the analytical performed on the bottom ash and fly ash mixture. These were stated to be held by Jamie Rocco.

Questions


5. What is the schedule for reseeding uncovered areas due to hog damage?
6. During the Covanta WTE portion of the inspection, we noted a leachate sump next to the grizzly area where the sump pump's control switch was set to "Off" (other options were "On" and "Auto"). Bruce Hartimer and Barry Wright were with us for this portion; their thought was that the switch did not actually control anything and that the pump was automatic, but that they would look into it. What was the finding from this? Does the pump work and why was it set to "Off"?
7. Groundwater sampling performed on 2MW-25D on 10/30/2017 indicated a large spike in Nitrate/Nitrite. We inquired on this during the post-inspection meeting in your office and you had indicated that the well could be resampled. Is this plan to resample still expected?



Comments/Other

8. An electronic copy of a new dead animal burial guidance is attached. This guidance is in response to cases in the state of animal secondary poisoning from consuming euthanized animals. The guidance encourages deeper burial of euthanized animals, and we (inspectors) are to distribute it to the Class I landfills. Thanks.

Benjamin Hsu
Engineering Specialist 1 - Air / Solid Waste Compliance Assurance Program
Florida Department of Environmental Protection - Southwest District
13051 North Telecom Parkway, Suite 101, Temple Terrace, FL 33637-0926
benjamin.hsu@floridadep.gov
Office: 813-470-5720
Fax: 813-470-5995



"Bringing Opportunities Home"

The information transmitted, including attachments, is intended only for the person(s) or entity to which it is addressed and may contain material that is confidential, privileged and/or exempt from disclosure under applicable law. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon this information by persons or entities other than the intended recipient is prohibited. If you received this in error, please contact the sender and destroy any copies of this information. Under Florida law, email addresses are public records. If you do not want your email address released in response to a public-records request, do not send electronic mail to this entity. Instead, contact this office by phone or in writing.

CUSA18A7