

### Florida Department of Environmental Protection

Bob Martinez Center 2600 Blair Stone Road Tallahassee, Florida 32399-2400 Rick Scott Governor

Carlos Lopez-Cantera Lt. Governor

Jonathan P. Steverson Secretary

07/01/2016 Kurt Fogleman, Environmental Health & Safety Manager Perma-Fix Of Florida Inc 1940 NW 67th Pl Gainesville, FL 32653-1649

The Florida Department of Environmental Protection has reviewed your form 8700-12FL notification for a new hazardous waste DEP/EPA Identification Number or status/information change. Based on the information received you must use the following identification number for all manifests or reports for Perma-Fix Of Florida Inc located at 1940 NW 67th PI, Gainesville, FL 32653-1649

#### FLD980711071

Your facility notified FDEP requesting the following hazardous waste status/activities which do not require a separate submission: Large Quantity Generator; Universal Waste Batteries, Universal Waste Lamps, Universal Waste Devices, Universal Pharmaceuticals, LQH Pharmaceuticals, LQH Acute Pharmaceuticals, HW Burner/Blender; Used Oil on-Spec Marketer; United States Importer of Hazardous Waste; Mixed Waste (hazardous and radioactive) Generator; Receives Hazardous Waste from Off-Site.

Your facility is currently registered for the following activities: UW Lamp Transporter, UW Device Transporter, UW Lamp Transfer Facility, UW Device Transfer Facility, UW Lamp SQH, UW Device SQH (reg exp on 03/01/2017); HW Transporter (reg exp on 06/30/2017); Used Oil Transporter, Used Oil Transfer Facility, Used Oil Filter Transporter, Used Oil Filter Transfer Facility (reg exp on 06/30/2017).

Your facility is currently permitted/active as: Operating Commercial TSD (exp on 05/27/2020).

If you have pending program registrations/certifications or permits, these will be mailed separately. You are required to notify us on form 8700-12FL if there is any change in your operations which would affect your status, activity or contact information. The form is found here:

 $\underline{\underline{\text{http://www.dep.state.fl.us/waste/categories/hwRegulation/pages/NotificationRegulatedWaste.htm.}}$ 

To review the details of your status, visit:

https://fideploc.dep.state.fl.us/www\_RCRA/Reports/handler\_results.asp?epaid=FLD980711071. For further assistance, please contact me at (850) 245-8749 or email at <a href="mailto:Glen.Perrigan@dep.state.fl.us">Glen.Perrigan@dep.state.fl.us</a>. Sincerely,

Glen Perrigan Environmental Manager Hazardous Waste Regulation Section

ME ID: 50775, Email Address: kfogleman@perma-fix.com



# 8700-12FL - FLORIDA NOTIFICATION OF REGULATED WASTE ACTIVITY

DEP Waste Management Division-HWRS, MS4560 2600 Blair Stone Rd. Tallahassee, FL 32399-2400 (850) 245-8760 Date Received
(for FDER Official, Use Only)

APR 01 2016

DOMESTING COMPLIANCE

EPA ID FLD980	711071							- SISTA	NCE PROGRESS
1. Reason for Submittal	<ul> <li>□ To provide initial notification (to obtain an EPA ID Number for hazardous waste, universal waste, or used oil activities).</li> <li>☑ To provide subsequent notification ☑ As a component of the Hazardous Waste Report.</li> <li>□ Is this the final notification (see instructions) for the facility?</li> </ul>								
	FL Registration(s	UW Mercury (page 3)	у 🔀 н	IW Trai	nsporter (	(page 4)	<b>⋈</b> Us	ed Oil (pag	e 4)
2. Facility or Business Name		OF FLORIDA, INC.							
3. Facility Operator (List additional Operators in the		OF FLORIDA, INC.					ew Oper		01/01/1994 mm dd yy
comments section).	1940 N.W.	67TH PLACE				7: 0.1			52)395-1353
	City or Town: GA	INESVIL		Stat	e: FL	Zip Code 32653		Country US	(if not USA):
	Operator Type:	Private Federal	Municipal	Stat	e 🔲 C	County [	Other		
4. Facility Physical	Physical Street A	Address: 1940 N.W.	67TH PLA	CE					
Location Information (No P.O. Boxes)	City or Town: C	GAINESVILLE			St	ate: FL	Zip C	Code: 326	53-
	County: ALACI	AUH		Count	ry (if no	t USA):			
5. Facility North American Industry Classification System (NAICS)		<b>A.</b> 562211	(required	d)		В.			
	5 digits)	C.	. <del></del>			D.			
6. Facility or Business Mailing	Street or P.O. Bo	x: 1940 N.W. 67TH	PLACE						
Address	City or Town: G	AINESVILLE	State: FL	Zip	Code: 3	32653-			
7.Facility or Business RCRA	First Name: KUR	T 395-1356	Last Nam	e:FOG	LEMAN	<i>o</i> 1	itle:		
Contact Person	Phone Number:	(352)313 39.Ext	tension: 13	<del>56</del>	Emai	l: KFOGLEN	MAN@PE	RMA-FIX.0	СОМ
!		x: 1940 N.W. 67TH	PLACE						
	City or Town: GAINES	/ILLE	State: FL	Zip	Code: 32653-	-	Country	(if not US	SA):
8. Real Property (Land) Owner of the Facility's	Name of Owner: PERMA-F	FIX OF FLORIDA, INC	С.				ecame w Own	Owner : er	01/01/1994 mm dd yy
Physical Location	Street or P.O. Bo 1940 N	x: .W. 67TH PLACE					Pho	one Numb	oer: (352)373-6066
(List additional real property owners	City or Town: GAINESV	IL	State: FL	1 -	Code: 53 -		Cour	itry (if not	USA):
in the comments section).	Owner Type: X	Private Federal Muni	cipal St	ate 🔲	County [	Other	-		

						EP	A ID No.	FLD9807	11071	
9. RCRA Haza	rdous Wa	ste Activ	ities at this Fa	cility <del>(</del> Mark	'X' in all tha	t apply):				
General greater hazardo of acute b. Small General 100kg/n lbs.) of (2.2 lbs) c. Cond General (220 lbs) (2.2 lbs) In addition, d. Sho e. Epis X f. Unit X g. Mix	(Do no noose only test in any coper month ous waste; coper hazardous all Quantity test in any como but less non-acute between a como but less of littionally Estes in any coper model.) or less of indicate cort-Term Gesodic: Not noted States In the States In the Codes for I. List them	ot include U one of the Generator ( alendar mo (kg/mo) (2 or Greater t s waste Generator ( alendar mo than 1,000 hazardous acute hazar xempt SQC alendar mo cute hazar cute hazar other gen enerator (or more than of hazardous federally in the ore	Iniversal Waste or following three (LQG): Onth 1,000 kilogri, 200 lbs.) of non han 1 kg (2.2 lbs) (SQG): Onth greater than 0 kg/mo (>220 to waste and/or 1 k rdous waste G (CESQG): Onth 100 kg/mo or dous waste and/or rdous waste elerator activitiene-time, not on-gone-time per yea Hazardous Waste and radioactive)  Regulated Hader they are professional residuations.	e categories.  rams or nacute s)  0 <2,200 g  or less or 1 kg  es that app going) r:SQG_L  te  Generator  azardous W esented in th	(2)    X	may be required a. Operating Cor b. Operating Nor c. Non-operating Permit or Con Recycler of Haz ecify: Common remit is required a. Small b. Smelti Person Autho not Waste gener gement activity Capplication for su eccived from FD Receives Haz Undergroun waste codes of t (e.g., DOO1, D	r, or Disposei Note: A haza I for this activ mercial TSD n-commercial T g: Postclosure of sent Order (HS zardous Wast ercial; No I for storage p r and/or Indu Quantity On-g ing, Melting, a rized to Man ated at other ONLY if you a nch authorizat EP. azardous Wast he Federal h OOO3, FOO7	r of Hazardous rdous waste per ity  SD r Corrective Action WA, etc.) te (at your facility n-Commercial. rior to recycling astrial Furnace is the Burner Exertand Refining Furnace and Refining Furnace facilities - Control  Ste from Off-Si Control  azardous waster, U112).	Waste rmit  on  lity)  g.  mption  irnace Exercises this a copy of norization  te	
D001	D002	porters iis	D003	DO O		Use an addition	D00	•	D007	
D008	D009		D010	DO	 L1	D012	D01	3	D014	
D015	D016		D017	DO	L8	D019	D02	0	D021	-
11. Other St	atus Chan	ges (Mark	'X' in the appr	opriate boxes	s): D022	D023	D024 D	025 D026	D027	D028
☐ 1. Bus <b>B. Facility Cl</b> ☐ 1. Clos if ☐ 2. Out c	iness no lor losed ed at this lo you will be	nger genera ocation and e handling - Business	ste at this facilitates, transports, to moved or moving regulated wastes closed on/	treats, stores,  ng to another there.	- submit a new	nazardous waste.  8700-12FL for t  (Date).  Petition for Ban				
G F W	D.CD. 4	First Nan	ne:		Last Name:			Title:		
Same as Facility Contact on page 1						1				
		Phone N	ımber:		Extension:	E-Mail:				
		Street or	P.O. Box:			•				
		City or T	own:			State:(Countr	y):	Zip Code:		

	EPA ID N	<b>o.</b> FLD980711071			
12 Universa	al Waste (UW) Activities ( Mark 'X' in all that apply) ("accumulated" mea	ns at any one time):			
A. Federal Notification	Federally Defined Large Quantity Handler (LQH) = Generate/Accumulate: 5 of any combination of UW accumulated (at any one time)	7,000 kg (11,000 lb) or more			
	Accumulates:  Accumulates:  a. UW Batteries  b. Pesticides  c. Pharmaceutica  d. Mercury Containing Devices	ls			
	d. Mercury Containing Devices	ng Lamps			
	Destination Facility for UW  Note: For this activity, a facility must treat, di  A permit is required for storage pr				
B. Florida Ur	niversal Pharmaceutical Waste (UPW): one-time registration				
X Ph	Pharmaceuticals Acute LQH = more than 1 kg (2.2 lb) of acutely hazardous ("P-listed") pharmaceutical waste (UPW) accumulated  Reverse Distributor of Universal Pharmaceutical Waste (UPW) (must be registered with the Florida Department of Health [DOH])				
C. Florida A	nnual Mercury Handler Registration:				
Devices operat [Chapter 62-73' Mercury-Contai If you only	For-hire transporters, transfer facilities, handlers, reclamation and recovery facilities of Mercury-Containing Lamps and  Devices operating in the State of Florida are required to register annually with the Department using this section of the form  [Chapter 62-737, F.A.C.]. A one-time fee of \$1,000 is required for first time registration as a Large Quantity for-hire Handler of  Mercury-Containing Lamps and Devices as detailed in 62-737.400(3)(a)3. (please contact FDEP first).  If you only generate lamps and/or devices or manage pharmaceuticals, do not register or complete the information below.				
	s being submitted as a Florida Registration of Universal Waste Transporter/Handle me registering Renewal One-time \$1,000 fee for Mercury for-hire first time				
For-hire To Mercury	ransporter of Universal Waste Mercury-Containing Lamps or Devices ransfer Facility of Universal Waste Mercury-Containing Lamps or Devices -Containing Devices (thermostats, etc) SQH = less than 100 kg accumulated by for-hire less than 2,000 kg (8,000 lamps) accumulated by for-hire har				
	ry-containing devices $LQH = 100 \text{ kg}$ (220 lb) or more accumulated by for-hire handler ary-containing lamps $LQH = 2,000 \text{ kg}$ (4400 lbs/8,000 lamps) or more accumulated by for-hire handler	Annual Registration + one- time \$1,000 fee+ More Requirements (contact FDEP)			
	covery and/or Reclamation Facility (A hazardous waste permit is required for this activity) time registering Renewal	Annual Registration Required			
Briefly Describe ye	our Universal Waste Activities: We use D	Orum Top Bulb Crusher(s).			
	te Regulated Waste Activities: Petroleum Contact Water (PCW) Recover	· — •			
Note: A wat	ter facility permit may be required for this activity. An annual report is required for a recovery facility pursual	nt to Rule [62-740.300(5)]			

	<b>EPA ID No.</b> FLD980711071
14. HW Transporter Activities: (Mark 'X' and complete all	that apply if you need to register your HW Transporter activities)
renew their registration. Evidence of casualty/liability insurance. Transfer facilities must submit several additional documents as of	e in the State of Florida are required to register and annually ce pursuant to 62-730.170(2)(a) is required in addition to this registration. detailed on page 5 the first time they register and when the information begin operations after receiving approval from the Department.  ithin the boundaries of their facility should not register.
A. HW Transporter Registration Information (must be a sequence of the control of	st be completed annually and when this information changes) s waste.
☐ Initial Registration	☐ Notification of changes ☐ Cancel Registration
1. For own waste only 2. For Commerce	cial Purposes 3. Both Commercial and Own Waste
4. Transportation Mode: Air; Rail; X Highway;	] Water; ☐ Other - specify
B. HW Transfer Facility Registration Information (	must be completed annually and when this information changes)
☐ This facility is a Hazardous Waste Transfer Facility: (at	this location) Storage Volume
This form is:	enewal Notification of changes Cancel Registration
Note: Hazardous Waste transfer facilities must comply with the re	equirements of Rule 62-730.171, FAC, and Rule 62-730.182, FAC.
The Transfer Facility records required under the provision our mailing (business) address	ns of Rule 62-730.171(6), F.A.C., are kept at (check one):  The site (facility) address
Please enter the EPA ID Number of the HW Transporter who carr	ries the insurance for this Transfer Facility:
Please see the top of page 5 for additional items that must be Transfer Facilities [Rule 62-730.171(3), Florida Adm	e submitted in addition to the above registration for Hazardous Waste ninistrative Code (F.A.C.)]:
15. Used Oil and Oil Filter Activities: (Mark 'X' and o	complete all that apply if you need to register your used oil activities)
Transporters (exemptions in 40 CFR 279.40(a)(1-4), transfer facilit	
This form is:   ☐ Initial Registration  ☐ Renew	wal Notification of changes Cancel Registration
If applicable, a check or money order, in the amount of \$10	00, payable to Florida Department of Environmental Protection is enclosed.
<ul> <li>(1) Used Oil Transporter - Mark activities (occurring in Florida)</li></ul>	(6) Used Oil Filter Management (must annually register)  X a. Transporter  X b. Transfer Facility  C. Processor  d. End User
(3) Used Oil Processor (A permit is required)	(7) The Transfer Facility records required as decided as
(4) Off-Specification Used Oil Burner	(7) The Transfer Facility records required under the provisions of Rule 62-710.510, F.A.C., are kept at (check one):
(5) Used Oil Fuel Marketer	Our mailing (business) address  The site (facility) address
Please see the top of page 5 for additional items that must be exempt Used Oil Transporters.	e submitted in addition to the above registration and fees required for

Signature of owner, operator, or an

**Print Name and Title** 

Date Signed



## Hazardous Waste Generation, Treatment, and Shipping Summary Report

03/31/2016

Biennnial Hazardous Waste Report electronic data submission summary.

### PERMA-FIX OF FLORIDA, INC.

N.W. 67TH PLACE

GAINESVILLE, FL 32653

**NAICS** 562211

Hazardous Waste Treatment and Disposal

Waste Generation and Management Information Generated, Treatment	ated, Shipped Tons
FLD980711071	<del></del>
GM Page: 00001 IGNITABLE CHLORINATED/NON-CHLORINATED SOLVENT FROM TSD BULKING OPERATION ON W204 Concentrated halogenated/ non-halogenated solvent mixture G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D001 F003 F005 D022 D007 D008	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	253.38 Tons
GM Page: 00002  IGNITABLE SOLVENTS WITH CHLOROSILANES IN SOLUTION FROM TSD OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002 D003	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	10.18 Tons
MAGNESIUM PERCHLORATE LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site  D001	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.00 Tons
W001 Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	7.12 Tons
GM Page: 00005 IGNITABLE ISOCYANATES, RESINS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D003 D039 D007 D011 D035	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	8.23 Tons

Waste Generation and Management Information Generated, Treate	ed, Shipped Tons
GM Page: 00006  IGNITABLE ISOCYANATES, RESINS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D003 D035	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.07 Tons
GM Page: 00007 IGNITABLE ISOCYANATES, RESINS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D035	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	1.08 Tons
GM Page: 00008 IGNITABLE ISOCYANATES, RESINS LAB PACK FROM TSD OPERATION W001 Lab packs with no acute hazardous waste (from any source) G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D001 D003 U223	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.12 Tons
GM Page: 00009 IGNITABLE ISOCYANATES, RESINS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D035 D039	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.77 Tons
GM Page: 00010 IGNITABLE ISOCYANATES, RESINS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D003	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	1.65 Tons
GM Page: 00011  W001 Lab packs with no acute hazardous waste (from any source)  G61  D003  AIR BAG INFLATORS LAB PACK FROM TSD OPERATION  Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.10 Tons
GM Page: 00012  ELEMENTAL METALS LITHIUM, SODIUM, POTASSIUM UNDER OIL LAB PACK FROM TS  D OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D003 D001	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.03 Tons

Waste Generation and Management Information Generated, Treate	d, Shipped Tons
IGNITABLE ALKYLAMINES LAB PACK FROM TSD OPERATIONS  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	<b>7.97</b> Tons
W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.13 Tons
M Page: 00015  W004 Lab packs containing acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 P022	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.00 Tons
M Page: 00016 W204 Concentrated halogenated/ non-halogenated solvent mixture G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D001 F001 F004 F003 F005 U122 D004 D005 D006 D007 D008 D009 D010 D01 D019 D021 D022 D028 D029 D035 D039 D040 D043 F002 U051	<b>0.00 Tons</b> 1 D018
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	78.30 Tons
IGNITABLE PESTICIDES HERBICIDES IN SOLUTION FROM TSD BULKING OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D012 D014 D016 D004 D013 D015 D019 D020	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	18.78 <sup>Tons</sup>
M Page: 00018  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D012 D014 D016 D004 D013 D015 D019 D020	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	9.96 Tons
M Page: 00019 ACUTE TOXIC SODIUM CYANIDE LAB PACK FROM TSD OPERATION Lab packs containing acute hazardous waste (from any source) Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Tons
D003 P106	

Waste Generation and Management Information Generation	ated, Treated, Shipped Tons
GM Page: 00020 ACUTE TOXIC POTASSIUM CYANIDE LAB PACK FROM TSD OPERATION Lab packs containing acute hazardous waste (from any source) Hazardous waste received from off-site for storage/bulking and transfer off-site	<b>0.00 Ton</b>
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>0.06</b> Tons
W004 Lab packs containing acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	<b>0.00 Ton</b> s
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>0.01</b> Tons
GM Page: 00022 IGNITABLE ACETIC, GC VIALS CONTAINING SOLVENTS FROM TSD BULKING O  ION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 F003 D002 F002 F005	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>1.05</b> Tons
GM Page: 00023  W004 Lab packs containing acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	<b>0.00 Tons</b>
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>0.01</b> Tons
GM Page: 00024 IGNITABLE RAGS, WIPES CONTAING ACETONE, LEAD FROM TSD BULKING OP  N  W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>0.29</b> Tons
GM Page: 00025  W004 Lab packs containing acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site	<b>0.00</b> Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>0.00</b> Tons
GM Page: 00026 CAUSTIC SOLUTION WITH SODIUM HYDROSULFIDE FROM TSD OPERATION W110 Caustic aqueous waste without cyanides( Ph >12.5) Hazardous waste received from off-site for storage/bulking and transfer off-site	<b>0.00 Tons</b>
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as	a <b>0.07</b> Tons

G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D003  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 0.02 To GM Page: 00028 INORGANIC ACIDS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source) 0.00 To G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 1.67 To GM Page: 00029 INORGANIC ACIDS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source) 0.00 To G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002 U134  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 1.25 Tor GM Page: 00030 CAUSTIC INORGANIC LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source) 0.00 To G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 3.50 Tor GM Page: 00031 CAUSTIC ORGANIC SOLUTION FROM TSD OPERATION  W110 Caustic aqueous waste waste without cyanides (Ph >12.5) C61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002 F002 F003  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 0.25 Tor GM Page: 00032 IGNITABLE TOXIC PESTICIDES, HERBICIDES SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture 0.00 Tc G61 Hazardous waste received from off-site for storage/bulking and transfer off-site O01 D012 D014 D016  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 0.09 Tor G6M Page: 00033 IGNITABLE TOXIC PESTICIDES, HERBICIDES SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture 0.00 Tc G61 Hazardous waste received from off-site for storage/bulking and t	Waste G	eneration and Manager	nent Information	Generated, Treated	, Shipped Tons
MORGANIC ACIDS LAB PACK FROM TSD OPERATION   Lab packs with no acute hazardous waste (from any source)   0.00 To G61   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste without cyanides (Ph >12.5)   0.00 To G81   Hazardous waste without cyanides (Ph >12.5)   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To G81   Hazardous waste received from off-site for storage/bulking	W002 G61	Contaminated debris: paper	, clothing, rags, wood, empty fiber or pla		0.00 Ton
W001   Lab packs with no acute hazardous waste (from any source)   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste received from off-site for storage/bulking and transfer off-site   0.00 To Get   Hazardous waste without cyanides   Ph > 12.5	Shipped to: C	<b>HD980613541</b> H040 In	cineration - thermal destruction other tha	an use as a	0.02 Tons
INDRGANIC ACIDS LAB PACK FROM TSD OPERATION   Description   Lab packs with no acute hazardous waste (from any source)   Description   Descri	W001 G61	Lab packs with no acute haz	ardous waste (from any source)	sfer off-site	0.00 Ton
W001   Lab packs with no acute hazardous waste (from any source)   Q.00 To G61   Hazardous waste received from off-site for storage/bulking and transfer off-site	Shipped to: C	HD980613541 H040 In	cineration - thermal destruction other tha	an use as a	1.67 Tons
GM Page: 00030  W001 Lab packs with no acute hazardous waste (from any source) G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 3.50 Tor GM Page: 00031 CAUSTIC ORGANIC SOLUTION FROM TSD OPERATION W110 Caustic aqueous waste without cyanides( Ph >12.5) G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002 F002 F003  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 0.25 Tor GM Page: 00032 IGNITABLE TOXIC PESTICIDES, HERBICIDES SOLUTION FROM TSD BULKING OPERA TION W204 Concentrated halogenated/ non-halogenated solvent mixture G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D001 D012 D014 D016  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 0.09 Tor GM Page: 00033 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION W204 Concentrated halogenated/ non-halogenated solvent mixture G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002 D001 F002 F003 F005 D021  O.00 Tc	W001 G61	Lab packs with no acute haz Hazardous waste received fo	ardous waste (from any source)	sfer off-site	0.00 Tons
W001   Cab packs with no acute hazardous waste (from any source)   G61   Hazardous waste received from off-site for storage/bulking and transfer off-site	Shipped to: 0	HD980613541 H040 In	cineration - thermal destruction other tha	an use as a	1.25 Tons
CAUSTIC ORGANIC SOLUTION FROM TSD OPERATION  Caustic aqueous waste without cyanides (Ph > 12.5)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 F002 F003  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a  GM Page: 00032 IGNITABLE TOXIC PESTICIDES, HERBICIDES SOLUTION FROM TSD BULKING OPERA  TION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D012 D014 D016  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a  0.09 Torage: 00033 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 D021	W001 G61	Lab packs with no acute haz	ardous waste (from any source)	sfer off-site	0.00 Tons
W110 Caustic aqueous waste without cyanides (Ph >12.5)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 F002 F003  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a  O.25 Tor  GM Page: 00032 IGNITABLE TOXIC PESTICIDES, HERBICIDES SOLUTION FROM TSD BULKING OPERA  TION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D012 D014 D016  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a  O.09 Tor  GM Page: 00033 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 D021	Shipped to: O	HD980613541 H040 Inc	cineration - thermal destruction other tha	an use as a	3.50 Tons
GM Page: 00032  IGNITABLE TOXIC PESTICIDES, HERBICIDES SOLUTION FROM TSD BULKING OPERA  TION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D012 D014 D016  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a  GM Page: 00033 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 D021	W110 G61	Caustic aqueous waste with Hazardous waste received for	out cyanides( Ph >12.5)	sfer off-site	0.00 Tons
TION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D012 D014 D016  Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 0.09 Tor  GM Page: 00033 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture 0.00 Tc  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 D021	Shipped to: O	HD980613541 H040 In	cineration - thermal destruction other tha	an use as a	0.25 Tons
GM Page: 00033 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 D021	W204 G61	TION  Concentrated halogenated/ i  Hazardous waste received fi	non-halogenated solvent mixture		0.00 Tons
W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 D021	Shipped to: C	HD980613541 H040 In	cineration - thermal destruction other tha	an use as a	0.09 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a 20.49 Tor	W204 G61	Concentrated halogenated/ Hazardous waste received for	non-halogenated solvent mixture rom off-site for storage/bulking and trans		0.00 Tons
Chipped to	Shipped to: C	HD980613541 H040 In	cineration - thermal destruction other tha	an use as a	20.49 Tons

Waste Generation and Management Information Generated, Treat	ed, Shipped Tons
GM Page: 00034 IGNITABLE ORGANIC ACID SOLUTION FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D001 F002 F003 F005 F001	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	1.52 Tons
GM Page: 00035  W001  Lab packs with no acute hazardous waste (from any source)  G61  Hazardous waste received from off-site for storage/bulking and transfer off-site  D002  D001  U123	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.07 Tons
GM Page: 00036   BENZIDINE LAB PACK FROM TSD OPERATION	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.06 Tons
GM Page: 00037 AMMONIUM SULFIDE SOLUTION LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D003 D001	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.02 Tons
GM Page: 00038 OXIDIZING CORROSIVE LIQUID LAB PACK FROM TSD OPERATION W001 Lab packs with no acute hazardous waste (from any source) G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D001 D002 D011 D005 D007 D008	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.60 Tons
GM Page: 00039 OXIDIZER SOLID LAB PACK FROM TSD OPERATION W001 Lab packs with no acute hazardous waste (from any source) G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D001 D011 D005 D007 D008 D006	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.74 Tons
GM Page: 00040  W001  Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site  U067	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.00 Tons

Waste Generation and Management Information Generated, Tree	eated, Shipped Tons
W004 Lab packs containing acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.16 Tons
FURFURAL LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  U125	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.05 Tons
M Page: 00043 INORGANIC TOXIC SOLID LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D004 D005 D006 D007 D008 D010	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.71 Tons
M Page: 00044  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 U117	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.01 Tons
M Page: 00045  IGNITABLE ACETIC SOLVENTS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002 F002 F003 F005 D004	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.72 Tons
M Page: 00046  IGNITABLE METAL POWDERS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D003 D001 D005 D008	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.85 Tons
SILVER PLATING SOLUTION LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D011 F007 D003 D006 D007	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.15 Tons

Waste Generation and Management Information Generated, Treated, S	Shipped Tons
GM Page: 00048  W001  Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.05 Tons
W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.08 Tons
MPage: 00050 INORGANIC ACID LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D004 D005 D006 D007 D008 D010 D011	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.82 Tons
GM Page: 00051  TOXIC LIQUID LAB PACK FROM TSD OPERATION  W001  Lab packs with no acute hazardous waste (from any source)  G61  Hazardous waste received from off-site for storage/bulking and transfer off-site  U052  U072  U144  U190  U218  D004  D005  D006  D007  D008  D010  D011  D025  D027	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.20 Tons
GM Page: 00052  IGNITABLE TOXIC LIQUID LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 U056 U028 D038	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.07 Tons
GM Page: 00053  TOXIC SOLID LAB PACK FROM TSD OPERATION  W001  Lab packs with no acute hazardous waste (from any source)  G61  Hazardous waste received from off-site for storage/bulking and transfer off-site  U052  U127  U187  U240  D004  D005  D006  D007  D008  D010  D011  D016  D025  D032	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.29 Tons
GM Page: 00054 IGNITABLE ORGANIC ACIDS LAB PACK FROM TSD BULKING OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002	0.00 Tons

Waste Generation and Management Information Generated, Trea	ated, Shipped Tons
GM Page: 00055  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.07 Tons
W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.02 Tons
GM Page: 00057 IGNITABLE SOLIDS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 U160 U165 U183	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.08 Tons
GM Page: 00058  BENOMYL LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D004 U271	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.00 Tons
GM Page: 00059 IGNITABLE ACETIC TOXIC LIQUID LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002 F002 F003 F005 U404 D011	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.08 Tons
GM Page: 00060  W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D003	0.00 Tons
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.03 Tons
	0.00-
W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D002	0.00 Tons

Waste Generation and Management Information Generated, Treated,	Shipped Tons
IGNITABLE PHARMACEUTICAL DRUG AEROSOL INHALERS FROM TSD BULKING OPERAT  ION  W005 Waste pharmaceuticals managed as hazardous waste	0.00.
G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D003	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	<b>0.11</b> Tons
W005 Waste pharmaceuticals managed as hazardous waste G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D004 D005	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.05 Tons
GM Page: 00064  ACUTE TOXIC PHARMCEUTICAL DRUGS FROM TSD BULKING OPERATION  W005  Waste pharmaceuticals managed as hazardous waste  G61  Hazardous waste received from off-site for storage/bulking and transfer off-site  P042  P046  P081  U002  U010  U035  U058  U059  U089  U129  U132  U150  U154  U187  U200  U201  P001  P002  U026  U206  U207  U248  D001  D004	<b>0.00 Ton</b>
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	7.75 Tons
GM Page: 00065  W001  Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site  D009	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.00 Tons
GM Page: 00066  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D002 D009 D007 D011	0.00 Ton
Shipped to: OHD980613541 H040 Incineration - thermal destruction other than use as a	0.06 Tons
W001 Lab packs with no acute hazardous waste (from any source)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site	0.00 Ton
Shipped to: IND093219012 H040 Incineration - thermal destruction other than use as a	0.01 Tons
GM Page: 00068  CAUSTIC ALKALINE CLEANERS SOLUTION FROM TSD OPERATION  W110  Caustic aqueous waste without cyanides (Ph > 12.5)  G61  Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Ton
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	9.28 Tons

Waste Generation and Management Information Generated, Treated	d, Shipped Tons
GM Page: 00069 W110 Caustic aqueous waste without cyanides( Ph >12.5) Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Tons
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	6.04 Tons
GM Page: 00070  W105 Acidic aqueous wastes less than 5% acid (diluted but Ph <2) Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Tons
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	34.64 Tons
GM Page: 00071   INORGANIC ACIDS WITH METALS IN AQUEOUS SOLUTION FROM TSD OPERATION	0.00 Tons
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	<b>21</b> .66 Tons
GM Page: 00072  NITRIC ACID IN AQUEOUS SOLUTION FROM TSD OPERATION  Acidic aqueous wastes less than 5% acid (diluted but Ph <2)  Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Tons
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	0.68 Tons
GM Page: 00073 OXIDIZING SOLIDS LAB PACK FROM TSD OPERATION  W001 Lab packs with no acute hazardous waste (from any source)  Hazardous waste received from off-site for storage/bulking and transfer off-site  D001	0.00 Tons
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	0.17 Tons
GM Page: 00074 SULFURIC ACID SOLUTION FROM TSD OPERATIONS Acidic aqueous wastes less than 5% acid (diluted but Ph <2) Hazardous waste received from off-site for storage/bulking and transfer off-site  D002	0.00 Tons
Shipped to: TXD069452340 H132 Landfill or surface impoundment that will be closed as	32.51 Tons
GM Page: 00075 POTASSIUM HYDROXIDE SOLUTION CONTAININGSPENT OXYGEN CANISTERS FROM TSD OPERATION W110 Caustic aqueous waste without cyanides( Ph >12.5) G61 Hazardous waste received from off-site for storage/bulking and transfer off-site D002 D005	0.00 Tons

	Management Information Generated, Treated,	Shipped Tons
W319 Other inorganic s	EDIA CONTAINING METALS FROM TSD OPERATION solids (specify in comments) re received from off-site for storage/bulking and transfer off-site	0.00 Ton
Shipped to: TXD069452340	H132 Landfill or surface impoundment that will be closed as	4.84 Tons
W211 Paint thinner or p	MATERIALS FROM TSD OPERATION petroleum distillates e received from off-site for storage/bulking and transfer off-site	0.00 Ton
Shipped to: TXD069452340	H141 Storage, bulking, and/or transfer off-site - no	2.73 Tons
TION W204 Concentrated ha	Alogenated/ non-halogenated solvent mixture e received from off-site for storage/bulking and transfer off-site F005 D004 D005 D006 D007 D008 D019 D032 D033 D034 11 D042 D043	<b>0.00 Tons</b>
Shipped to: KYD053348108	H061 Fuel blending prior to energy recovery at another site.	<b>224.66</b> Tons
M Page: 00079 IGNITABLE SOLV	/ENTS AND PAINT FUELS FROM TSD OPERATION	
W204 Concentrated ha. G61 Hazardous waste F001 F002 F003 F004	alogenated/ non-halogenated solvent mixture e received from off-site for storage/bulking and transfer off-site F005 D004 D005 D006 D007 D008 D019 D035 D038 D039 44 U166 D018 D027 D028 D029 D030	<b>0.00 Tons</b>
W204 Concentrated ha. G61 Hazardous waste F001 F002 F003 F004	e received from off-site for storage/bulking and transfer off-site F005 D004 D005 D006 D007 D008 D019 D035 D038 D039	
W204 Concentrated hat G61 Hazardous waste F001 F002 F003 F004 D043 D009 D010 D011 U002 U164  Shipped to: SCD003368891  GM Page: 00080 IGNITABLE SOLV W204 Concentrated hat G61 Hazardous waste F001 F002 F003 F004	e received from off-site for storage/bulking and transfer off-site F005 D004 D005 D006 D007 D008 D019 D035 D038 D039 4 U166 D018 D027 D028 D029 D030	D040
W204 Concentrated hat G61 Hazardous waste F001 F002 F003 F004 D043 D009 D010 D011 U002 U164  Shipped to: SCD003368891  GM Page: 00080 IGNITABLE SOLV W204 Concentrated hat G61 Hazardous waste F001 F002 F003 F004	e received from off-site for storage/bulking and transfer off-site  F005 D004 D005 D006 D007 D008 D019 D035 D038 D039  44 U166 D018 D027 D028 D029 D030  H050 Energy recovery at this site - use as fuel (includes  /ENTS AND PAINTS FUEL BLENDED FROM TSD OPERATION  alogenated/ non-halogenated solvent mixture  e received from off-site for storage/bulking and transfer off-site  F005 D004 D005 D006 D007 D008 D019 D035 D038 D039	533.47 Tons 0.00 Tons

Shipped to: ALD000622464

H132

Landfill or surface impoundment that will be closed as

300.94 Tons

Waste Generation and Management Information Generated, Treated, S	Shipped Tons
MIXED WASTE IGNITABLE SOLVENTS FROM TSD FUEL BLENDING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G25 Hazardous waste management - indicate management method (residuals from F001 F002 F003 F005 U220 D001 U074 U228	0.00 Ton
Shipped to: TND982109142 H050 Energy recovery at this site - use as fuel (includes	13.71 Tons
MIXED WASTE IGNITABLE SOLVENTS FROM TSD FUEL BLENDING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G25 Hazardous waste management - indicate management method (residuals from D004 D005 D006 D007 D008 D009 D010 D011 F002 F003 F005 D001 U188 U220	0.00 Tons
Shipped to: TND982109142 H050 Energy recovery at this site - use as fuel (includes	11.47 Tons
GM Page: 00084 MIXED WASTE IGNITABLE SOLVENTS FROM TSD FUEL BLENDING OPERATION	
W204 Concentrated halogenated/ non-halogenated solvent mixture G25 Hazardous waste management - indicate management method (residuals from D004 D005 D006 D007 D008 D009 D010 D011 F001 F002 F003 F005 P098 U138 U220 D001 F004 P106 U003 U011 U036 U052 U061 U063 U142 U163 U188 U211 U240	<b>0.00 Tons</b>
Shipped to: TND982109142 H050 Energy recovery at this site - use as fuel (includes	19.26 Tons
IGNITABLE AEROSOLS FROM TSD OPERATION  W801 Compressed gases (any type)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D001 D035	0.00 Tons
Shipped to: KYD985073196 H141 Storage, bulking, and/or transfer off-site - no	26.85 Tons
MIXED WASTE SOLIDS WHICH CONTAIN ORGANICS FROM TSD BULKING OPERATION  W204 Concentrated halogenated/ non-halogenated solvent mixture  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  F001 F002 F003 F005 D007 D008	0.00 Tons
Shipped to: TNR987766078 H129 Other treatment (specify in comments - not otherwise	8.61 Tons
MIXED WASTE DEBRIS WITH REACTIVE CHARACTERISTIC LITHIUM BATTERIES FROM  TSD BULKING OPERATION  W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  F005 F003 D003 D004 D005 D006 D007 D008 D009 D010 D011	0.00 Tons
Shipped to: UTD982598898 H132 Landfill or surface impoundment that will be closed as	1.44 Tons
GM Page: 00088 MIXED WASTE DEBRIS WITH LEAD ACID BATTERIES FROM TSD BULKING OPERATION	0.00 Tons
W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site  D008 D002	

Waste Generation and Management Information Gene	rated, Treated, Shipped Tons
MIXED WASTE THAT IS PRIMARILY INORGANIC WITH METALS FROM TSD BUL PERATION W319 Other inorganic solids (specify in comments)	0.00 Ton
G61 Hazardous waste received from off-site for storage/bulking and transfer off-si  D004 D006	te
Shipped to: UTD982598898 H132 Landfill or surface impoundment that will be closed	as 0.61 Tons
MIXED WASTE THAT IS PRIMARILY INORGANIC WITH METALS FROM TSD BUL PERATION	KING O
W319 Other inorganic solids (specify in comments)  G61 Hazardous waste received from off-site for storage/bulking and transfer off-site double	<b>0.00 Ton</b> ste
Shipped to: UTD982598898 H132 Landfill or surface impoundment that will be closed	as <b>5.87 Tons</b>
MIXED WASTE DEBRIS, DEVICES FROM TSD MACRO OERATION  W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  G25 Hazardous waste management - indicate management method (residuals fro  F001 F003 D004 D005 D006 D007 D008 D009	<b>0.00 Ton</b> s
Shipped to: TXD988088464 H132 Landfill or surface impoundment that will be closed	as <b>7.58</b> Tons
W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic Hazardous waste management - indicate management method (residuals from D008	<b>0.00 Ton</b> s
Shipped to: NV3890090001 H132 Landfill or surface impoundment that will be closed	as 0.80 Tons
MIXED WASTE DEBRIS, DEVICES FROM TSD MACRO OPERATION  W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  G25 Hazardous waste management - indicate management method (residuals from D008 F001 F002 F003 F004 F005	<b>0.00 Ton</b> s
Shipped to: NV3890090001 H132 Landfill or surface impoundment that will be closed	as 0.39 Tons
MIXED WASTE DEBRIS, DEVICES FROM TSD MACRO OPERATION  W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  G25 Hazardous waste management - indicate management method (residuals fro  D008 F002 D004 D005 D006 D007	<b>0.00 Tons</b> m
Shipped to: NV3890090001 H132 Landfill or surface impoundment that will be closed	as 0.34 Tons
MIXED WASTE DEBRIS, DEVICES FROM TSD MACRO OPERATION  W002 Contaminated debris: paper, clothing, rags, wood, empty fiber or plastic  Hazardous waste management - indicate management method (residuals fro	<b>0.00 Tons</b> m
Shipped to: NV3890090001 H132 Landfill or surface impoundment that will be closed	as 6.54 Tons

Waste G	eneration and	Mana	gement Information	Generated, Trea	ted, Shipped Tons
GM Page: 00096 W001 G61 D002	Lab packs with n	o acute	ER SOLUTION LAB PACK FROM TSD OPER e hazardous waste (from any source) red from off-site for storage/bulking and tra		0.00 Ton
Shipped to: F	LD984229609	H141	Storage, bulking, and/or transfer off-site	- no	0.10 Tons
GM Page: 00097  W001  G61  D011 D0	N Lab packs with n Hazardous waste	o acute	TAINING SILVER NITRATE LAB PACK FROM hazardous waste (from any source) red from off-site for storage/bulking and train		0.00 Ton
Shipped to: F	LD984229609	H141	Storage, bulking, and/or transfer off-site	- no	2.48 Tons
W001 G61 D011 D0	N Lab packs with n Hazardous waste	o acute	TAINING SILVER NITRATE LAB PACK FROM hazardous waste (from any source) ed from off-site for storage/bulking and trai		0.00 Tons
Shipped to: F	LD984229609	H141	Storage, bulking, and/or transfer off-site	- no	0.06 Tons
GM Page: 00099 W002 G61 D009	Contaminated de	bris: pa	WITH ELEMENTAL MERCURY FROM TSD (aper, clothing, rags, wood, empty fiber or pled from off-site for storage/bulking and trans	astic	0.00 Tons
Shipped to: L	AD000365668	H141	Storage, bulking, and/or transfer off-site	- no	0.14 Tons
M Page: 00100 W001 G61 D009	Lab packs with n	o acute	LIDS LAB PACK FROM TSD OPERATION hazardous waste (from any source) ed from off-site for storage/bulking and trai	nsfer off-site	0.00 Tons
Shipped to: L	AD000365668	H141	Storage, bulking, and/or transfer off-site	- no	0.02 Tons
GM Page: 00101 W001 G61 D002 D0	Lab packs with n Hazardous waste	o acute	LIDS LAB PACK FROM TSD OPERATION hazardous waste (from any source) hed from off-site for storage/bulking and train	nsfer off-site	0.00 Ton
Shipped to: L	AD000365668	H141	Storage, bulking, and/or transfer off-site	- no	0.00 Tons
GM Page: 00102 W001 G61 D009 D0	Lab packs with n Hazardous waste	o acute	SOLUTION LAB PACK FROM TSD OPERATION has hazardous waste (from any source) red from off-site for storage/bulking and training		0.00 Tons
Shipped to: L	AD000365668	H141	Storage, bulking, and/or transfer off-site	- no	0.20 Tons

*## Dawa. 00100					
W001 G61 D009	Lab packs with	no acute	DLUTION LAB PACK FROM TSD OPERATION hazardous waste (from any source) ed from off-site for storage/bulking and transfe	er off-site	0.00 To
Shipped to: LA	D000365668	H141	Storage, bulking, and/or transfer off-site - no	)	0.11 Tons



March 31, 2016 <u>VIA UPS</u>

Erin Wilcox Department of Environmental Protection Hazardous Waste Management Section 2600 Blair Stone Road, MS 4555 Tallahassee, FL 32399-2400

RE: Biennial Report Submission for Perma-Fix of Florida (FLD980711071)

Dear Ms. Wilcox:

With this letter I am submitting a signed Site Identification form, a summary of GM forms and an electronic copy of GM, WR and OI forms as required for the 2015 Hazardous Waste Biennial Report. The electronic files are in a zipped file named "fld980711071br2015.zip" on the root directory of the enclosed data CD.

If you have any questions regarding this information, please feel free to call me at (352) 395-1356 or e-mail me at kfogleman@perma-fix.com.

Sincerely,

Kurt Fogleman

Environmental, Health and Safety Manager

Perma-Fix of Florida, Inc.