

Knauss, Elizabeth

From: BOSEK, JOHN E <bosek.john@cleanharbors.com>
Sent: Thursday, March 23, 2017 2:43 PM
To: neill.mike@epamail.epa.gov; garcia.javier@epa.gov
Cc: Knauss, Elizabeth; Desha, David A.
Subject: Subpart BB recheck results of T-101 and T-102
Attachments: 0708_001.pdf

Good afternoon –

Here are the updated readings from T-101 and T-102 after the gaskets were repaired / replaced.

Safety Starts with Me: Live It 3-6-5

John Bosek

Facility General Manager
Clean Harbors Florida LLC
7001 Kilo Avenue
Bartow, FL 33830
(o) 863.519.6331
(c) 863.559.1610
(f) 863.519.6361

bosek.john@cleanharbors.com

www.cleanharbors.com



From: noreply@cleanharbors.com [mailto:noreply@cleanharbors.com]
Sent: Thursday, March 23, 2017 2:33 PM
To: BOSEK, JOHN E
Subject: Attached Image