

[illegible]

"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 120.1","Specific Conductance","308","umhos/cm","D","Chris Monaco","03/14/2011 14:34","A101108","Y","SEMGW"

"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 360.1","Dissolved Oxygen","0.56","mg/l","D","Chris Monaco","03/14/2011 14:34","A101108","Y","SEMGW"

"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 150.1","pH","7.03","SU","D","Chris Monaco","03/14/2011 14:34","A101108","Y","SEMGW"

"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","24.25","degrees C","D","Chris Monaco","03/14/2011 14:34","A101108","Y","SEMGW"

"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","0.50","NTU","D","Chris Monaco","03/14/2011 14:34","A101108","Y","SEMGW"

"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.00","FT","D","Chris Monaco","03/14/2011 14:34","A101108","Y","SEMGW"

"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 120.1","Specific Conductance","334","umhos/cm","D","Chris Monaco","03/14/2011 15:57","A101108","Y","SEMGW"

"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 360.1","Dissolved Oxygen","2.46","mg/l","D","Chris Monaco","03/14/2011 15:57","A101108","Y","SEMGW"

"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 150.1","pH","7.33","SU","D","Chris Monaco","03/14/2011 15:57","A101108","Y","SEMGW"

"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 170.1","Temperature, Water","23.12","degrees C","D","Chris Monaco","03/14/2011 15:57","A101108","Y","SEMGW"

"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 180.1","Turbidity","0.20","NTU","D","Chris Monaco","03/14/2011 15:57","A101108","Y","SEMGW"

"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 120.1","Specific Conductance","361","umhos/cm","D","Chris Monaco","03/15/2011 14:12","A101420","Y","SEMGW"

"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 360.1","Dissolved Oxygen","1.73","mg/l","D","Chris Monaco","03/15/2011 14:12","A101420","Y","SEMGW"

"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 150.1","pH","7.19","SU","D","Chris Monaco","03/15/2011 14:12","A101420","Y","SEMGW"

"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","23.18","degrees C","D","Chris Monaco","03/15/2011 14:12","A101420","Y","SEMGW"

"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","0.90","NTU","D","Chris Monaco","03/15/2011 14:12","A101420","Y","SEMGW"

"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","65.79","FT","D","Chris Monaco","03/15/2011 14:12","A101420","Y","SEMGW"

"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 120.1","Specific Conductance","251","umhos/cm","D","Chris Monaco","03/15/2011 14:49","A101420","Y","SEMGW"

"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 360.1","Dissolved Oxygen","2.53","mg/l","D","Chris Monaco","03/15/2011 14:49","A101420","Y","SEMGW"

"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 150.1","pH","7.56","SU","D","Chris Monaco","03/15/2011 14:49","A101420","Y","SEMGW"

"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","23.84","degrees C","D","Chris Monaco","03/15/2011 14:49","A101420","Y","SEMGW"

"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","0.50","NTU","D","Chris Monaco","03/15/2011 14:49","A101420","Y","SEMGW"

"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","65.92","FT","D","Chris Monaco","03/15/2011 14:49","A101420","Y","SEMGW"

,"EQUIPMENT BLANK1","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Chris Monaco","03/14/2011 16:10","A101108",,

,"EQUIPMENT BLANK2","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Chris Monaco","03/15/2011 13:02","A101396",,"DUP"

,"TRIP BLANK1","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/14/2011 00:00","A101108",,

,"TRIP BLANK2","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/14/2011 00:00","A101396",,

,"TRIP BLANK4","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/16/2011 00:00","A101420",,