

40612

May 9, 2011

Department of environmental Protection
13051 North Telecom Parkway
Temple Terrace, FL 33637-0926

Dept. Of Environmental Protection
MAY 11 2011
Southwest District

Dear Ms.Gaskins:

In response to the inspection of our facility, that was conducted March 24,2011. The following corrections are being addressed in the closure permit.

Rule: 62-701.320(1), 403-161

Question Number: 4.24

Explanation: At the time of the inspection the Hardee County Landfill received several roll off loads of railroad ties in order not to use what little space the landfill had we found a recycling company to take the loads of railroad ties we had already received from the mines. Corrective Actions: We shipped what ties were left and have notified the mines we are unable to take the mass loads of railroad ties they had and suggested other disposal options.

Rule: 62-701.500(4), 62.701.500(13)(c),

Question Number: 1.2


Correction: The Topo for capacity estimate have been submitted to FDEP

Rule: 62-701.510(6)(c), 62.701.500(8)(a)

Question Number: 1.3

Corrective actions: The contractor's Vice President was notified of the violations and to follow up made sure the samples were taken and submitted.

Thank you,



Teresa Carver
Hardee County
Solid Waste Director