

"21324","MW-9B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","25.93","degrees C","D","Chris Monaco","03/14/2012 11:08","A201113","Y","SEMGW"
"21324","MW-9B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","1.50","NTU","D","Chris Monaco","03/14/2012 11:08","A201113","Y","SEMGW"
"21324","MW-9B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.02","FT","D","Chris Monaco","03/14/2012 11:08","A201113","Y","SEMGW"
"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 120.1","Specific Conductance","337","umhos/cm","D","Chris Monaco","03/14/2012 11:41","A201113","Y","SEMGW"
"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 360.1","Dissolved Oxygen","0.33","mg/l","D","Chris Monaco","03/14/2012 11:41","A201113","Y","SEMGW"
"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 150.1","pH","6.82","SU","D","Chris Monaco","03/14/2012 11:41","A201113","Y","SEMGW"
"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","25.34","degrees C","D","Chris Monaco","03/14/2012 11:41","A201113","Y","SEMGW"
"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","0.90","NTU","D","Chris Monaco","03/14/2012 11:41","A201113","Y","SEMGW"
"21325","MW-10B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.23","FT","D","Chris Monaco","03/14/2012 11:41","A201113","Y","SEMGW"
"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 120.1","Specific Conductance","329","umhos/cm","D","Chris Monaco","03/13/2012 16:47","A201113","Y","SEMGW"
"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 360.1","Dissolved Oxygen","2.29","mg/l","D","Chris Monaco","03/13/2012 16:47","A201113","Y","SEMGW"
"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 150.1","pH","6.86","SU","D","Chris Monaco","03/13/2012 16:47","A201113","Y","SEMGW"
"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 170.1","Temperature, Water","23.90","degrees C","D","Chris Monaco","03/13/2012 16:47","A201113","Y","SEMGW"
"21326","Supply Well","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","BP","W","EPA 180.1","Turbidity","0.70","NTU","D","Chris Monaco","03/13/2012 16:47","A201113","Y","SEMGW"
"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 120.1","Specific Conductance","361","umhos/cm","D","Chris Monaco","03/14/2012 16:47","A201358","Y","SEMGW"
"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 360.1","Dissolved Oxygen","1.90","mg/l","D","Chris Monaco","03/14/2012 16:47","A201358","Y","SEMGW"
"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 150.1","pH","6.73","SU","D","Chris Monaco","03/14/2012 16:47","A201358","Y","SEMGW"
"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","24.04","degrees C","D","Chris Monaco","03/14/2012 16:47","A201358","Y","SEMGW"
"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","2.00","NTU","D","Chris Monaco","03/14/2012 16:47","A201358","Y","SEMGW"
"21964","MW-3B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.10","FT","D","Chris Monaco","03/14/2012 16:47","A201358","Y","SEMGW"
"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 120.1","Specific Conductance","256","umhos/cm","D","Chris Monaco","03/14/2012 17:08","A201358","Y","SEMGW"
"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 360.1","Dissolved Oxygen","2.50","mg/l","D","Chris Monaco","03/14/2012 17:08","A201358","Y","SEMGW"
"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 150.1","pH","7.20","SU","D","Chris Monaco","03/14/2012 17:08","A201358","Y","SEMGW"
"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 170.1","Temperature, Water","23.55","degrees C","D","Chris Monaco","03/14/2012 17:08","A201358","Y","SEMGW"
"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","EPA 180.1","Turbidity","0.70","NTU","D","Chris Monaco","03/14/2012 17:08","A201358","Y","SEMGW"
"21965","MW-4B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.10","FT","D","Chris Monaco","03/14/2012 17:08","A201358","Y","SEMGW"
,"EQUIPMENT BLANK1","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Chris Monaco","03/14/2012 16:14","A201358",,
,"TRIP BLANK1","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/14/2012 00:00","A201113",,
,"TRIP BLANK2","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/14/2012 00:00","A201358",,
,"TRIP BLANK3","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/13/2012 00:00","A201113",,
,"TRIP BLANK4","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/13/2012 00:00","A201113",,
"28682","MW-15B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.07","FT","D","Chris Monaco","03/13/2012 13:03","A201113","Y","SEMGW"
"28683","MW-16B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.12","FT","D","Chris Monaco","03/13/2012 14:33","A201113","Y","SEMGW"
"28684","MW-17B","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","SP","W","DEP-SOP","Water Level (NGVD)","66.02","FT","D","Chris Monaco","03/13/2012 15:42","A201113","Y","SEMGW"
,"TRIP BLANK1","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/14/2012 00:00","A201113",,
,"TRIP BLANK3","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/13/2012 00:00","A201113",,
,"TRIP BLANK4","87895","ENTERPRISE LF & RECYC (FKA SID LARKIN & SON, INC.)","W","","Enco","03/13/2012 00:00","A201113",,