



July 9, 2015

Thomas Lubozynski, P.E.
Florida Department of Environmental Protection
Central District
3319 Maguire Boulevard
Suite 232
Orlando, Florida 32803

Re: Groundwater Monitoring Notification
Tomoka Farms Road Landfill
Facility ID: 27540

Dear Mr. Lubozynski:

This notification is being transmitted to notify the FEDP that, during the May 2015 Semiannual Groundwater Sampling and Monitoring Event at the facility noted above, that, lead and mercury were identified in the surface water sample collected from SW-1 at concentrations (10.4 µg/L and 31.3 ng/L respectively) above their respective Class III criteria as specified in 62-302.530, F.A.C.

However, SW-1 is located adjacent to Interstate 4 which has undergone significant drainage modifications recently. FDOT has expanded the pond and also now discharges storm water from I-4 into the pond. Up to this time, SW-1 has not had any exceedances.

During the last permit renewal with FDEP we requested that the sampling point be removed from the MPIS due to these changes. However, FDEP only changed its well type. At this time, we again request for this sampling point to be removed from the MPIS due to this impact from FDOT and I-4 runoff.

Sincerely,
HDR Engineering, Inc.

A handwritten signature in black ink that reads 'Handi Wang'.

Handi Wang, PhD
Sr. Environmental Scientist

hdrinc.com

200 W Forsyth Street, Suite 800
Jacksonville, FL 32202
904 598 8900 O 904 598 8988 F, Jacksonville, FL 32202-4321
(904) 598-8900