

Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

															_
		WELL # & NAME			WELL TYPE		0	OG/PA NUMBER		- 1	DATE INSPECTED				
	8-1 ST. REGIS PAPER CO.			INJE	IECTOR OG_511 3115		311584		5/5/2020						
OPERATOR				FIELD			COUNTY API NUM		MBER						
BREITBURN OPERATING, L.P.					JA	ΔY		SANTA ROSA 09-113-20034							
						WELLS	/ELL STATUS			L	LAST MIT P F			1	
						IN (TE	MPOR	IPORARILY) 1/28/2020				/28/2020	✓		1
											•				
WELL SITE INSPECTION CHECKPOINTS						YES	NO				NOTES				
LEGIBLE WELL SIGN POSTED						~									
PAD HOUSEKEEPING SUFFICIENT						~									
PERIMETER BERM/DIKE SUFFICIENT						~									
FLOW	LINE/PIPE	LINE A	ACCESI	BLE/CLEAN		~									
	NCE OF L		SPILLS	ON			,								
PAD/L	OCATION														
WELLHEADS					YES	NO	N	IOTES	6-*MAX INJEC	CTION-	4 400 PW/	7 500 N	12*		
PRESSURE GAUGES IN WORKING CONDITION						·		•		III) DE III DE	<u> </u>	1,1001111	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•	
TUBING* ANNULAR SURFACE															
								TSI							
5300 0 0				~											
HIGH/LOW FLOWLINE SHUT IN SENSORS LOCATED NEAR WELLHEAD															
	ED NEAR	1	Γ				~				N/A				
HIGH: LOW:															
CELLAR CONDITION SATISFACTORY					~										
WELLHEAD LEAKING						~									
	HYDROGEN SULFIDE DETECTION SYSTEM														
IF YES, FILL OUT						YES	NO			ı	NOTES				
DETECTION SYSTEM REQUIRED						>									
ENTRY ALARMS IN WORKING CONDITION										N/A					
SENSORS IN WORKING CONDITION										N/A					
CHEMICAL ADDITIVE SYSTEM					YES	NO	NOTES								
SYSTEM PRESENT						~									
SYSTEM LEAKING										N/A					
SECONDARY CONTAINMENT PROVIDED										N/A					
CHEMICALS ON LOCATION						1.)									
					2.)										
ı															



Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Permit Number	511		
Oculus ID	OG_511	Current Status	INJ
API Number	0911320034	Historical Status	PRODUCER/INJ
PA Number	311584	TVD	15,872
Well Name	SRPC #8-1	MD	15,872
Operator	BREITBURN OPERATING LP	Conductor Casing	20"@ 80'
Field	JAY	Surface Casing	10-3/4"@ 3628
County	SANTA ROSA	Intermediate Casing	NA
Sec/Twp/Range	4S8 5N 29W	Production Casing	7"@ 15857
SHL	1227'FNL&2388'FWL	Tubing	3-1/2"@ 15350
BHL	SAME	Perforations	15583-15642
Latitude	30.96869281	Plugs	
Longitude	-87.18226779	Issue Date	8/3/1971
		Spud Date	12/31/1971
		Completion Date	4/10/1972
		Plug Date	



WELL SIGN

WELL & PAD

I inspected the above well & premise on May 5, 2020

Signed

ØIL AND GAS COORDINATOR

[X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1

cc: