## RECEIVED



MAR 0 3 2008 NORTHWEST FLORIDA

TECHNICAL SOLUTIONS
NORTH AMERICA

February 29, 2008

Ms. Melissa Woehle Florida Department of Environmental Protection 160 Governmental Center Pensacola, FL 32502-8360

RE: February 20th, 2008 Equipment Event

Dear Ms. Woehle,

Veolia ES Technical Solutions, L.L.C. (Veolia) is submitting this event report in accordance with the requirements of s. 40 CFR 264.56(i) The event occurred at Veolia's Tallahassee location and involved a small electrical fire in the control panel during the operation of what is known as Lamp Line One. The details are provided below.

## Owner:

Veolia ES Technical Solutions, L.L.C. 700 East Butterfield Road Lombard, IL 60148

## **Facility:**

Veolia ES Technical Solutions, L.L.C. 342 Marpan Lane Tallahassee, FL 32305 FL0000207449

Type of Incident: Fire

Date and Time of Incident: February 20<sup>th</sup>, 2008 approx. time 7:40am (eastern)

Name and Quantity of Material: There was no material released.

Injuries: None

Potential or Actual Hazard to Human Health or Environment: None.

Quantity and Disposition of Materials: There was no resulting material to clean up from this

incident.

Narrative: At approximately 7:40am the operator of the processing equipment noticed smoke coming from the control panel. Upon notification and donning of PPE facility staff members discovered a small electrical fire in the control panel of the equipment. This was the result of a small piece of metal jamming the crusher unit and backing it up, the motor continued to run. The

Ms. Melissa Woehle February 29, 2008 Page 2 of 2

overload sensor on the system failed for reasons unknown at this time. All electrical power was cut to the panel and the resulting electrical fire was immediately put out using the fire extinguisher located in the processing room.

Contingency Plan Amendments: A review of the Contingency Plan was completed and the specific incidences of the spill were reviewed. Veolia determined that amendments to the facility's contingency plan are not necessary.

If you have any questions please call me at 850-877-8299.

Sincerely,

VEOLIA ES TECHNICAL SOLUTIONS, L.L.C.

Linda Dunwoody Operation Manager

cc:

Mr. Phillip Ditter - Veolia ES Technical Solutions, L.L.C. EH&S

Mr. John Mc Shane – Veolia ES Technical Solutions, L.L.C. General Manager

File

Enclosure: As Stated

LD

