



# Florida Department of Environmental Protection

Northwest District  
160 Governmental Center  
Pensacola, Florida 32502-5794

Charlie Crist  
Governor

Jeff Kottkamp  
Lt. Governor

Michael W. Sole  
Secretary

April 25, 2008

Mr. Joe Wier  
McKenzie Tank Lines, Inc.  
Post Office Box 1200  
Tallahassee, Florida 32302

Dear Mr. Wier:

This letter is in regards to the Drum Cleanup Project at the McKenzie Tank Lines Inc., (COM\_68413) located at 2778 West Tharpe Street, Tallahassee, Leon County, Florida.

Upon review of the February 25, 2008 Interim Source Removal report (ISRR) Addendum, it appears that no impacted soils remain in the East Drum Accumulation Area. It was this area that Florida Department of Environmental Protection and Region IV Environmental Protection Agency personnel discovered several 55-gallon drums of material improperly stored with evidence of spilled material in a site inspection conducted in February 2007.

However, during the assessment, your consultant has identified impacted soils in the north, northwest portion of the site in areas where additional drums had been stored. This area has been identified as the Washrack Drum/West Drum Accumulation/Drums West/Drum 76 Area on the site map included in the February 25, 2008 ISRR Addendum; a copy of map is enclosed. Since this area is located approximately 200 feet west of the East Drum Accumulation Area and the impacted soils were not discovered until later on in the assessment prompted by the site inspection, it has been determined that these two areas are to be considered separate and independent cleanup projects by the Department. Therefore, each project will be required to meet the criteria of Chapter 62-780, Florida Administrative Code.

Upon review of the information submitted to date, it appears that the East Drum Accumulation Area cleanup project (FDEP COM\_312177) may meet the No Further Action (NFA) criteria of Rule 62-780.680, F.A.C. An NFA Proposal regarding the East Drum Accumulation Area project should be submitted to the FDEP Northwest District Cleanup Section for review. The groundwater analytical and sampling logs for the re-sampling of well MW-2D requested in our March 27, 2008 letter should be included in the proposal.

Mr. Joe Wier  
McKenzie Tank Lines, Inc.  
April 25, 2008  
Page two

Furthermore, a complete site assessment should commence in the West Drum Accumulation Area (FDEP COM\_312175) and a site assessment report (SAR) meeting the criteria of Rule 62-780.600, F.A.C will need to be submitted to the FDEP Northwest District Cleanup Section for review.

Unless notified otherwise, we look forward to receiving your NFA Proposal for the East Drum Accumulation Area cleanup project by June 30, 2008 and a SAR for the West Drum Accumulation Area no later than December 31, 2008. If you have any questions please contact Julie Ann Hardy, Project Manager, at (850) 595-8360, extension 1211 or at email address [julie.hardy@dep.state.fl.us](mailto:julie.hardy@dep.state.fl.us).

Sincerely,

A handwritten signature in cursive script that reads "Karen Shea".

Karen Shea, P.E.  
Cleanup Section Supervisor

KBS:jhr

Enclosure: Map Page from February 2008 ISSR Addendum

cc: John M. Elrod, P.G., Geovac Environmental Services, Inc.  
Jim Byer, FDEP

# LEGEND

- Recovery Well
  - ⊛ Monitoring Well
  - Sand Blast Materials
  - Drum Accumulation
- all data in mg/Kg dry  
Flags  
I - between lab reporting  
limit and detection limit  
V - also in blanks


Washrack Drums 7/17/07  
1,2,4-Trimethylbenzene 0.0003  
Acetone 0.0067 V  
Benzene 0.0003 I  
Carbon Disulfide 0.001 I  
m,p xylenes 0.0004 I  
Styrene 0.0003 I  
Toluene 0.0006 I  
TPH 489  
Drums West, 1/31/08  
Benzo(b)fluoranthene 0.24 I  
Benzo(g,h,i)perylene 0.27 I  
Fluoranthene 0.21 I  
Ideno(1,2,3-cd)pyrene 0.27 I  
TPH 96

Drum 76, 7/17/07  
Methylene Chloride 0.018  
Toluene 0.0003 I  
Benzo(b)fluoranthene 0.4 I  
Phenanthrene 0.20 I  
TPH 421

Railroad  
Spur

spent blast  
sand

Excavation Area



Samples:  
Washrack Drums  
Drums West

West drum  
accumulation  
area

wash  
rack

East drum  
accumulation  
area

MW-2S, 2D

fuel  
tank

cement  
plant

sand  
blast  
area

East Drums West 7/17/07  
TPH 12.8  
East Drums Center 7/17/07  
Methylene Chloride 0.032  
TPH 11.3  
East Drums East 7/17/07  
Toluene 0.0004 I  
TPH 11.2  
East Drums South 8/7/07  
Acetone 0.0056 V  
Carbon Disulfide 0.0006 I  
Methylene Chloride 0.011 I  
Toluene 0.0009 I  
TPH 14.5  
East Drums North 8/7/07  
Acetone 0.0054 IV  
Carbon Disulfide 0.0004 I  
Methylene Chloride 0.0055 V  
Toluene 0.0005 I  
TPH 23

truck  
maintenance

electric  
shop

Tank Shop and Office

RW-5

RW-2R  
MW-1I

MW-9S

MW-RW-3

production  
well

RW-3R

MW-11S

former  
tire  
shop

RW-4

RW-1

Drainage  
pipe

Drum 76

Geovac  
Environmental Services

0 200



Feet



Organic Results, Soil  
Terminal Services Co.  
2778 W. Tharpe St.