

Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

	WELL # & NAME		WELL TYPE		0	OG/PA NUMBER		[DATE INSPECTED					
	9-	4	ST. F	REGIS PAPER	co.	PROD	UCER	OG_	479	309840		3/24/20	20	
	OPERATOR			FIE	LD		COUNTY API NUMBER			MBER				
BREITBURN OPERATING, L.P.					JAY SAN			NTA ROSA	09-113-20015					
						WELL STATUS				LAST MIT P F				
						IN (TEMPORARILY)					2,	/6/2019	✓	
WELL SITE INSPECTION CHECKBOINTS						YES	NO				OTES			
WELL SITE INSPECTION CHECKPOINTS LEGIBLE WELL SIGN POSTED						<u>1 L S</u> ✓	NO			•	TOTES			
PAD HOUSEKEEPING SUFFICIENT						~								
PERIMETER BERM/DIKE SUFFICIENT						~								
FLOWLINE/PIPELINE ACCESIBLE/CLEAN						~								
EVIDENCE OF LEAKS/SPILLS ON							>							
PAD/LOCATION							_							
<u>WELLHEADS</u>						YES	NO				OTES			
PRESSURE GAUGES IN WORKING CONDITION						~								
TUB	ING	ANNU	LAR	SURFACE										
NA 0 0				~		TSI								
HIGH/L	OW FLC	WLINE	SHUT	N SENSORS										
LOCAT	ED NEA		ſ		Ī	>								
HIGH: 900 LOW: 0														
CELLAR CONDITION SATISFACTORY						>								
WELLHEAD LEAKING							~							
	HVDDC	CENC	יוון בור	E DETECTION	NI CV	CTEM								
HYDROGEN SULFIDE DETECTION SYS						YES	NO			1	OTES			
IF YES, FILL OUT DETECTION SYSTEM REQUIRED						I E S	NO							
ENTRY ALARMS IN WORKING CONDITION						· ·								
SENSORS IN WORKING CONDITION						· ·								
OLINOO	110 111 11	OKKRII	0 00111	DITION		·								
CHEMICAL ADDITIVE SYSTEM					YES	NO			N	OTES				
SYSTEM PRESENT						~								
SYSTEM LEAKING										N/A				
SECONDARY CONTAINMENT PROVIDED										N/A				
CHEMICALS ON LOCATION						1.)								
						2.)								
						3.)								



Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

H2S DETECTION SYSTEM IN PLACE.

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Permit Number	479		
Oculus ID	OG_479	Current Status	PROD
API Number	0911320015	Historical Status	PRODUCER
PA Number	309840	TVD	15,867
Well Name	SRPC #9-4	MD	15,867
Operator	BREITBURN OPERATING LP	Conductor Casing	16" @ 80'
Field	JAY	Surface Casing	10-3/4"@ 3676'
County	SANTA ROSA	Intermediate Casing	NA
Sec/Twp/Range	4S9 5N 29W	Production Casing	7" @ 15867'
SHL	1237'FSL&1643'FEL	Tubing	3-1/2"@ 15434
BHL	SAME	Perforations	15507-15593
Latitude	30.95709412	Plugs	
Longitude	-87.17580971	Issue Date	3/23/1971
		Spud Date	4/9/1971
		Completion Date	1/28/1972
		Plug Date	



WELL SIGN

WELL & PAD

I inspected the above well & premise on March 24, 2020

Signed

OIL AND GAS COORDINATOR

cc: [X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1