

Florida Department of Environmental Protection Hazardous Waste Inspection Report

FACILITY INFORMATION:

Facility Name: Safety-Kleen Sy	stems Inc			
On-Site Inspection Start Date:	03/17/2009	On-Site Ins	pection End Date:	03/17/2009
ME ID#: 48680		EPA ID#:	FLD984167791	
Facility Street Address: 5610 Alpha Dr, Boynton Beach, Florida 33426-8329				
Contact Mailing Address: 5610 Alpha Dr, Boynton Beach, Florida 33426-8329				
County Name: Palm Beach		Contact Ph	one: (561) 523-4	719

NOTIFIED AS:

LQG (>1000 kg/month) Transporter Transfer Facility TSD Facility Unit Type(s) Used Oil

INSPECTION TYPE:

Routine Inspection for LQG (>1000 kg/month) facility Routine Inspection for Hazardous Waste Transporter facility Routine Inspection for Used Oil Transporter facility Routine Inspection for Universal Waste Transporter facility Routine Inspection for Used Oil Generator facility Routine Inspection for TSD Facility Unit Type(s) Routine Inspection for Hazardous Waste Transfer Facility Routine Inspection for Used Oil Transfer Facility

INSPECTION PARTICIPANTS:

Principal Inspector:Kathy R Winston, InspectorOther Participants:Ron Burkett, Branch Manager

LATITUDE / LONGITUDE: Lat 26° 32' 24.766" / Long 80° 4' 51.4123"

SIC CODE: 4953 - Trans. & utilities - refuse systems

TYPE OF OWNERSHIP: Private

Introduction:

Safety Kleen - Boynton Beach (SK - BB) has been in operation at this location since 1991 and on November 19, 1997 received a Department permit (HO50-287405) to operate a Hazardous Waste Storage Facility. Situated in an industrial park, the facility is approximately five acres. The facility has 15 full time employees and is on city water and sewer. The facility has three 4000 gallon used oil collection trucks, a 4000 gallon vacuum truck, four 28 foot box trucks used for hazardous waste transport and their Fluid Recovery Services (FRS) program, and two vans for their sales people.

Process Description:

SK - BB sells and distributes raw solvents and collects spent solvent through a solvent leasing program with its customers. SK- BB also collects used oil, used oil filter, used antifreeze, waste paint related material, spent fluorescent bulbs and FRS waste for recycling. The facility consists of a container storage area, aboveground storage tank area, and a return/fill area.

Summary of Potential Violations and Areas of Concern:

Potential Violations

No Violations

Areas of Concern

No Areas of Concern

Conclusion:

Based on this inspection, SK - BB will generate greater than 1000 kilograms of hazardous waste per month, which would classify them as a Large Quantity Generator (LQG). The facility was in compliance at the time of the inspection.

Safety-Kleen Systems Inc Inspection Report

Inspection Date: 03/17/2009

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62 -740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Kathy R Winston	Inspector			
PRINCIPAL INSPECTOR NAME	PRINCIPAL INSPECTOR TITLE			
Kath		3/16/2009		
PRINCIPAL INSPECTOR SIGNATURE		DATE		
Ron Burkett	Branch Manager			
REPRESENTATIVE NAME	REPRESENTATIVE TITLE			
Z-Burlis		0.47/0000		
	Safety Kleen	3/17/2009		
REPRESENTATIVE SIGNATURE	ORGANIZATION	DATE		
Report Approvers:				
Joe Lurix	Environmental Manager			
SUPERVISOR NAME	SUPERVISOR TITLE			
NO SIGNATURE	FDEP			
SUPERVISOR SIGNATURE	ORGANIZATION			

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.