



October 8, 2009

Ms. Kathy Winston
Florida Department of Environmental Protection
Southeast District
400 N. Congress Ave., Suite 200
West Palm Beach, FL 33401

12:11 Delivered
RECEIVED
OCT 13 2009
DEPT of ENV PROTECTION
WEST PALM BEACH

RE: Hazardous Waste Inspection Report 8/27/09, Safety-Kleen Systems, Inc., 8755 NW 95th St., Medley, FL 33178. EPA ID number FLD984171694.

Dear Ms. Winston:

I am in receipt of the above referenced inspection report at Safety-Kleen's Medley branch service center. Please accept this letter in response to items listed on the report as new potential violations and areas of concern.

1. FDEP Area of Concern 262.34(a)(3) – Several containers had hazardous waste stickers over used oil stickers; containers should only have hazardous waste stickers. Please provide sign in sheet showing all employees have been advised. *SK response – enclosed please find a sign in sheet for proper hazardous waste container labeling training attended by all SK Medley employees.*
2. FDEP Area of Concern 262.34(c)(2) – There was a branch debris waste satellite drum that had an accumulation start date. *SK response – All material handlers have been informed that satellite containers are not to be dated until they are full and ready to be moved into the container storage area.*
3. FDEP Violation 263.12 – A drum from the generator Miami Marine Specialist was dated 8/13/09 on the facility acceptance records, as well as, on the drum itself. Please provide an explanation of why this drum dated 8/13/09 was over the ten day transfer facility allowable limit. *SK response – Enclosed please find a copy of the facility acceptance document and drum label. This waste stream, Immersion Cleaner, is a permitted waste stream that terminates at the SK Medley facility. Although the label is dated in the wrong area the waste drum is permitted to be stored at the facility up to one year.*
4. FDEP Violation 62-730.160(6) – Facility's container inspection log does not include legible printed name of the inspector and the total number of hazardous waste containers. Please create a container inspection log that includes the legible printed name of the inspector and the total number of waste drums. Fill out the log for three weeks and provide a copy to the Department. *SK response – Enclosed please find container inspection logs for three weeks with the legible inspectors printed name.*

SAFETY-KLEEN CORP.


5610 ALPHA DRIVE BOYNTON BEACH, FL 33426



5. FDEP Violation 62-710.510(1) – Information for the facility's acceptance and delivery logs were located on several different documents. *SK response – Enclosed please find the Medley operating log for oil acceptance and delivery.*

Thank you for the Department's time in this matter. If you have any questions or need additional information please contact me at (561) 523-4719.

Best regards,

A handwritten signature in black ink, appearing to read 'Jeff Curtis', followed by a long horizontal line extending to the right.

Jeff Curtis
EHS Manager
Safety-Kleen Systems, Inc.
5610 Alpha Drive
Boynton Beach, FL 33426
jeff.curtis@safety-kleen.com

SAFETY-KLEEN SYSTEMS

TRAINING ATTENDANCE / CERTIFICATION SHEET



* Only one
HAZ Waste Label
on each HAZ Waste
Drum

Date: 10-8-09Training Location: MedleyCourse Name: Proper HAZ Waste Labeling Event/Class Number: _____Course Code: _____ Time: 3:30 to 4:00 pm Duration: 1:50 hrs

	PRINTED NAME	SIGNATURE	EMPLOYEE #	FACILITY (CITY, STATE)
1.	Vincent Howard		430358	MEDLEY
2.	Bokarra Adams			MEDLEY
3.	Jorge R. S.		24978	MEDLEY
4.	Lazaro Mender		29091	Medley
5.	GERARDO TOMES		434167	U I
6.	Yaniel Diaz		434062	U I
7.	Robert Adams		28940	MEDLEY
8.				
9.				
10.				
11.				
12.				
13.				
14.				
15.				
16.				
17.				
18.				
19.				
20.				
21.				
22.				
23.				
24.				
25.				

I certify that the above listed employees have satisfactorily passed associated tests and, demonstrated satisfactory performance and comprehension of this training..

Trainer: _____

(Please Print Name)

Trainer's Signature:

Trainer's Location: Bonita Beach, FL

Trainer: _____

(Please Print Name)

Trainer's Signature: _____

Trainer's Location: _____

WASTE CORROSIVE LIQUID, BASIC, ORGANIC, NOS
(MONOETHANOLAMINE) 8 UN3267 PG1111(D006,
D018, D027, D039, D040) (ERG153) 7. 9#/9
D006, D018, D027, D039, D040

** TOXIC **

LIQUID

HAZARDOUS WASTE

FEDERAL LAW PROHIBITS IMPROPER DISPOSAL
IF FOUND, CONTACT THE NEAREST POLICE, OR
PUBLIC SAFETY AUTHORITY, OR THE U.S.
ENVIRONMENTAL PROTECTION AGENCY.

IN EVENT OF EMERGENCY CALL
1-800-468-1760 (24 HOURS)

GENERATOR INFORMATION:

ACCOUNT NO. 0000-1400-42
NAME MIAMI MARINE SPECIALISTS
ADDRESS 1950 NE 135 ST
CITY/STATE MIAMI FL 33181
USA EPA ID NO. STATE EPA ID NO.

ACCUMULATION
START DATE

MANIFEST
DOCUMENT NO.

39694572

GENERATOR
STORAGE DATE

TRANSFER
START DATE

8-13-09

TSDF
STORAGE DATE

CONTAINER NO.

090812002175

USE LABEL BY

09/12/10

DTC: RIC

SK DDT # 001495



PART NO. 81515 (7/97)

5400 Legacy Dr.
Cluster II, Building 3
Plano, Texas 75024
305 884-0123

REFERENCE
0039694572
SRVC WEEK: 09-33
SRVC DATE: 08/13/09 09
FI: 33181

TAX EXEMPTION NBR:

PRODUCT/SERVICES

SERVICE/ PRODUCT		QTY	UNIT PRICE	TAX	TOTAL CHARGE
	30300 MODEL 30 W/105 RECYCLED	1	155.0000	10.85	165.85
S/N	7001925 TAG 00001140SK07001925	CLEAN 15	SPENT 10		
	SERVICE TERM 12				
	11100 IMMERSION CLEANER W/PWH HEA	1	210.0800	14.71	224.79
S/N	49737 TAG T0000000XX90146919	CLEAN 6	SPENT 5		
	SERVICE TERM 12				
	100001 FEE, FUEL SURCHARGE	1	10.5000	0.74	11.24
	TOTAL SERVICE/PRODUCTS		375.5800	26.30	401.88

USEPA TRANSPORTER 1 TXR000050930
USEPA TRANSPORTER 2
FORM CODE DP

GENERATOR USEPA
GENERATOR STATE

US DOT DESCRIPTION (INCLUDING PROPER SHIPPING NAME, HAZARD CLASS, AND ID)			
WASTE COMBUSTIBLE LIQUID, N.O.S. (PETROLEUM NAPHTHA) NA1993 PGIII RQ (0001)			
0018,0039,0040 ERG#128			
TOTAL CONT 1	TYPE DM	TTL QTY 10	UNIT WT/VOL G SKDOT
CNT# 90812002176	QTY 10		

UNIT WT/VOL G SKDOT 801

WASTE CORROSIVE LIQUID, BASIC, ORGANIC,
N.O.S. (MONOETHANOLAMINE)
8 UN3267 PGIII
(D006, D018, D027, D039, D040 (ERG153))
TOTAL CONT 1 TYPE DM TTL
CNT# 90812002175 QTY: 5

UNIT WT/VOL G SKDOT 14950

DESIGNATED FACILITY NAME/ADDRESS:
SAFETY-KLEEN SYSTEMS, INC.
8755 NORTHWEST 95TH ST
MEDLEY.

FL 33178

USEPA ID NO FLD984171694
STATE ID NO

TOTAL CHARGE
WASTE MIN

TOTAL DUE

401.85

5.01

401.8

UNPAID BALANCE THIS RECEIPT

401.88

Machine clean and good condition? Yes
Decals in place and legible? Yes
Fusible link installed? Yes
Emergency closing of lid unobstructed? Yes
Machine properly grounded? Yes
Spent solvent meets acceptance criteria? Yes

GENERATOR STATUS
0 - 220 lbs/month

Customer certifies that (i) the above-named materials are properly classified, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and (ii) no material change has occurred either in the characteristics of the waste/material or in the process generating the waste/material. Customer agrees to pay the above charges and to be bound by the terms and conditions (1) set forth in (a) the General Terms and Conditions provided separately to Customer or (b) any SK agreement signed by Customer and SK, and (2) incorporated herein by reference. Unless otherwise indicated in the payment received section, SK is authorized to charge Customer's account for this transaction. Customer certifies that the individual signing this Service Acknowledgement is duly authorized to sign and bind Customer. The following provision is applicable to Safety-Kleen's parts cleaner and paint gun cleaner services: Customer agrees that it will not introduce any substance into the solvent or aqueous cleaning solution, including without limitation any hazardous waste or hazardous waste constituent, except to the extent such introduction is incidental to the normal use of the machine. Customer further agrees that it will not clean parts/paint guns that have been contaminated with or otherwise introduce polychlorinated biphenyls (PCB's), herbicides, pesticides, dioxins or listed hazardous waste into the solvent or aqueous cleaning solution. IN THE EVENT OF AN EMERGENCY CALL 1-800-468-1760 (24 hours)

// www.safety-kleen.com //

Requested Service / Notes:

Product #

##

N INVOICES/PAST DUE AMOUNTS:

Order taken by:

INSPECTION LOG SHEET FOR: Medley Figure 8.4-1

Daily Inspection of CONTAINER STORAGE AREA

PERMITTED STORAGE VOLUME: 6912 Gallons

Inspector's Name/Title: Vakeith Howard / WAREHOUSEInspector's Signature: Vakeith Howard

Monday	Tuesday	Wednesday	Thursday	Friday
	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>
Date: <u>9/8/09</u>	Date: <u>9/8/09</u>	Date: <u>9/9/09</u>	Date: <u>9/10/09</u>	Date: <u>9/11/09</u>
Time: <u>9:30</u>	Time: <u>9:30</u>	Time: <u>9:30</u>	Time: <u>10:30</u>	Time: <u>10:00</u>

****Date of Oldest 10-day Container and Container # 1

Containers	Monday	Tuesday	Wednesday	Thursday	Friday
Branch Generated - 16 gallon		0	0	0	0
Branch Generated - 30 gallon		0	0	0	0
Branch Generated - 55 gallon		3/165	4/220	4/220	1/55
Immersion Cleaner		4/48	4/48	4/48	4/48
Lacquer Thinner - 5 gallon		1/5	1/5	3/15	3/15
Paint Waste - 16 gallon		0	0	3/48	0
Paint Waste - 30 gallon		0	0	0	0
Paint Waste - 55 gallon		1/55	1/55	1/55	0
Perc filters - split 30 WATER		0	0	2/32	0
Perc filters - 16 gallons		0	0	2/32	0
Perc Sludge		0	0	0	1/16
FRS - 5 gallon (i.e. absorbent)		0	0	0	0
FRS - 16 gallon (i.e. absorbent)		0	0	0	0
FRS - 30 gallon		4/120	4/120	4/120	4/120
FRS - 55 gallon		29/1595	30/1650	31/1705	15/825
FRS - 85 gallon		0	0	0	1/85
Photo Waste - 5 gallon		0	0	0	0
Photo Waste - 16 gallon		0	0	0	0
Photo Waste - 30 gallon		0	0	0	0
Photo Waste - 55 gallon		0	0	0	0
Total Volume (gallons)		1988	2098	2275	1164
Waste Film (pounds)		0	0	0	0
Fluorescent bulbs (boxes)		1	27	27	27
Used Oil filters		39	42	42	42

Container Storage Area (Continued) Figure 8.4-1

Item	Monday	Tuesday	Wednesday	Thursday	Friday
Condition of Containers	A N	A N	A N	A N	A N
If "N", circle appropriate problem: missing or loose lids, missing, incorrect or incomplete labels, rust, leaks, distortion, other:					
Stacking / Placement / Aisle Space	A N	A N	A N	A N	A N
If "N", circle appropriate problem: different from Part B Floor Plan, containers not on pallets, unstable stacks, broken or damaged pallets, other:					

Containment

Item	Monday	Tuesday	Wednesday	Thursday	Friday
Curbing, Floor and Sump(s)	A N	A N	A N	A N	A N
If "N", circle appropriate problem: ponding/wet spots, deterioration (cracks, gaps, etc.), displacement, leaks, inadequate sealant, other:					
Loading / Unloading Area	A N	A N	A N	A N	A N
If "N", circle appropriate problem: cracks, deterioration, ponding/wet spots, other:					

(If an item is not applicable, enter N/A after it and draw a line through the acceptable/not acceptable row)

OBSERVATIONS, COMMENTS, DATE AND NATURE OF REPAIRS OF ANY ITEMS INDICATED AS "NOT" ACCEPTABLE:

*When calculating total volume, assume the containers are full.

**Enter a short description of the waste (e.g., M.S., I.C., paint, etc.)

A = Acceptable N = Not Acceptable

INSPECTION LOG SHEET FOR: Medley Figure 8.4-1

Daily Inspection of CONTAINER STORAGE AREA

PERMITTED STORAGE VOLUME: 6912 Gallons

Inspector's Name/Title: Vakeith Howard WarehouseInspector's Signature: VH

Monday	Tuesday	Wednesday	Thursday	Friday
<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>
Date: <u>9/14/09</u>	Date: <u>9/15/09</u>	Date: <u>9/16/09</u>	Date: <u>9/17/09</u>	Date: <u>9/18/09</u>
Time: <u>10:00</u>	Time: <u>10:00</u>	Time: <u>10:00</u>	Time: <u>10:00</u>	Time: <u>10:00</u>

*****Date of Oldest 10-day Container and Container #

1

Containers	Monday	Tuesday	Wednesday	Thursday	Friday
Branch Generated - 16 gallon	0	0	0	0	0
Branch Generated - 30 gallon	0	0	0	0	0
Branch Generated - 55 gallon	2/110	3/165	3/165	3/165	2/110
Immersion Cleaner	4/64	4/64	4/64	4/64	3/48
Lacquer Thinner - 5 gallon	5/25	5/25	5/25	5/25	2/10
Paint Waste - 16 gallon	0	0	0	0	1/16
Paint Waste - 30 gallon	0	0	0	1/30	1/30
Paint Waste - 55 gallon	3/165	3/165	4/220	7/385	3/165
Perc filters - split 30 WATER	0	0	0	1/16	1/16
Perc filters - 16 gallons	2/32	2/32	2/32	2/32	2/32
Perc Sludge	2/32	5/80	5/80	5/80	0
FRS - 5 gallon (i.e. absorbent)	0	0	0	0	0
FRS - 16 gallon (i.e. absorbent)	0	0	2/32	3/48	0
FRS - 30 gallon	9/270	11/330	11/330	11/330	2/80 2/60
FRS - 55 gallon	19/1045	20/1100	43/2365	43/2365	23/1265
FRS - 85 gallon	1/85	1/85	1/85	1/85	0
Photo Waste - 5 gallon	0	0	0	0	0
Photo Waste - 16 gallon	0	0	0	0	0
Photo Waste - 30 gallon	0	0	0	0	0
Photo Waste - 55 gallon	0	0	0	0	0
Total Volume (gallons)	1828	2046	3398	3625	1752
Waste Film (pounds)	0	0	0	0	0
Fluorescent bulbs (boxes)	145	145	145	145	0
Used Oil filters	49	54	60	35	35

Container Storage Area (Continued) Figure 8.4-1

Item	Monday	Tuesday	Wednesday	Thursday	Friday
Condition of Containers	(A) N	(A) N	(A) N	(A) N	(A) N
If "N", circle appropriate problem: missing or loose lids, missing, incorrect or incomplete labels, rust, leaks, distortion, other:					
Stacking / Placement / Aisle Space	(A) N	(A) N	(A) N	(A) N	(A) N
If "N", circle appropriate problem: different from Part B Floor Plan, containers not on pallets, unstable stacks, broken or damaged pallets, other:					

Containment

Item	Monday	Tuesday	Wednesday	Thursday	Friday
Curbing, Floor and Sump(s)	(A) N	(A) N	(A) N	(A) N	(A) N
If "N", circle appropriate problem: ponding/wet spots, deterioration (cracks, gaps, etc.), displacement, leaks, inadequate sealant, other:					
Loading / Unloading Area	(A) N	(A) N	(A) N	(A) N	(A) N
If "N", circle appropriate problem: cracks, deterioration, ponding/wet spots, other:					

(If an item is not applicable, enter N/A after it and draw a line through the acceptable/not acceptable row)
 OBSERVATIONS, COMMENTS, DATE AND NATURE OF REPAIRS OF ANY ITEMS INDICATED AS
 "NOT" ACCEPTABLE: _____

*When calculating total volume, assume the containers are full.

**Enter a short description of the waste (e.g., M.S., I.C., paint, etc.) _____

A = Acceptable N = Not Acceptable

INSPECTION LOG SHEET FOR: Medley Figure 8.4-1

Daily Inspection of CONTAINER STORAGE AREA

PERMITTED STORAGE VOLUME: 6912 Gallons

Inspector's Name/Title: WarehouseInspector's Signature: Vakeith Howard

Monday	Tuesday	Wednesday	Thursday	Friday
<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>	<u>Vakeith Howard</u>
Date: <u>9/21/09</u>	Date: <u>9/22/09</u>	Date: <u>9/23/09</u>	Date: <u>9/24/09</u>	Date: <u>9/25/09</u>
Time: <u>10:00</u>	Time: <u>10:00</u>	Time: <u>10:00</u>	Time: <u>10:00</u>	Time: <u>9:00</u>

****Date of Oldest 10-day Container and Container # 1

Containers	Monday	Tuesday	Wednesday	Thursday	Friday
Branch Generated – 16 gallon	0	0	0	0	0
Branch Generated – 30 gallon	0	0	0	0	0
Branch Generated – 55 gallon	2/110	2/110	2/110	2/110	2/110
Immersion Cleaner	5/80	4/64	4/64	5/80	1/16
Lacquer Thinner – 5 gallon	2/10	0	0	0	0
Paint Waste – 16 gallon	1/16	0	0	0	0
Paint Waste – 30 gallon	1/30	1/30	1/30	1/30	0
Paint Waste – 55 gallon	3/165	3/165	3/165	4/220	4/55
Perc filters – split 30 <u>WATER</u>	1/16	1/16	1/16	1/16	0
Perc filters – 16 gallons	0	2/32	2/32	2/32	0
Perc Sludge	2/32	4/64	4/64	4/64	0
FRS – 5 gallon (i.e. absorbent)	0	1/5	1/5	1/5	0
FRS – 16 gallon (i.e. absorbent)	0	0	1/16	1/16	0
FRS – 30 gallon	6/180	149/4470	149/4470	149/4470	159/4770
FRS – 55 gallon	46/2530	46/2530	53/1590	57/3135	30/1650
FRS – 85 gallon	0	0	0	0	0
Photo Waste – 5 gallon	0	0	0	0	0
Photo Waste – 16 gallon	0	0	0	0	0
Photo Waste – 30 gallon	0	0	0	0	0
Photo Waste – 55 gallon	0	0	0	0	0
Total Volume (gallons)	3/69	7486	6562	878	6601
Waste Film (pounds)	0	0	0	0	0
Fluorescent bulbs (boxes)	19	19	19	19	19
Used Oil filters	41	43	43	13	15

Container Storage Area (Continued) Figure 8.4-1

Item	Monday	Tuesday	Wednesday	Thursday	Friday
Condition of Containers	☒ N	☒ N	☒ N	☒ N	☒ N
If "N", circle appropriate problem: missing or loose lids, missing, incorrect or incomplete labels, rust, leaks, distortion, other:					
Stacking / Placement / Aisle Space	☒ N	☒ N	☒ N	☒ N	☒ N
If "N", circle appropriate problem: different from Part B Floor Plan, containers not on pallets, unstable stacks, broken or damaged pallets, other:					

Containment

Item	Monday	Tuesday	Wednesday	Thursday	Friday
Curbing, Floor and Sump(s)	☒ N	☒ N	☒ N	☒ N	☒ N
If "N", circle appropriate problem: ponding/wet spots, deterioration (cracks, gaps, etc.), displacement, leaks, inadequate sealant, other:					
Loading / Unloading Area	☒ N	☒ N	☒ N	☒ N	☒ N
If "N", circle appropriate problem: cracks, deterioration, ponding/wet spots, other:					

(If an item is not applicable, enter N/A after it and draw a line through the acceptable/not acceptable row)
OBSERVATIONS, COMMENTS, DATE AND NATURE OF REPAIRS OF ANY ITEMS INDICATED AS "NOT" ACCEPTABLE: _____

*When calculating total volume, assume the containers are full.

**Enter a short description of the waste (e.g., M.S., I.C., paint, etc.) _____

A = Acceptable N = Not Acceptable

309702 MEDLEY FL (MIAMI)		SAFETY-KLEEN CORP.	
OILTANK OIL TANK		FACILITY OPERATING LOG	
HANDLING CODE: S02		PERIOD 09 TO DATE	
DATE	CONTAINER#	GENERATOR	INBOUND
RECD	COMMENTS	NUMBER	MANIFEST
=====			
* SK/DOT 0000850 USED OIL		(NOT USDOT HAZARDOUS MA	
+	090812006404 SAFETY-KLEEN SYSTEMS, INC.	FLD984171694	
+	090812006414 SAFETY-KLEEN SYSTEMS, INC.	FLD984171694	
+	090812006417 SAFETY-KLEEN SYSTEMS, INC.	FLD984171694	
+	090813006848 SAFETY-KLEEN SYSTEMS, INC.	FLD984171694	
+	090813006881 SAFETY-KLEEN SYSTEMS, INC.	FLD984171694	
+081009	090228018981 THE COLLECTION	0000139996	0039522967
+081009	081018021733 ALL STAR MOTOR SERVICE	0000771362	M005891513
+081009	081108020334 GOODYEAR 2556	0000857856	0039522976
+081009	081115022220 GOODYEAR 6671	0000857859	0039429861
+081009	090411018917 SEARS A/C 06915	0001901219	0039522981
+081009	090718016601 AUTOZONE # 2485	0002322346	0039522995
+081009	081129022423 WILLIAMSON CADILLAC CO.	0002793104	0039476857
+081009	090502018497 BILL USSERY MOTORS	0002797166	0039476858
+081009	080925002370 OCEAN COLLISION CENTER	0003141534	P002129613
+081009	090801017880 FIRESTONE 014400	0003149443	0039523022
+081009	090718016593 ADVANCE AUTO # 9413	0003159500	0039523026
+081009	090806007706 HI TECH TRANS	0003303386	M005906888
+081009	090131018976 RYDER T/S 0146	0009497793	M005920918
+081009	090620017747 AUTOZONE # 1217	0009506579	0039523031
+081009	090425017934 AUTOZONE # 1245	0009506580	0039523032
+081009	090704018357 ADVANCE AUTO # 9358	0009506614	0039523044
+081009	090117020115 ADVANCE AUTO # 9376	0009506640	0039523056
+081109	090801017852 US FOUNDRY & MFG CORP	0000139729	0039522966
+081109	090704018437 SOUTH MOTORS BMW	0000771227	0039522970
+081109	090307022060 TIRE KINGDOM # 92	0000771383	0039476822
+081109	090627018299 ONE WAY TRUCK REPAIR	0000771393	0039522972
+081109	090321019280 GRAND PRIZE MOTORS	0001935545	0039522984
+081109	090808018409 ALAMO RENT A CAR	0001935850	M005920333
+081109	090207020457 KIA OF KENDALL 3174	0001974621	0039522986
+081109	090801017902 SOUTH MOTOR INFINITI 003071	0002128515	0039522992
+081109	090606018085 SOUTH MOTOR HONDA 003279	0002605410	0039522999
+081109	090718016655 AUTOZONE # 1284	0002704046	0039523001
+081109	090718016598 AUTOZONE # 1070	0002738961	0039523003
+081109	090411018873 JMG & SONS, CORP. (DBA CABRERA	0003129749	0039691706
+081109	090718016665 REPUBLIC SERVICES INC	0003340870	0039523028
+081109	090718016666 REPUBLIC SERVICES INC	0003340873	0039523029
+081109	090131019018 ADVANCE AUTO # 9492	0009506598	0039523037
+081109	090418018891 ADVANCE AUTO # 9382	0009506624	0039476906
+081109	090214019860 ADVANCE AUTO # 9386	0009506639	0039523051
+081209	080830023576 GOODYEAR 6648	0000139238	M005925435
+081209	090509018718 TIRE KINGDOM # 68	0000771255	0039522971
+081209	090328019070 HEADQUARTER TOYOTA	0000771410	0039522974
+081209	090801017861 TIRE KINGDOM # 148	0001813956	0039522979
+081209	080809025378 HERTZ RAC 1301-15	0001933202	M005925434
+081209	090523017753 TIRES PLUS #533521	0001989637	0039522987
+081209	090613019541 NICK EXXON AUTO CENTER	0002011350	0039522988
+081209	081004024681 TIRES PLUS #663921	0002302455	0039522994
+081209	090509018686 AUTOZONE # 1083	0002896529	0039523010
+081209	081227021312 DOLLAR THRIFTY	0003045700	M005925433
+081209	090620017778 FIRESTONE 004502	0003149449	0039523025
+081209	080906024326 CUMMINS SOUTHEASTERN POWER	0009506589	0039476895
+081209	080906024299 ADVANCE AUTO # 9258	0009506591	0039523033
+081209	090523017758 ADVANCE AUTO # 9418	0009506610	0039523042
+081209	090718016628 ADVANCE AUTO # 9419	0009506635	0039523050
+081309	080811006912 MD&P INVESTMENTS DBA TECH AUTO	0000139167	P002147585
+081309	090725017349 US FOUNDRY & MFG CORP	0000139729	M005928062
+081309	080816022818 TIRE KINGDOM # 76	0000771130	M005906893
+081309	080927022459 TIRE KINGDOM # 65	0000771398	M005928071
+081309	090718016674 TIRE KINGDOM # 83	0000771433	0039522975
+081309	080913022511 GOODYEAR 6651	0000857854	M005906894
+081309	090711018825 ALAMO RENT A CAR	0001935850	M005928064
+081309	090523017792 SEARS A/C 06636	0002499247	0039522997
+081309	090620017771 TIRE KINGDOM 246	0003036881	M005906891
+081309	090725017380 FIRESTONE 004499	0003149442	0039476875
+081309	090801017868 AAMCO TRANSMISSION	0003388636	M005906889

* THIS INFORMATION DESCRIBES THE CONTAINERS OF WASTE LISTED IMMEDIATELY BELOW THE

+ WASTE RECEIVED BY BRANCH AS NON-HAZARDOUS.

** THIS COLUMN INDICATES EITHER THE OUTBOUND LOCATION OR THE MOVEMENT TO A NEW ST