

Thomas, Richard

From: Thomas, Richard
Sent: Wednesday, May 18, 2016 11:34 AM
To: 'mike@streamlineenv.com'
Cc: 'Lawrence'; Marsh, Julia; Yerg, Cayla
Subject: Deliverable Review Letter

Mr. Michael Roose
Streamline Environmental, Inc.
1821 Sahlman Drive, Suite B
Tampa, Florida 33605

Subject: Task 2 Partial Deliverable Review
ABA Industries Inc
10260 US HWY 19 N
Pinellas Park, Pinellas County
FDEP Facility ID# 52/8520575
Discharge Dates: 09/08/1994 (ATRP)
Priority Score: 10
Purchase Order #: AE99D9, Task 2
Task Assignment #: GC775-026A

Dear Mr. Roose:

The Petroleum Restoration Program (PRP) has reviewed the Partial Supplemental Site Assessment Report dated and received electronically May 5, 2016, submitted for this facility. The Well Construction Log for DW-1 indicates that a 4" outer casing was installed opposed to the 6" outer casing outlined in the purchase order. Clarification as to how DW-1 was installed is needed prior to the report being approved. Please provide additional information by May 25, 2016.

During the review a few clerical issues were encountered. Please ensure the following edits are included when submitting the final Supplemental Site Assessment Report. The TRPH and Benzene results documented in Table 2 do not need to be bolded. The Toluene result for MW-1 in Figure 9 does not include an "I" qualifier which is documented in the laboratory analytical report. Additionally, the Benzene result for MW-4 and the 2-Methylnaphthalene result for MW-1 need to be bolded in Figure 9. If you should have any questions about the review, please contact me at (850) 222-6446, extension 306 or at the Bob Martinez Center, 2600 Blair Stone Road, Tallahassee, Florida 32399-2400, Mail Station 4585.

Richard Thomas
Staff Geologist



NorthStar Contracting Group, Inc.
508-A Capital Circle SE
Tallahassee, FL 32301
Office: (850)222-6446 *306
24 Hour Emergency Response: 800.283.2933

