



Florida Department of
Environmental Protection
Hazardous Waste Inspection Report

Draft

FACILITY INFORMATION:

Facility Name: Safety - Kleen Systems Inc

On-Site Inspection Start Date: 10/14/2010

On-Site Inspection End Date: 10/14/2010

ME ID#: 11672

EPA ID#: FLD984171694

Facility Street Address: 8755 NW 95th St, Medley, Florida 33178-1462

Contact Mailing Address: 3003 W Breezewood Lane, Neenah, Wisconsin 54957-0368

County Name: Miami-Dade

Contact Phone: (800) 558-5011

NOTIFIED AS:

LQG (>1000 kg/month)

Transporter

Transfer Facility

TSD Facility Unit Type(s)

Used Oil

INSPECTION TYPE:

Routine Inspection for LQG (>1000 kg/month) facility

Routine Inspection for Transporter facility

Routine Inspection for Transfer Facility

Routine Inspection for Used Oil Marketer facility

Routine Inspection for Used Oil Transporter facility

Routine Inspection for Used Oil Transfer Facility

Routine Inspection for TSD Facility Unit Type(s)

INSPECTION PARTICIPANTS:

Principal Inspector: Kathy R. Winston, Inspector

Other Participants: Ben Fisch, Environmental Specialist

LATITUDE / LONGITUDE: Lat 25° 51' 37.5641" / Long 80° 20' 25.4331"

SIC CODE: 4212 - Trans. & utilities - local trucking, without storage

TYPE OF OWNERSHIP: Private

New Potential Violations and Areas of Concern:

Transporters Checklist

Type: Area Of Concern

Rule: 265.171

Question Number: 1.720

Question: Are the containers in good condition? (check for leaks, corrosion, bulges, etc.)

Explanation: A shipment was being prepared at the time of the inspection; however, non-transfer facility waste was being stored in the designated transfer facility container storage area.

Corrective Action: Please be sure to only store transfer facility waste in your transfer facility area

Summary of Potential Violations and Areas of Concern:

Potential Violations

No Violations

Areas of Concern

Rule Number	Area	Date Cited	Explanation
Transporters Checklist 265.171		10/14/2010	A shipment was being prepared at the time of the inspection; however; non-transfer facility waste was being stored in the designated transfer facility container storage area.

Inspection Date: 10/14/2010

Draft

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Kathy R. Winston

PRINCIPAL INSPECTOR NAME

Inspector

PRINCIPAL INSPECTOR TITLE**PRINCIPAL INSPECTOR SIGNATURE**

10/14/2010

DATE

Ben Fisch

INSPECTOR NAME

Environmental Specialist

INSPECTOR TITLE

NO SIGNATURE

INSPECTOR SIGNATURE

FDEP

ORGANIZATION

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.