



Florida Department of Environmental Protection

Northeast District
7825 Baymeadows Way, Suite B200
Jacksonville, Florida 32256

Rick Scott
Governor

Jennifer Carroll
Lt. Governor

Herschel T. Vinyard, Jr.
Secretary

January 25, 2011

SENT VIA EMAIL

alan.chandler@aagenvironmental.com

Mr. Alan Chandler, President
AAG Environmental
PO Box 959
Newberry, Florida 32669

**Re: AAG Environmental
EPA/DEP ID: FLR 000 167 635
Alachua County - Hazardous Waste**

Dear Mr. Chandler:

Thank you for your assistance during the hazardous waste compliance inspection conducted by the Florida Department of Environmental Protection at your facility on December 8, 2010. Enclosed is the report that documents this inspection.

Based on this inspection, your facility was found to be in violation of Florida Statutes and Rules concerning hazardous waste management. Subsequent to the inspection, your facility submitted information stating that the violations have been corrected. Since your facility has returned to compliance, no enforcement action will be taken.

Your continued cooperation is appreciated. If you have any questions regarding this report or hazardous waste regulation in general, please contact me at 904.256.1670.

Sincerely,

Pamela Fellabaum, CHMM
Environmental Specialist III
Hazardous Waste Section

Enclosure(s)



**Florida Department of
Environmental Protection
Hazardous Waste Inspection Report**

FACILITY INFORMATION:

Facility Name: AAG Environmental Inc

On-Site Inspection Start Date: 12/08/2010

On-Site Inspection End Date: 12/08/2010

ME ID#: 94605

EPA ID#: FLR000167635

Facility Street Address: 25370 NW 8th Ln, Newberry, Florida 32669-2538

Contact Mailing Address: PO Box 959, Newberry, Florida 32669-0959

County Name: Alachua

Contact Phone: (352) 472-7295

NOTIFIED AS:

Non-Handler

Transporter

INSPECTION TYPE:

Routine Inspection for Hazardous Waste Transporter facility

Routine Inspection for Universal Waste Transporter facility

Routine Inspection for CESQG (<100 kg/month) facility

INSPECTION PARTICIPANTS:

Principal Inspector: Pam Fellabaum, Inspector

Other Participants: Alan Chandler, President

LATITUDE / LONGITUDE: Lat 29° 39' 21.4128" / Long 82° 36' 35.6256"

SIC CODE: 4959 - Trans. & utilities - sanitary services, nec

TYPE OF OWNERSHIP: Private

Introduction:

AAG Environmental is a hazardous waste transporter and a hazardous material emergency response contractor. The facility is not a hazardous waste transfer facility. AAG Environmental has been issued EPA/DEP identification number FLR000167635 for this location. The facility was last inspected by the DEP on September 11, 2007, when it was located at 25145 NW 8th Place, Suite 10 (FLR000141259). This inspection was unannounced.

Process Description:

AAG Environmental routinely responds to and remediates hazardous material incidents and fuel spills. The facility may also transport non-hazardous waste. The facility has not transported any hazardous waste in approximately three years, but wishes to retain its hazardous waste transporter status. The facility has not removed waste from a methamphetamine laboratory since September 2008.

The facility does not operate a hazardous waste transfer facility, but it does have a shop area where equipment is stored and maintained. The facility's vehicles are taken off-site to private vendors for repair and maintenance. There were two non-empty aerosol cans in a trash container (Photo 1) [40 CFR 261.5(g)(3)]. Since the waste in the cans has a flash point below 140 degrees Fahrenheit, the waste is a D001 hazardous waste, at a minimum. The cans were removed from the trash container and placed into a 5-gallon bucket (Photo 2). When the bucket is full, the cans will be taken to the Alachua County Household Hazardous Waste collection facility.

Record Review:

Inspection Date: 12/08/2010

The facility has not transported any hazardous waste in at least three years, so no manifests were examined during this inspection. All other records required for hazardous waste transporters were reviewed and found to be in order. The facility does not generate any other hazardous waste, any used oil, or used oil filters since all vehicle work is performed off-site.

New Potential Violations and Areas of Concern:**Checklist Independent Potential Violations and Areas of Concern**

Type: Violation
Rule: 261.5(g)(3)
Explanation: Two non-empty aerosol cans were found in a trash container.
Corrective Action: No further action is necessary. During the inspection, the cans were placed into a closed, labeled bucket. When the bucket is full, it will be taken to the Alachua County HHW facility.

Summary of Potential Violations and Areas of Concern:Potential Violations

Rule Number	Area	Date Cited	Explanation
Checklist Independent Violations 261.5(g)(3)		12/08/2010	Two non-empty aerosol cans were found in a trash container.

Areas of Concern


No Areas of Concern

ATTACHMENTS:

Photo 1



Photo 2



Inspection Date: 12/08/2010

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Pam Fellabaum

PRINCIPAL INSPECTOR NAME

Inspector

PRINCIPAL INSPECTOR TITLE**PRINCIPAL INSPECTOR SIGNATURE**

FDEP

ORGANIZATION

1/25/2011

DATE

Alan Chandler

REPRESENTATIVE NAME

President

REPRESENTATIVE TITLE

NO SIGNATURE

REPRESENTATIVE SIGNATURE

AAG Environmental

ORGANIZATION**Report Approvers:**

Vicky Valade

SUPERVISOR NAME

Environmental Manager

SUPERVISOR TITLE**SUPERVISOR SIGNATURE**

FDEP

ORGANIZATION

1/25/2011

DATE

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.