

State of Florida
DEPARTMENT OF ENVIRONMENTAL REGULATION



Interoffice Memorandum

FOR ROUTING TO OTHER THAN THE ADDRESSEE

To: File 10-30 LOCTN: _____
To: _____ LOCTN: _____
To: _____ LOCTN: _____
FROM: _____ DATE: _____

TO: Don Trussell, Hazardous Waste Section, Tallahassee

THROUGH: Jerry Owen
Phil Coram *PC*
Vicky Valade *KV*

FROM: Jane W. Mears *JW*
Northeast District - Jacksonville

DATE: October 25, 1985

SUBJECT: M & W Southeastern
Hazardous Waste Inspection of October 21, 1985
Duval County - FLD non-handler

Attached is subject inspection report.

JWM:ddb

STATE OF FLORIDA
DEPARTMENT OF ENVIRONMENTAL REGULATION

NORTHEAST DISTRICT

3426 BILLS ROAD
JACKSONVILLE, FLORIDA 32207
(904) 396-6959



BOB GRAHAM
GOVERNOR
VICTORIA J. TSCHINKEL
SECRETARY
ERNEST E. FREY
DISTRICT MANAGER

October 25, 1985

Mr. Rick McPherson
M & W Southeastern
806 Talleyrand Avenue
Jacksonville, Florida 32206

Dear Mr. McPherson:

M & W Southeastern
Hazardous Waste Inspection of October 21, 1985
Duval County - FLD Non-handler

Pursuant to the October 21, 1985 Hazardous Waste Inspection, this office has determined that M & W Southeastern does not generate or handle hazardous waste.

Enclosed is a copy of the inspection report. If this office can be of any assistance in the future, please do not hesitate to contact us at the letterhead address or telephone number.

Sincerely,

Jane W. Mears
Environmental Specialist

JWM:ddb

Enclosures

STATE OF FLORIDA
DEPARTMENT OF ENVIRONMENTAL REGULATION

TWIN TOWERS OFFICE BUILDING
2600 BLAIR STONE ROAD
TALLAHASSEE, FLORIDA 32301-8241



BOB GRAHAM
GOVERNOR
VICTORIA J. TSCHINKEL
SECRETARY

HAZARDOUS WASTE INSPECTION REPORT

1. INSPECTION REPORT COMPLAINT X ROUTINE FOLLOW-UP PERMITTING
FACILITY NAME M & W Southeastern Inc. DER/EPA ID FL D Non-handler
ADDRESS 806 Talleyrand Avenue, Jacksonville, FL 32206
COUNTY Duval Phone (904) 355-1524 DATE 10-21-85 TIME 11:00

TYPE OF FACILITY:

Generator	Storage	Treatment
<u> </u> Small Quantity	<u> </u> Container	<u> </u> Tank
<u> </u> Generator	<u> </u> Tank	<u> </u> Land Treatment
	<u> </u> Waste Pile	<u> </u> Thermal
Transporter	<u> </u> Surface Impoundment	<u> </u> Chem/Phys/Bio.
<u> </u> Transporter		<u> </u> Incinerator
<u>X</u> Non-handler	Disposal	<u> </u> Surface Impoundment
	<u> </u> Landfill	
	<u> </u> Surface Impoundment	
	<u> </u> Waste Pile	

2. Applicable Regulations:

 40 CFR 262 40 CFR 263 40 CFR 264 40 CFR 265

3. Responsible Official: (Name & Title) Rick McPherson, President

4. Survey Participants & Principal Inspector

Rick McPherson, M & W
Jane W. Mears, FDER
Vicky Valade, FDER

5. Facility Latitude: 30°20'00" Longitude: 81°37'55"

6. Type of Ownership: FEDERAL STATE COUNTY MUNICIPAL PRIVATE

7. Permit Number: Date Issued: Expiration Date:

8. Prearranged inspection: X yes no

7. Discrepancies with Process Description; if different from previews report.

M & W Southeastern Inc., cleans petroleum storage tanks. Their number one priority is in pipeline construction and repairs. When the tanks are cleaned, the facility has the rinsewater analyzed for flammability, EP toxicity and lead. If it passes these tests, they receive a manifest from the city and take the rinsewater to the north landfill. If the rinsewater is a hazardous waste, M & W places it in drums, which are left on the customer's property. The customer is responsible for solidifying the material and disposing of it as a hazardous waste at an approved hazardous waste disposal facility.

When the facility was called M & W Industrial Coating, they had a separator, which was located on Adams Street. When the company was sold to M & W Southeastern, Conversion Technology Corporation bought the separator.

The facility had an EPA identification number because they were transporting hazardous waste at one time. They have since discontinued transporting and have notified Tallahassee as a non-handler.

No violations were found during this inspection.

8. List and explain noncompliance items.

NONE

1. EPA ID: NO HANDLER

2. H.W. PERMIT NO.					--				
--------------------	--	--	--	--	----	--	--	--	--

3. HANDLER NAME: M. W. Southeastern

4. ADDRESS: 806 TALLEYROAD AVENUE
JACKSONVILLE, FL 32206

5. RESPONSIBLE FACILITY OFFICIAL: Rick McPherson, President

6. COUNTY: Duval LAT/LONG: 30°30'00" / 81°39'55"

8. DATE OF INITIAL EVALUATION WHICH IS THE BASIS FOR THIS REPORT:

8a. AGENCY RESPONSIBLE FOR

EVALUATION:

Put *code in box

(*SEE Back of Form)

7. Handler Type: (Circle One)
Major Non-Major

7a. Type Facility: (Circle One)
Treat/Store/Dispose
Non-Handler
Transporter
Generator
Small Quan. Generator
Exempt

7b. Type Ownership: (Circle One)
Federal State
County Municipal
Private

8b. TYPE OF EVALUATION COVERED
BY THIS REPORT:
Put *code in box
Choose one

9. DATE OF EVALUATION COVERED BY THIS REPORT (enter only if different from 8): / /

10. AREA AND CLASS OF VIOLATION
(enter 'X' in appropriate box
if violations found. Enter
'0' if no violations found in
Area evaluated.)

Class of Violation

Area of Violation

GWM

01 / PC

Fin. Res.

Perm

+ [Comp] Sch

Manif

Other

I

II

11. ENFORCEMENT ACTIONS:

[illegible]

12. COMMENTS:

Principal Inspector