

Per the exit interview, Safety Kleen had two drums on a pallet in the warehouse that was not waste they remanifest; therefore, the drums should have been stored in the transfer facility area. The issue was discussed during the inspection and the drums were moved before the end of the inspection