



**Florida Department of
Environmental Protection
Hazardous Waste Inspection Report**

FACILITY INFORMATION:

Facility Name: Crowley Liner Services Inc

On-Site Inspection Start Date: 09/04/2012

On-Site Inspection End Date: 09/04/2012

ME ID#: 21129

EPA ID#: FL0000360560

Facility Street Address: 4300 McIntosh Rd, Fort Lauderdale, Florida 33316

Contact Mailing Address: 4300 McIntosh Road, Fort Lauderdale, Florida 33316

County Name: Broward

Contact Phone: (305) 470-4059

NOTIFIED AS:

CESQG (<100 kg/month)

Transporter

Transfer Facility

INSPECTION TYPE:

Routine Inspection for Transporter facility

Routine Inspection for Transfer Facility

Routine Inspection for SQG (100-1000 kg/month) facility

INSPECTION PARTICIPANTS:

Principal Inspector: Magdalena Gierczak, Inspector

Other Participants: Mark Kemp, Director, Maintenance & Repair; Jose Santiago, Materials Manager

LATITUDE / LONGITUDE: Lat 26° 4' 5.4186" / Long 80° 7' 19.456"

SIC CODE: 8999 - Services - services, nec

TYPE OF OWNERSHIP: Private

Introduction:

The facility is a seaport shipping and transfer facility. It has been in operation for over 20 years. It is located on 28 acres, employs about 150 people, and uses city utilities.

Facility was last inspected by the Department on 05/20/2010.

Process Description:

Facility performs maintenance on their own vehicles and generates the following waste streams:

- used oil - stored in AST; indoors; within secondary containment; managed by Cliff Berry
- used oil filters and solids - stored in four (4) 55-gal drums; indoors; managed by Cliff Berry
- spent antifreeze - - stored in AST, indoors; within secondary containment; managed by Cliff Berry
- parts washer mineral spirits wastes - 2 System One parts washers; managed by Safety Kleen

There are 2 underground fuel tanks holding gasoline and diesel.

There is an underground 3-unit water-oil separator. Each unit is about 2000 gal, all are maintained by Cliff Berry and waste is picked up on annual basis.

Transfer Facility:

Facility does not take wastes off/out of containers. They accept shipping containers, move them into the parking area and ship them off all without unloading.

Inspection Date: 09/04/2012

The facility recently expanded their facility by adding one lot south of main building. Transfer operations were moved to the newly acquired lot without notification of changes to the Department. No hazardous waste containers were stored in designated transfer area at time of inspection.

New Potential Violations and Areas of Concern:**Violations**

Type: Violation

Rule: 265.16(a)(1)

Explanation: HAZWOPER Training records for the following employees were not provide at time of inspection:
- Mark Kemp
- Jose Santiago
- Michael Lesser

Corrective Action: Please provide proof of HAZWOPER training completed within the last three (3) years for the above-mentioned employees.

Please provide proof of compliance within seven (7) days of receipt of final Inspection Report.

Type: Violation

Rule: 62-730.171(3)

Explanation: 62-730.171 (3)(b) A transporter who is operating a transfer facility must notify the Department prior to making changes in any of the items listed in paragraph 62-730.171(3)(a), F.A.C.

The facility recently expanded their facility by adding one lot south of main building. Transfer operations were moved to the newly acquired lot without notification of changes to the Department.

Corrective Action: Please file all required notification documentation with the Department within seven (7) days of receipt of the final inspection report.

Type: Violation

Rule: 62-710.850(5)(a)

Question Number: 5.140

Question: Are used oil filter containers labeled "Used Oil Filters"?

Explanation: Facility failed to properly label one used oil drum.

Corrective Action: Violation was corrected at time of inspection.

Photo Attachments:

Inspection Date: 09/04/2012

Corrected violation



Conclusion:

A hazardous waste compliance inspection was conducted on this date, to determine the facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspectors.

Inspection Date: 09/04/2012

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Magdalena Gierczak

PRINCIPAL INSPECTOR NAME

Inspector

PRINCIPAL INSPECTOR TITLE**PRINCIPAL INSPECTOR SIGNATURE**

9/21/2012

DATE**Supervisor:** Karen Kantor

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.