



Florida Department of
Environmental Protection
Hazardous Waste Inspection Report

FACILITY INFORMATION:

Facility Name: Veolia ES Technical Solutions LLC

On-Site Inspection Start Date: 10/16/2012

On-Site Inspection End Date: 10/16/2012

ME ID#: 62668

EPA ID#: FLR000124917

Facility Street Address: 4972 Woodville Hwy (South Lot), Tallahassee, Florida 32305-0903

Contact Mailing Address: 342 Marpan Ln, Tallahassee, Florida 32305-0904

County Name: Leon

Contact Phone: (850) 877-8299

NOTIFIED AS:

Non-Handler

INSPECTION TYPE:

Routine Inspection for Non-Handler facility

Routine Inspection for Transfer Facility

INSPECTION PARTICIPANTS:

Principal Inspector: Aaron Mitchell, Inspector

Other Participants: Javier Garcia, EPA Inspector; Linda Dunwoody, Operations Manager; Randy Williams, Supervisor

LATITUDE / LONGITUDE: Lat 30° 21' 45.5093" / Long 84° 15' 57.5033"

SIC CODE: 4789 - Trans. & utilities - transportation services, nec

TYPE OF OWNERSHIP: Private

Process Description:

The Veolia Transfer Yard (Veolia) is used for the storage of facility transport trailers and is a registered Universal Waste Transfer Area. Twelve trailers were inspected to ensure compliance with state and federal regulations. Four trailers were empty, one trailer was full of empty containers, and six others were full of universal and electronic waste. The storage times vary depending on the content of the trailers. Trailers that have universal waste stored on them are kept in the transfer yard for a maximum of ten days. On the tenth day or previous to that day, the universal waste is off-loaded at the main facility's docking area for processing. No trucks carrying universal waste was beyond its ten day storage time limit.

PHOTO ATTACHMENTS:

Inspection Date: 10/16/2012

Transfer Yard



Inside of a container truck



Conclusion:

No violations were observed during the inspection of the transfer yard.
The Veolia transfer yard appeared to be in compliance at the conclusion of the inspection.

Inspection Date: 10/16/2012

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Aaron Mitchell

PRINCIPAL INSPECTOR NAME

Inspector

PRINCIPAL INSPECTOR TITLE*Aaron Mitchell***PRINCIPAL INSPECTOR SIGNATURE**

FDEP

ORGANIZATION

11/21/2012

DATE**Supervisor:** James Byer

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.