

Petroleum Cleanup Site Inspection Form

INSTRUCTIONS: This form should be completed by FDEP Site Managers to document all site visits. System performance information is optional and should only be collected if access to the compound can be safely obtained from the contractor or site owner. A separate form should be used for each site and each site visit. A site map illustrating the monitor well locations and/or system layout should be included with this form.

Site Name:	Citgo-RPC #605	Inspector:	Mark Williams	
FAC ID No.:	8514511	Inspection Date:	07/18/13	Time: 10:00 AM
Location:	901 Belvedere Rd.	Site Manager:	David Gibson	
	West Palm Beach	Contractor Rep.(s):		
Contractor:	CB&I			
Others On-Site:				

Purpose of Inspection:

- ☐ Initial Site Visit/Walkover
☐ Task Observation Site Visit
☐ Initial System Inspection & Equipment Inventory (attach inventory form)
☐ Routine System Performance Inspection
☐ Sampling/Audit Inspection
☒ Other (specify) Check conditions of site

General Comments and/or Recommendations:

Site is PAC

Pictures of site included

CB&I has proposed new wells

Was contact made with the site owner or representative?

☒ Yes ☐ No

Comment

Task Observation:

☐ IRA

☐ CA

☐ RAC

☐ Other:

WO or TA #:

General Description (what is the activity to be observed):

8514511

7/18/2013

QUIK MART

901

OPEN

ICE

metroPCS
Authorized
Payment Center

Now Accepting
EBT cards



WESTERN
UNION
MONEY ORDERS

12 Pack
\$10.99

GRAB
SOME
BUDS 12 Pack
\$10.99





8514511
7/18/2013



8514511
7/18/2013

8514511
7/18/2013



8514511
7/18/2013

