

WORLD PETROLEUM CORPORATION

Petroleum Recovery, Used Oil & Environmental Services


RECEIVED
ENVIRONMENTAL PROTECTION

MAR 25 2014

PERMITTING & COMPLIANCE
ASSISTANCE PROGRAM

March 19, 2014

Florida Department of Environmental Protection
2600 Blair stone Road
Tallahassee, Florida 32399-2400
Bheem Kothur, P.E. III



RE: Tanks Final Inspection Report ; FACILITY ID: FLD 980 709 075

Dear Mr. Kothur,

Pursuant to your email March 7th, 2014 and our phone conversation please find attached the following.

- a. Tank #1 photo showing repairs and touch-up. **(Photo #1)**
- b. Tank #2 photo showing newly installed vent and grounding. **(Photos #2 & 3)**
- c. Tank #3 touch-up around the manway and shell (all bolts present). **(Photo #4)**
- d. Tank #8 level gauge, grounding and corrosion repairs. **(Photo #5)**
- e. Tank #9 grounding, missing bolt replaced on manway and corrosion repairs on shell. **(Photos #6 & 7)**
- f. Tank #10 grounding, corrosion repairs on shell and level indicator gauge. **(Photo #8)**
- g. Photo 9 shows grounding on tanks 5, 7 and 9
- h. Photo 10 shows grounding on tanks 2, 4, 6 and 10.

Please do not hesitate to call me at (954) 327-0724 if you have any further comments or questions.

Sincerely,

Philip Pierre-Louis
General Manager
World Petroleum Corp


①

1
USED OIL





3



4

3

USED OIL



3

8

OILY WATER

WATER



⑥


9
USED OIL



7

9

USED OIL





9

5 OIL
USED



