



**Florida Department of
Environmental Protection
Hazardous Waste Inspection Report**

FACILITY INFORMATION:

Facility Name: Veolia ES Technical Solutions LLC

On-Site Inspection Start Date: 12/17/2015

On-Site Inspection End Date: 12/17/2015

ME ID#: 62668

EPA ID#: FLR000124917

Facility Street Address: 4972 Woodville Hwy (South Lot), Tallahassee, Florida 32305-0903

Contact Mailing Address: 342 Marpan Ln, Tallahassee, Florida 32305-0904

County Name: Leon

Contact Phone: (850) 877-8299

NOTIFIED AS:

Non-Handler

INSPECTION TYPE:

Routine Inspection for Non-Handler facility

Routine Inspection for Transfer Facility

INSPECTION PARTICIPANTS:

Principal Inspector: Aaron Mitchell, Inspector

Other Participants: Jill Scarborough, Environmental Consultant; Matthew Melott, Operations Manager; Heather Perkins, Inspector; Raj Aiyar, Inspector; Randy Williams, Operations Supervisor

LATITUDE / LONGITUDE: Lat 30° 21' 45.5093" / Long 84° 15' 57.5033"

SIC CODE: 4953 - Trans. & utilities - refuse systems

TYPE OF OWNERSHIP: Private

Process Description:

The Veolia Transfer Yard (Veolia) is used for the storage of facility transport trailers and is a registered Universal Waste Transfer Area.

Fourteen trailers were randomly inspected to ensure compliance with state and federal regulations. Trailers 800401, 817421, and 622828 were empty. Trailers 484466, 889890, 889222, and 694756 contained inbound Universal Waste. The inbound materials were various batteries (NiCad, Li...etc.), universal waste lamps (HIDs and Fluorescent), mercury containing devices, and other universal wastes permitted to be processed at the facility. All containers were labeled, dated, and matched the transport documentation used by Veolia. Trailers 683536, 622832, 889985, 8000398, and 818134 contained outbound Universal Waste, post retort materials, (aluminum end caps and post-retort phosphor powder) and electronic waste. The Outbound universal waste shipments are sent to sister Veolia processing sites in Port Washington, Wisconsin and Phoenix, Arizona. All Outbound shipments were properly closed labeled and matched the facility shipping documentation. Trailer 8181358 was used for the storage of Georgia Power containers that were sent to the facility for the transport of their Universal Waste. Trailer 818133 was damaged and is being used for the storage of empty drums and containers used by Veolia to ship universal wastes.

No violations were observed at the time of the inspection.

Inspection Date: 12/17/2015

PHOTO ATTACHMENTS:

Universal Waste Transfer Area



Universal Waste on Trailer



Post Retort Phosphor Powder



Container Storage Trailer



Conclusion:

The transfer yard appeared to be in compliance at the conclusion of the inspection.

Inspection Date: 12/17/2015

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737, & 62-740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C. The above noted potential items of non-compliance were identified by the inspector(s).

This is not a formal enforcement action and may not be a complete listing of all items of non-compliance discovered during the inspection.

Aaron Mitchell

PRINCIPAL INSPECTOR NAME

Inspector

PRINCIPAL INSPECTOR TITLE**PRINCIPAL INSPECTOR SIGNATURE**

FDEP

ORGANIZATION

5/4/2016

DATE**Supervisor:** Brad Hartshorn

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.