

F: 3-072-01 Orange Park, FL  
Part B Corrresp.

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IV

345 COURTLAND STREET  
ATLANTA, GEORGIA 30365

FEB 25 1987

4WD-RM

Mr. Stanley Walczynski  
Regional Environmental Engineer  
Safety-Kleen Corporation  
777 Big Timber Road  
Elgin, Illinois 60120

RECEIVED

FEB 27 1987

Environmental Department  
SAFETY-KLEEN CORP.

Re: Safety-Kleen Corporation, Orange Park  
EPA I.D. No. - FLD 980 847 214

Dear Mr. Walczynski:


As a result of the RCRA Facility Assessment (RFA) conducted on February 11, 1987, EPA has determined that there is no evidence of releases of hazardous wastes or hazardous constituents from solid waste management units (SWMUs) at the subject facility. Therefore, at this time, Section 3004(u) of the Hazardous and Solid Waste Amendments (HSWA) of 1984 does not apply and a federal HSWA permit will not be required.

EPA will recommend that the Florida Department of Environmental Regulation (FDER) proceed with the State permitting process. Your Florida Hazardous Waste Operation Permit (when issued) will be the full RCRA permit for this facility.

The cooperation of Mr. Paul Johnson, the facility contact, was greatly appreciated.

If you have any questions please contact Mr. Herb Miller, of my staff, at (404) 347-3433.

Sincerely yours,

  
James H. Scarbrough, P.E., Chief  
Residuals Management Branch  
Waste Management Division

cc: Robert W. McVety, FDER, Tallahassee  
Paul Johnson, Safety-Kleen, Orange Park  
Ashwin Patel, FDER, North East District



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IV

345 COURTLAND STREET, N.E.  
ATLANTA, GEORGIA 30365

4WD-RCRAFFB

OCT 12 1991

CERTIFIED MAILRETURN RECEIPT REQUESTED

Ms. Melissa Hlebasko  
Environmental Permit Writer  
Safety-Kleen Corporation  
777 Big Timber Road  
Elgin, Illinois 60123

RE: Finalized RCRA Facility Assessment Report  
Safety-Kleen Corporation's Orange Park Facility  
EPA I.D. Number FLD 980 847 214

Dear Ms. Hlebasko:

Enclosed please find a copy of the final Resource Conservation and Recovery Act (RCRA) Facility Assessment (RFA) Report. There were no comments on the Draft RFA Report, therefore no changes have been made in the final version.

The findings of the RFA Report will be incorporated into the Hazardous and Solid Waste Amendments (HSWA) Permit to be issued for this facility. Below is a list of Solid Waste Management Units (SWMUs) identified at this time:

SWMU #


1. Warehouse Container Storage Area
2. Paint Wastes Building
3. FRS Waste Building
4. Former Restaurant Filter Building
5. Return and Fill Area
  - A. Mineral Spirits Dumpster
  - B. Dumpsters Satellite Accumulation Area
6. Spent Mineral Spirits Tank
7. Spent Ethylene Glycol Tank
8. Loading/Unloading Areas
  - A. Inside Warehouse
  - B. Tank Farm Area
  - C. Warehouse Dock
9. Pallet Accumulation Area
10. BFI Dumpster

- 2 -

At this time only SWMU # 8 will require further investigation in the form of Confirmatory Sampling. A Confirmatory Sampling Workplan will be required by the HSWA permit.

Should you have any questions concerning the RFA report or the HSWA permit, please contact Ms. Susan Zazzali at (404) 347-3433.

Sincerely yours,

  
James H. Scarbrough, P.E., Chief  
RCRA & Federal Facilities Branch  
Waste Management Division

Enclosure

cc: Satish Kastury, FDER, Tallahassee (with enclosure)  
Ashwin Patel, FDER, Jacksonville (with enclosure)