

## Florida Department of Environmental Protection Oil & Gas Program

## MONTHLY O&G INSPECTION CHECKLIST

	WELL # & NAME			WELL	VELL TYPE O		OG/PA NUMBER		DATE INSPECTED	
	41-5 SCOTT			INJECTOR		OG_	OG_ 1002   312062		2/18/2021	
	OPERATOR			FIELD			COUNTY		API NUMBER	
BREITBURN OPERATING, L.P.					JAY			SANTA ROSA		09-113-20187
					WELL STATUS					LAST MIT P F
				INJECTING					4/10/2019 ✓	
										., 20, 2025
WELL SITE INSPECTION CHECKPOINTS					YES	NO			NO	DTES
LEGIBLE WELL SIGN POSTED					✓					
PAD HOUSEKEEPING SUFFICIENT					<b>~</b>					
PERIMETER BERM/DIKE SUFFICIENT					<b>&gt;</b>					
FLOWLINE/PIPELINE ACCESIBLE/CLEAN					<b>~</b>					
EVIDENCE OF LEAKS/SPILLS ON						,				
PAD/LOCATION										
WELLHEADS				YES	NO	ı	NOTE	S-*MAX INJECT	ΓΙΟΝ=4,400 PW/7,500 N <sup>2</sup>	
PRES	SURE G	AUGES IN WO		TION	<b>&gt;</b>					,
TUBING* ANNULAR SURFACE										
30	000	0	0		<b>&gt;</b>					PW
HIGH/LOW FLOWLINE SHUT IN SENSORS										
LOCATED NEAR WELLHEAD						<b>~</b>		N/A		
HIGH: LOW:										
CELLAR CONDITION SATISFACTORY					✓					
WELLHEAD LEAKING						<b>✓</b>				
HYDROGEN SULFIDE DETECTION SYS							NOTES			OTES
IF YES, FILL OUT					YES	NO				
		YSTEM REQUIR				~				
ENTRY ALARMS IN WORKING CONDITION SENSORS IN WORKING CONDITION										N/A
SENSC	ļ						N/A			
CHEMICAL ADDITIVE SYSTEM					YES	NO			NO	OTES
SYSTEM PRESENT						>				
SYSTEM LEAKING										N/A
SECONDARY CONTAINMENT PROVIDED										N/A
СНЕМІ	CALS O	N LOCATION			1.)					
				_	2.)					
					3.)					



## Florida Department of Environmental Protection Oil & Gas Program

## MONTHLY O&G INSPECTION CHECKLIST

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Permit Number	1002		
Oculus ID	OG_1002	Current Status	INJ
API Number	0911320187	Historical Status	PRODUCER
PA Number	312062	TVD	15,778
Well Name	R.D.SCOTT #41-5	MD	16,027
Operator	BREITBURN OPERATING LP	Conductor Casing	16" 100'
Field	JAY	Surface Casing	10-3/4" 3691'
County	SANTA ROSA	Intermediate Casing	NONE
Sec/Twp/Range	2S41 5N 29W	Production Casing	7" 16025'
SHL	660'FNL&660'FEL of Sec 19	Tubing	3-1/2" 15431'
BHL	1000 FWL 300 FSL (of Sec 41)	Perforations	15696-15897
Latitude	30.95108889	Plugs	
Longitude	-87.15776944	Issue Date	2/5/1980
		Spud Date	6/24/1980
		Completion Date	10/11/1980
		Plug Date	



I inspected the above well & premise on February 18, 2021

Signed

OIL AND GAS COORDINATOR

**WELL & PAD** 

cc: [X]FDEP (Oil & Gas Section): Tallahassee

**WELL SIGN** 

Form IH-1