


Figure II.A.5
04-28-2018

Figure II.A.5 Facility Overview - Main Facility Map



LEGEND

- Security Fence with Barbed Wire
Fire Extinguisher, 20lbs
Fire Extinguisher, 150lbs
Safety Shower
Eye Wash
Spill Control Station
Stretcher
Emergency and Personnel Safety Equipment Cabinet
Fire Alarm Operator
Fire Hydrant
Facility traffic patterns



SCALE
0 60 ft

Triumvirate Environmental Services, Inc.
10100 Rocket Boulevard, Orlando, FL

Facility Layout
Facility Warning Signs
Facility Traffic Patterns
Emergency Equipment Location


PROJECT NO: 317

DATE: June 11, 2013


Figure II.A.5

FLORIDA ENVIRONMENTAL
COMPLIANCE CORPORATION
2000 West Orange Avenue, Suite 200
Orlando, Florida 32805


Figure II.A.2
04-26-2018



1 Mile Radius Topographic Map



SCALE 1:24 000




CONTOUR INTERVAL 5 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929

LAKE JESSAMINE, FLA.
N 2822.5—W 8122.5/7.5

1983
PHOTO REVISSED 1990
DMA 4740 IV NW—SERIES V047

Triumvirate Environmental Services, Inc.


10100 ROCKET BOULEVARD
SCALE: 1:24000 DATE: 3-29-95
1 MILE RADIUS TOPOGRAPHIC MAP




Emergency Service Organizations

Figure IIA-7

Image Source: <http://map.floridiadisaster.org/GATOR/map.html>



Facility Layout (Information puposes only) Figure 1.D.1



Facility Layouts
I.D.I.a





Figure II.K.1 Closure Map showing SWMUs


Figure II.K.1
04-26-2018




FACILITY MAPS

II.A.9

EVACUATION MAP



Wind Rose Plot: All Year	Display: Wind Speed
[ORL] – Orlando/Herndon	Direction (blowing from)



Comments:	Data Period:	Calm Winds:	Average Wind Speed:
FIGURE II A 3 Revision 0 Date: June 5 th 2013	Dec 31 1947 –Feb 12 2013	9.6%	8.0 MPH
Total Count: 490942			Date: 6/5/2013