VESSEL: Water Goat	DATE: 9-3-2020
PROJECT: Cleaning up debri	
LABOR	
Start Time: 8:00 am	Tank Techs: N/A
Finish Time: 10:00 am	Driver(s): Calvin Bynum, Carlos Rodriguez, Juan Santiago,
List all time portal to portal	Foreman: Jerome Speights
EQUIPMENT SUMMARY	
Vac Truck (hours): N/A	Other tools / equipment:
Air compressor: N/A	Pressure Washer: N/A
Double Diaphragm Pumps: N/A	Other: Snake Bed Truck/ 2 hr
¾" Air hoses: N/A	Other: N/A
2" Suction / discharge hoses: N/A	Other: N/A
P.P.E	
Respirator cartridges: N/A	Yellow Tyveks: N/A
Nitrile gloves: 6 pairs	White Tyveks: 6 pairs
Other: N/A	Other: rubber boots
CHEMICALS Designate gallons or bucket	S
2 nd Shift: N/A	UES TANK CLEAN: N/A
PEAKLOAD: N/A	Other: N/A
MATERIALS	
Rags: N/A	Duct Tape: N/A
Gray Carpet: N/A	Air Sock: N/A
Other: TRASH BAGS	Other: RAKES
DISPOSAL Designate container type or t	unit (gallons, drum bags, pounds, etc.)
Oily Waste: N/A	Muck / Solids: N/A
Oily Water Slops N/A	Other: 8 GARBAGE BAGS\ 10LBS EACH
COMMENTS / NOTES Anything else that will be helpful to generating an invoice!!	
tree that hangs over the water that the	rd for UES personnel to move around . Their is a ne buoy is getting hung up on and it creates trash ve pull it out from the tree. Recommendation would

SIGNATURE: