



**Florida Department of
Environmental Protection
Hazardous Waste Inspection Report**

FACILITY INFORMATION:

Facility Name: Veolia ES Technical Solutions LLC
On-Site Inspection Start Date: 11/18/2020 **On-Site Inspection End Date:** 11/18/2020
ME ID#: 62668 **EPA ID#:** FLR000124917
Facility Street Address: 4972 Woodville Hwy (South Lot), Tallahassee, Florida 32305-0903
Contact Mailing Address: 342 Marpan Ln, Tallahassee, Florida 32305-0904
County Name: Leon **Contact Phone:** (850) 877-8299

NOTIFIED AS:

Non-Handler

WASTE ACTIVITIES:

Generator: Non-Handler **Universal Waste:** Indicate types of UW generated and/or accumulated at the facility: **Transport:** Mercury Containing Lamps, Mercury Containing Devices **Transfer Facility:** Mercury Containing Lamps, Mercury Containing Devices **Maximum quantity of UW handled or transported at any time:** 5000 kg or more; Large Quantity Handler (LQH)

INSPECTION TYPE:

Routine Inspection for Transfer Facility Facility

INSPECTION PARTICIPANTS:

Principal Inspector: Monica Hardin, Inspector
Other Participants: Corinna Clanton, Environmental Specialist; Scott Fulton, Operations Manager

LATITUDE / LONGITUDE: Lat 30° 21' 45.5093" / Long 84° 15' 57.5033"

NAIC: 562211 - Hazardous Waste Treatment and Disposal

TYPE OF OWNERSHIP: Private

Introduction:

Veolia ES Technical Solutions (FL0000207449) operates a universal waste transfer facility (FLR000124917) at 4972 Woodville Highway, Tallahassee, for the parking of transport vehicles prior to and after unloading at the permitted facility. The transfer yard and permitted facility are located on non-contiguous property in the same industrial park.

On November 18, 2020 Monica Hardin and Corinna Clanton, of the Florida Department of Environmental Protection (DEP or Department), conducted a routine compliance evaluation inspection at Veolia Transfer Yard (transfer yard or facility) to ensure compliance with applicable State and Federal universal waste transfer area regulations. The transfer yard was last inspected on June 14, 2017 with no violations cited.

Process Description:

At the time of the inspection a total of thirteen trailers were present in the transfer yard (photos 1-2). Of these, twelve were empty. The one trailer with contents contained empty carbon fiber drums. When trailers are stored onsite with contents, the storage times vary depending on the content of the individual trailers. Trailers with universal waste stored on them are kept in the transfer yard for a maximum of ten days. On or before the tenth day, the universal waste is off-loaded at the main facility's docking area for processing. This 10-day storage is tracked by the facility utilizing an Excel spreadsheet, and was reviewed as part of this inspection.

PHOTO ATTACHMENTS:

Veolia ES Technical Solutions LLC Inspection Report

Inspection Date: 11/18/2020

Photo 1: Trailers in Transfer Yard



Photo 2: Trailers in Transfer Yard



Conclusion:

At the conclusion of this inspection, Veolia ES Technical Solutions (transfer yard), appeared in compliance with applicable state and federal universal waste transfer area regulations.

Inspection Date: 11/18/2020

1.0: Pre-Inspection Checklist

Requirements:

The requirements listed in this section provide an opportunity for the Department's inspector to indicate the conditions found at the time of the inspection. A "Not Ok" response to a requirement indicates either a potential violation of the corresponding rule or an area of concern that requires more attention. Both potential violations and areas of concern are discussed further at the end of this inspection report.

Note: Checklist items with shaded boxes are for informational purposes only.

Item No.	Pre-Inspection Review	Yes	No	N/A
1.1	Has the facility notified with correct status? 262.18(a)	✓		
1.2	Has the facility notified of change of status? 62-730.150(2)(b)			✓
1.3	Did the facility conduct a waste determination on all wastes generated? 262.11			✓

Inspection Date: 11/18/2020

Signed:

A hazardous waste compliance inspection was conducted on this date, to determine your facility's compliance with applicable portions of Chapters 403 & 376, F.S., and Chapters 62-710, 62-730, 62-737 & 62 -740 Florida Administrative Code (F.A.C.). Portions of the United States Environmental Protection Agency's Title 40 Code of Federal Regulations (C.F.R.) 260 - 279 have been adopted by reference in the state rules under Chapters 62-730 and 62-710, F.A.C

<u>Monica Hardin</u>	<u>Inspector</u>	
Principal Investigator Name	Principal Investigator Title	
<u>M. E. H.</u>	<u>DEP</u>	<u>01/06/2021</u>
Principal Investigator Signature	Organization	Date
<u>Corinna Clanton</u>	<u>Environmental Specialist</u>	
Inspector Name	Inspector Title	
	<u>DEP</u>	
	Organization	
<u>Scott Fulton</u>	<u>Operations Manager</u>	
Representative Name	Representative Title	
	<u>Veolia ES Technical Solutions</u>	
	Organization	

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Potential Violations" or areas of concern.

Report Approvers:

Approver:	<u>Russell G Sullivan</u>	Inspection Approval Date:	<u>01/08/2021</u>
------------------	---------------------------	----------------------------------	-------------------