



Florida Department of Environmental Protection
Twin Towers Office Bldg. 2600 Blair Stone Road. Tallahassee, Florida 32399-2400
Division of Waste Management
Bureau of Petroleum Storage Systems

Storage Tank Facility Annual Compliance Site Inspection Report

Facility Information:

Facility ID: 8731909 County: OSCEOLA Inspection Date: 03/06/2013
Facility Type: A -Retail Station
Facility Name: 7-ELEVEN FOOD STORE #27160 # Of Inspected ASTs: 0
4015 IRLO BRONSON MEMORIAL HWY USTs: 2
KISSIMMEE, FL 34741 Mineral Acid Tanks: 0
Latitude: 28° 18' 17.2114"
Longitude: 81° 26' 40.0736"
LL Method: DPHO

Inspection Result:

Result : In Compliance
Description: Facility is In Compliance.

Financial Responsibility

Financial Responsibility: INSURANCE
Insurance Carrier: IRONSHORE SPECIALTY INSURANCE CO
Effective Date: 12/18/2012 Expiration Date: 12/18/2013

Findings:

Class A Owner Training Certificates are present.
Class B Maintenance Training Certificates are present.
Class C Operator Training Certificates are present.

Signatures:

TKOREP - ORANGE CNTY ENVIRONMENTAL PROTECTION DIVISION

Storage Tank Program Office

(407) 836-1400

Storage Tank Program Office Phone Number

Facility ID: 8731909

Steve A. Cottrell

INSPECTOR NAME



INSPECTOR SIGNATURE

Scott Jorgensen, MVI Field Services

REPRESENTATIVE NAME



REPRESENTATIVE SIGNATURE

Owners of UST facilities are reminded that the Federal Energy Policy Act of 2005 requires Operator Training at all facilities by August 8, 2012. For further information please visit:
http://www.dep.state.fl.us/waste/categories/tanks/pages/op_train.htm

System Tests

Type	Date Completed	Results	Reviewed	Next Due Date	Comment
------	----------------	---------	----------	---------------	---------

Completed Tests

Annual Operability Test	12/04/2012	Passed	03/12/2013	12/04/2013	By Tanknology
Breach of Integrity Test	01/09/2012	Passed	02/10/2012	01/09/2017	Tested by Eddie Vega, Tanknology
Annual Inline Leak Detector Test	12/04/2012	Passed	03/12/2013	12/04/2013	By Tanknology

Reviewed Records

Record Category	Record Type	From Date	To Date	Reviewed Record Comment
Two Years	Certificate of Financial Responsibility	12/18/2012	03/06/2013	
Two Years	Monthly Maint. Visual Examinations and Results	12/02/2011	03/06/2013	
Life Time	Written Release Detection Response Level Info	03/06/2013	03/06/2013	
Two Years	Electronic Release Detection Equip. Monthly Checks	12/02/2011	03/06/2013	

Inspection Comments

03/12/2013

Annual Compliance Inspection
Arrival time: 0850 hrs

At the time of inspection:
Current Placard available
Current Financial Responsibility available
Current Certification of Financial Responsibility available.
Written Release Detection Response Level available
Release detection is monthly electronic and visual inspections
Monthly records available and recorded correctly
Current Annual Leak Detector, Line Leak Detector and Breach of Integrity test records are available, all passed.

Fill port covers are properly marked.

Activity Opened Date: 03/06/2013

Page 2 of 3

Cottrell, Steve

Facility ID: 8731909

Inspection Comments

Spill buckets are mostly dry and in good condition.
Drop tubes are coaxial with flapper valves for overfill protection.
Piping sumps are mostly dry. Sensors are properly positioned within sumps.
Dispensers are mostly dry and shear valves are properly anchored.
All fuel hoses and breakaways are in fair condition.
Tank monitor is a Veeder-Root, showing All Functions Normal.

Signed Report sent on March 12, 2013 via e-mail to Shellie Learn at: shellie.learn@7-11.com