

### Florida Department of Environmental Protection Oil & Gas Program

# MONTHLY O&G INSPECTION CHECKLIST

													-
	WELL # & NAME		WELL TYPE		O	OG/PA NUMBER		DATE INSPECTED					
	10-4 C.H. BRAY		PRODUCER OG		OG_			7/7/2020					
OPERATOR				FIELD			COUNTY		API NUMBER				
BREITBURN OPERATING, L.P.				JAY S		SA	NTA ROSA	09-113-20008-01					
					WELL S	STATUS			LAST MIT	Р	F	1	
					PROD	UCING	JCING 4/16/201			4/16/2019	<b>✓</b>		1
WELL SITE INSPECTION CHECKPOINTS					YES	NO			N	OTES			
LEGIBLE WELL SIGN POSTED					<b>✓</b>								
PAD HOUSEKEEPING SUFFICIENT					<b>~</b>								
PERIMETER BERM/DIKE SUFFICIENT										N/A			
FLOWLINE/PIPELINE ACCESIBLE/CLEAN					<b>✓</b>								
	NCE OF LEAKS	S/SPILLS	ON			v							
PAD/L	OCATION					·							
WELLIEADO YEO NO								<b>N</b> 14	2752				
WELLHEADS					YES	NO	NOTES						
PRESSURE GAUGES IN WORKING CONDITION					<b>~</b>								
TUBING ANNULAR SURFACE													
200 0 0			<b>~</b>		PRODUCING								
HIGH/LOW FLOWLINE SHUT IN SENSORS													
LOCATED NEAR WELLHEAD					<b>~</b>								
HIGH: 800 LOW: 0													
CELLAR CONDITION SATISFACTORY					<b>~</b>								
WELLHEAD LEAKING						~							
LIVERS OF N CITI FIRE DETECTION OVERTING													
HYDROGEN SULFIDE DETECTION SY IF YES, FILL OUT					YES	NO			N	OTES			
DETECTION SYSTEM REQUIRED					·								
ENTRY ALARMS IN WORKING CONDITION					~								
SENSORS IN WORKING CONDITION					~								
CHEMICAL ADDITIVE SYSTEM					YES	NO	NOTES						
SYSTEM PRESENT						<b>✓</b>							
SYSTEM LEAKING										N/A			
SECONDARY CONTAINMENT PROVIDED										N/A			
CHEMICALS ON LOCATION					1.)								
					2.)								
I													



#### Florida Department of Environmental Protection Oil & Gas Program

## MONTHLY O&G INSPECTION CHECKLIST

#### H2S DETECTION SYSTEM IN PLACE.

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Permit Number	452BH		
Oculus ID	OG_452	Current Status	PROD
API Number	0911320008-01	Historical Status	PRODUCER
PA Number	309838	TVD	15,711
Well Name	C H BRAY ETAL #10-4BH	MD	18,304
Operator	BREITBURN OPERATING LP	Conductor Casing	
Field	JAY	Surface Casing	
County	SANTA ROSA	Intermediate Casing	
Sec/Twp/Range	4S10 5N 29W	Production Casing	
SHL	1595'FSL&1062'FEL	Tubing	
BHL	2727' NE OF SHL	Perforations	
Latitude	30.95747755	Plugs	
Longitude	-87.15880134	Issue Date	9/16/2009
		Spud Date	11/25/1970
		Completion Date	10/30/2008
		Plug Date	



**WELL SIGN** 

WELL & PAD

I inspected the above well & premise on July 7, 2020

Signed

OILAND GAS COORDINATOR

hassee

cc: [X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1