

### Florida Department of Environmental Protection Oil & Gas Program

# MONTHLY O&G INSPECTION CHECKLIST

ī	<u></u>								_			
	WELL # & NAME		WELL TYPE			G/PA NUMBER	27112111012	DATE INSPECTED				
	19			MOORE			UCER	OG_	1106 302996	1/29/20		
OPERATOR					FIELD			COUNTY	API NUMBER			
BREITBURN OPERATING, L.P.					JAY			SANTA ROSA	09-113-20208			
					WELL S	TATUS LAST MI			LAST MIT	Р	F	
						Y PLUGGED & ABANDONED			2/7/2019	✓		
WELL SITE INSPECTION CHECKPOINTS						YES	NO		NO	DTES		
LEGIBLE WELL SIGN POSTED												
PAD HOUSEKEEPING SUFFICIENT						~						
PERIMETER BERM/DIKE SUFFICIENT						<b>*</b>						
FLOWL	.INE/PIP	ELINE A	ACCESI	BLE/CLEAN		<b>*</b>						
	ICE OF		/SPILLS	ON			,					
PAD/LOCATION												
WELLIEADS					YES	NO		N/	OTES			
WELLHEADS  PRESSURE CAUSES IN WORKING CONDITION						I E O	NO		INC	JIES		
TRESORE GAUGES IN WORKING CONDITION												
				SURFACE								
(	)	(	)	0		<b> </b>		TP&A'D 9/20/12; CEMENT PLUGS SET @ 6,328' & @ 13,831'				
HIGH/LOW FLOWLINE SHUT IN SENSORS												
LOCAT	ED NEA	R WEL			ı		~	N/A				
HIGH: LOW:												
CELLAR CONDITION SATISFACTORY						~						
WELLHEAD LEAKING							<b>&gt;</b>					
HYDROGEN SULFIDE DETECTION SYS									NOTES			
<u>IF YES, FILL OUT</u>						YES	NO					
DETECTION SYSTEM REQUIRED						<b>*</b>						
ENTRY ALARMS IN WORKING CONDITION						~						
SENSORS IN WORKING CONDITION						<b>Y</b>						
CHEMICAL ADDITIVE SYSTEM						YES	NO		N/	TEC		
CHEMICAL ADDITIVE SYSTEM						IES	NO V		NO	OTES		
SYSTEM PRESENT										N/A		
SYSTEM LEAKING										N/A		
SECONDARY CONTAINMENT PROVIDED										N/A		
CHEMICALS ON LOCATION						1.)						
						2.)						
1						3.)						



#### Florida Department of Environmental Protection Oil & Gas Program

## MONTHLY O&G INSPECTION CHECKLIST

## 1106 IS CURRENTLY TEMPORARILY PLUGGED & ABANDONED EFFECTIVE 9/20/12. CEMENT PLUGS SET @ 6,328' & 13,831'

#### H2S DETECTION SYSTEM IN PLACE.

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

OTTE TO CELAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS ON EXCESSIVE CONNOCION ON WELLINEAD.								
Permit Number	1106							
Oculus ID	OG_1106	Current Status	TA					
API Number	0911320208	Historical Status	PRODUCER					
PA Number	302996	TVD	15,835					
Well Name	JESS E MOORE #19-8	MD	15,963					
Operator	BREITBURN OPERATING LP	Conductor Casing	16" 102'					
Field	JAY	Surface Casing	10-3/4" 3838'					
County	SANTA ROSA	Intermediate Casing	NONE					
Sec/Twp/Range	2S19 5N 29W	Production Casing	7" 15938'					
SHL	1554'FNL&1812'FWL	Tubing	3-1/2" 15620'					
BHL	600 FNL 2063 FWL	Perforations	15816-15862					
Latitude	30.94911961	Plugs	14,249'-13,381', 6,467'-6,3					
Longitude	-87.16694462	Issue Date	1/10/1983					
		Spud Date	3/8/1983					
		Completion Date	7/17/1983					
		Plug Date	9/20/2012					





**WELL SIGN** 

**WELL & PAD** 

I inspected the aboye well & premise on January 29, 2021

Signed

OU AND GAS COORDINATOR

cc: [X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1