

Florida Department of Environmental Protection Inspection Checklist

FACILITY INFORMATION:

Facility Name: GARDEN STREET IRON & METAL (WASTE TIRE PROCESSING CENTER)

On-Site Inspection Start Date: 06/30/2011
On-Site Inspection End Date: 06/30/2011

WACS No.: 98386

Facility Street Address: 3350 METRO PARKWAY

City: FORT MYERS

County Name: LEE

Zip: 33916

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Bill Krumbholz, Env. Mgr.

Other Participants: Jay Standiford, E.S. II; Rob Webber, Owner/ Operator

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

COMMENTS:

07/11/2011

Determine possible usage of tire chips as initial cover at permitted landfills

Observation confirmed that the processed tire chips were cut into sufficiently small pieces to to be used as initial landfill cover in accordance with F.A.C. Rule 62-711.400(3)(a); 70% cut into pieces 4 square inches or less and 100% cut into pieces 32 square inches or less. It was also noted that tire chips within the processed on-site tire pile interlocked to form a slope much steeper than that required at a landfill; slope no greater than a 3 feet horizontal to a 1 foot vertical rise. Please see picture.

Waste tire chips are approved for initial cover. Any chips observed that are too large to meet the requirements of F.A.C. Rule 62-711.400(3)(a) should be removed by the landfill operator for disposal or additional processing.

ATTACHMENTS:

Inspection Date: 06/30/2011

Processed Tire Pile



Inspection Date: 06/30/2011

Bill Krumbholz	Env. Mgr. PRINCIPAL INSPECTOR TITLE	
PRINCIPAL INSPECTOR NAME		
Bell Crumbholz	FDEP	7/11/2011
PRINCIPAL INSPECTOR SIGNATURE	ORGANIZATION	DATE
Jay Standiford	E.S. II	
INSPECTOR NAME	INSPECTOR TITLE	
NO SIGNATURE	FDEP	
INSPECTOR SIGNATURE	ORGANIZATION	
Rob Webber	Owner/ Operator	
INSPECTOR NAME	INSPECTOR TITLE	
NO SIGNATURE	Gsrden Street	
INSPECTOR SIGNATURE	ORGANIZATION	

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.