

Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

_										
		WELL	# & NAME		WELL	TYPE	0	G/PA NUMBER	DATE INSPE	CTED
	30-2	Α	MITCHELL		PROD	UCER	0	G_557/309889	10/2/20	18
	OPERATOR			FIELD			COUNTY	API NUMBER		
BREITBURN OPERATING, L.P.					JAY			SANTA ROSA	09-113-20062	
					WELL STATUS		S		LAST MIT	P F
				PRODUCING				6/17/2014	√	
						ı				
WELL SITE INSPECTION CHECKPOINTS					YES	NO		NO	OTES	
LEGIBLE WELL SIGN POSTED					~					
PAD HO	DUSEKEE	PING SUF	FICIENT		✓					
PERIME	ETER BEF	RM/DIKE S	UFFICIENT		Y					
_			SIBLE/CLEAN		~					
		EAKS/SPIL	LS ON			,				
PAD/LC	CATION									
		WELLE	ADE		YES	NO		N/)TES	
WELLHEADS					I E O	NO		INC	OTES	
PRESSURE GAUGES IN WORKING CONDITION							<u> </u>			
TUB		ANNULAF		I		l	I			
35	50	0	0		~			PRO	DUCING	
HIGH/LOW FLOWLINE SHUT IN SENSORS										
LOCATED NEAR WELLHEAD					~					
HIGH: 1100 LOW: 0										
CELLAR CONDITION SATISFACTORY				~						
WELLHEAD LEAKING					~					
HYDROGEN SULFIDE DETECTION SYS								NOTES		
<u>IF YES, FILL OUT</u>					YES	NO				
DETECTION SYSTEM REQUIRED					~					
ENTRY ALARMS IN WORKING CONDITION					~					
SENSORS IN WORKING CONDITION					~					
	0115111		EIV		\/F\$				2770	
CHEMICAL ADDITIVE SYSTEM					YES	NO		N	OTES	
SYSTEM PRESENT					~					
SYSTEM LEAKING						~				
SECONDARY CONTAINMENT PROVIDED				~						
CHEMICALS ON LOCATION				1.)						
					2.)					



Permit Number

Florida Department of Environmental Protection Oil & Gas Program

MONTHLY O&G INSPECTION CHECKLIST

H2S DETECTION SYSTEM IN PLACE.

SITE IS CLEAN & WELL MAINTAINED. NO EVIDENCE OF LEAKS OR EXCESSIVE CORROSION ON WELLHEAD.

Oculus ID	OG_557		Current Status	
API Number	0911320062		Historical Status	PRODUCER
PA Number	309889	TVD	16,031	
Well Name	MITCHELL UNIT #30-2	MD	16,031	
	BREITBURN OPERATING LP	Conductor Casing		
Field		Surface Casing	10-3/4"@ 3787'	
County	SANTA ROSA	Intermediate Casing		
Sec/Twp/Range	2S30 5N 29W	Production Casing	NA	
SHL	660'FNL&1985'FWL		3-1/2"@ 15480'	
	SAME		15644-15670	
Latitude	30.92255236		Plugs	
Longitude	-87.14995371		Issue Date	2/28/1972
			Spud Date	
			Completion Date	
			Plug Date	
	1			-
1		l		

I inspected the above well & premise on October 2, 2018

Signed

OIL AND CAS COORDINATOR

cc: [X]FDEP (Oil & Gas Section): Tallahassee

Form IH-1