

Environmental Consultants
and Contractors

4041 Park Oaks Blvd.
Suite 100
Tampa, FL 33610-9501

813 621-0080
FAX 813 623-6757
www.scsengineers.com

SCS ENGINEERS

March 7, 2012
File No. 09210021.07

Mr. Douglas Hyman, P.E.
Environmental Resource Management
Florida Department of Environmental Protection, Southwest District
13051 N. Telecom Parkway
Temple Terrace, Florida 33637-0926

Dept. of Environmental
Protection

Subject: Stormwater Management System Inspection Report
Citrus County Closed Landfill Re-Closure
Citrus County, Florida
Permit Number 09-0292195-001

MAR 07 2012

Dear Mr. Hyman:

Southwest District

On behalf of the Citrus County Solid Waste Management Division (SWMD), SCS Engineers (SCS) is submitting the required documentation in compliance with Operation Condition 15 of the Environmental Resource Permit No. 09-0292195-001 for the Citrus County Central Landfill Re-Closure Area.

SCS conducted a site visit on February 15, 2012 to observe the condition of the stormwater management system. These findings are based on the site walk through and visual assessment. Overall the site appeared dry. There was no debris, sedimentation or vegetation buildup observed in the stormwater management system. There was no unauthorized stormwater discharge observed during the site visit. All structures appeared in sound condition. Thus, as of the site walk through, the stormwater management system at the above referenced project appears to be functioning in accordance with the requirements of the permit and Chapter 373 F.S.

Attachment 1 of this letter contains two originals of the "Environmental Resource Permit Inspection Certification" (Form No. 62-343.900(6), F.A.C.) signed by Dominique H. Bramlett, a Registered Professional Engineer in the State of Florida. Attachment 2 of this letter contains photos of the stormwater management system.

Mr. Douglas Hyman, P.E.
March 7, 2012
Page 2

If you have any questions, please feel free to contact us at 813-621-0080.

Sincerely,



Dominique H. Bramlett, P.E.
Project Manager
SCS ENGINEERS



C. Ed Hilton, P.E.
Vice President
SCS ENGINEERS

DHB/CEH:dhb

cc: Steve Morgan, P.E., FDEP Tampa
Casey Stephens, Citrus County Solid Waste Management Division

Attachment 1

"Environmental Resource Permit Inspection Certification"
(Form No. 62-343.900(6), F.A.C.)

ENVIRONMENTAL RESOURCE PERMIT INSPECTION CERTIFICATION

Permit Number: 09-0292195-001

Project Name: Citrus County Central Landfill Re-Closure

Inspection Date(s): 02/15/2012


Inspection results: (check one)

☒ I hereby certify that I or my designee under my direct supervision have inspected the system at the above referenced project and that the system appears to be functioning in accordance with the requirements of the permit and Chapter 373 F.S. (as applicable).

☐ The following necessary maintenance was conducted:

☐ I hereby certify that I or my designee under my direct supervision has inspected the system at the above referenced project and that the system does not appear to be functioning in accordance with the requirements of the permit and Chapter 373 F.S. (as applicable). I have informed the operation and maintenance entity of the following: (a) that the system does not appear to be functioning properly, (b) that maintenance is required to bring the system into compliance, and (c) if maintenance measures are not adequate to bring the system into compliance, the system may have to be replaced or an alternative design constructed subsequent to Department approval.

Dominique H. Bramlett
Name


Signature of Professional Engineer

SCS Engineers
Company Name

61829
Florida Registration Number

4041 Park Oaks Blvd., Suite 100
Company Address


Date

Tampa, FL 33610
City, State, Zip Code

(813) 621-0080
Telephone Number

(affix seal)

Within 30 days of completion of the inspection, submit two copies of the form to the following Department Office:

Department of Environmental Protection

Florida Department of Environmental Protection
Southwest District Office
13051 North Telecom Parkway
Temple Terrace, FL 33637-0926

ENVIRONMENTAL RESOURCE PERMIT INSPECTION CERTIFICATION

Permit Number: 09-0292195-001

Project Name: Citrus County Central Landfill Re-Closure

Inspection Date(s): 02/15/2012

Inspection results: (check one)

☒ I hereby certify that I or my designee under my direct supervision have inspected the system at the above referenced project and that the system appears to be functioning in accordance with the requirements of the permit and Chapter 373 F.S. (as applicable).

☐ The following necessary maintenance was conducted:

☐ I hereby certify that I or my designee under my direct supervision has inspected the system at the above referenced project and that the system does not appear to be functioning in accordance with the requirements of the permit and Chapter 373 F.S. (as applicable). I have informed the operation and maintenance entity of the following: (a) that the system does not appear to be functioning properly, (b) that maintenance is required to bring the system into compliance, and (c) if maintenance measures are not adequate to bring the system into compliance, the system may have to be replaced or an alternative design constructed subsequent to Department approval.

Dominique H. Bramlett
Name


Signature of Professional Engineer

SCS Engineers
Company Name

61829
Florida Registration Number

4041 Park Oaks Blvd., Suite 100
Company Address

02/17/12
Date

Tampa, FL 33610
City, State, Zip Code

(813) 621-0080
Telephone Number

(affix seal)

Within 30 days of completion of the inspection, submit two copies of the form to the following Department Office:

Department of Environmental Protection

Florida Department of Environmental Protection
Southwest District Office
13051 North Telecom Parkway
Temple Terrace, FL 33637-0926

Attachment 2

Photographs

Photograph Number 1



Date: February 15, 2012 **Site:** Citrus County Closed Landfill Re-Closure
Description: DRA-3 facing the entrance to the landfill

Photograph Number 2



Date: February 15, 2012 **Site:** Citrus County Closed Landfill Re-Closure
Description: DRA-3 structure

Photograph Number 3



Date: February 15, 2012 **Site:** Citrus County Closed Landfill Re-Closure
Description: Structure at DRA-2

Photograph Number 4



Date: February 15, 2012 **Site:** Citrus County Closed Landfill Re-Closure
Description: Perimeter ditch into DRA-2 looking south

Photograph Number 5



Date: February 15, 2012

Site: Citrus County Closed Landfill Re-Closure

Description: DRA-1

Photograph Number 6



Date: February 15, 2012

Site: Citrus County Closed Landfill Re-Closure

Description: DRA-4 looking east